

September 28, 1995

Mr. John P. Stetz
Vice President - Nuclear
Davis-Besse Nuclear Plant
Centerior Service Company
c/o Toledo Edison Company
300 Madison Avenue
Toledo, OH 43652

SUBJECT: INSPECTION AT DAVIS-BESSE (REPORT NO. 50-346/95007)

Dear Mr. Stetz:

This refers to the inspection conducted by Mr. S. Stasek and others of this office on June 26, 1995, through August 23, 1995. The inspection included a review of activities authorized for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, performance at Davis-Besse continues to be excellent overall. Unit activities reviewed during this inspection were typically conducted in a controlled and conservative manner. However, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern because maintenance personnel's inattention to detail while performing a procedure resulted in an improper as-left condition of a safety-related valve.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In addition, several issues were identified during this inspection related to the adequacy of service water system inlet temperature monitoring. The NRC is continuing to review these issues and will document our conclusions in a future inspection report.

190016

9510190172 950928
PDR ADOCK 05000346
G PDR

IEO/
111

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by R. D. Lanksbury

R. D. Lanksbury, Chief
Reactor Projects Section 3B

Docket Nos. 50-346, 72-14

Enclosures:

- 1. Notice of Violation
- 2. Inspection Report
No. 50-346/95007(DRP)

cc w/encl: D. C. Shelton, Senior
Vice President - Nuclear
J. K. Wood, Plant Manager
W. T. O'Connor, Manager
Regulatory Affairs
State Liaison Officer, State
of Ohio
Robert E. Owen, Ohio
Department of Health
A. Grandjean, State of Ohio,
Public Utilities Commission

Docket File w/encl
PUBLIC IE-01 w/encl
OC/LFDCB w/encl
Resident Inspector, RIII
SRI, Davis-Besse w/encl
Project Manager, NRR w/encl

DRP w/encl
RIII PRR w/encl

To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII	E	RIII	E	RIII	N	RIII	N
NAME	Tongue/co <i>AMT</i>		Creed (Secs. 4.2 & 5.6)		Gardner (Sec. 5.) <i>DBP</i>		Lanksbury <i>RDL</i>	
DATE	9/28/95		9/28/95		9/28/95		9/28/95	

OFFICIAL RECORD COPY