

Appendix A

NOTICE OF VIOLATION

Baltimore Gas and Electric Company  
Calvert Cliffs Unit 1

Docket/License: 50/317; DPR53

As a result of the inspection conducted on May 15 - June 12, 1984 and in accordance with the NRC Enforcement Policy, (10 CFR2 Appendix C) the following violation was identified:

10 CFR 50, Appendix B, Criterion XVI requires that measures be established to assure that conditions adverse to quality are promptly identified and corrected.

Contrary to the above, following a violation (317/84-03-03; date of occurrence February 15, 1984) involving a valve tagout error of the Oxygen Analyzing System due in part to inadequate valve labeling, the licensee did not take timely action to correct labeling deficiencies in the Gas Analyzing Systems. Prompt corrective action in this area may have prevented the improper lifting of a power lead to Hydrogen Analyzing System valve O-SV-6509 on June 5, 1984, which partially disabled that System.

This is a Severity Level V Violation (Supplement I) applicable to DPR 53.

Pursuant to the provisions of 10 CFR2.201, Baltimore Gas and Electric Company is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including : (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

Where good cause is shown, consideration will be given to extending the response time.

OFFICIAL RECORD COPY

50-317/84-11 - 0013.0.0  
06/26/84

8407240436 840703  
PDR ADOCK 05000317  
Q PDR