

September 28 1984

W3P84- 2740 Q-3-A35.07.108 3-A1.01.04

OCT - 4 1984

Mr. John T. Collins Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76012

Dear Mr. Collins:

Subject: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 108 "Potential Failure to Comply with FSAR Safe Shutdown Commitment" Fifth Interim Report

Reference: LP&L Letter W3K84-2547 dated September 14, 1984

The above referenced letter indicated submittal of the Final Report to the USNRC on September 28, 1984.

However, during validation of FP Control Room/Cable Vault Safe Shutdown List in the FSAR, seven (7) additional cables were identified which require re-routing from the cable vault. The final report is scheduled to be submitted to the NRC on October 31, 1984.

Very truly yours,

FW Cook

K.W. Cook

Nuclear Support & Licensing Manager

KWC:RJB:pbs

cc: Director

Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission

Washington, D.C. 20555

IE-27

1/0

Mr. John T. Collins W3P84- 2740 Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake Shaw, Pittman, Potts & Trowbridge 1000 M. Street, N.W. Washington, D.C. 20036

Mr. W. M. Stevenson Monroe & Lemann 1424 Whitney Building New Orleans, Louisiana 70130

Mr. W. A. Cross 4827 Rugby Avenue Suite B-1 Bethesda, Maryland 20814

Nr. G. W. Knighton, Chief Licensing Branch, No. 3 Division of Licensing Washington, D.C. 20555