

317 BARONNE STREET P.O. BOX 60240 NEW ORLEANS, LOUISIANA 70180

(504) 595-2204

50 - 362

October 15, 1984

J.M. CAIN President and Chief Executive Officer

W3B84-0496

Director of Nuclear Reactor Regulation ATTN: Mr. Larrell G. Eisenhut, Director Division of Licensing U.S. Nuclear Regulatory Commission Washington, D.C. 20555

SUBJECT: Waterford 3 SES Partial Response to Items from Waterford Review Team


> 8410170239 841005 DR ADDCK 05000382

- REFERENCES: 1) Letter, D.G. Eisenhut to J.M. Cain, "Waterford 3 Review," dated June 13, 1984
  - Letter W3B84-0495, J.M. Cain to D.G. Eisenhut, "Revised Program Plan" dated October 10, 1984

Dear Mr. Eisenhut:

The purpose of this letter is to submit a supplement to the response to Issue 2, reflecting information developed since our August 10, 1984 submittal. The information contained in this supplement was informally provided to your staff. The logic in our original response to Issue 2 remains unchanged.

The supplement has been reviewed and verified by LP&L QA in accordance with procedure QASP 19-13. The designated subcommittee of the Waterford Safety Review Committee also has reviewed the adequacy of the supplement for resolving the issues raised. The subcommittee scope of responsibility does not include independent validation of the facts.



JMC:DA:pbs

Attachm^\*\*

Mr. Darrell G. Eisenhut, Director W1884-0496 October 15, 1984

cc: Mr. R.S. Leddick

Mr. D.E. Dobson

Mr. R. R. Burski

Mr. K.W. Cook

Mr. T.F. Gerrets

Mr. A.S. Lockhart

Mr. R.P. Barkhurst

Mr. L. Constable JSNRC - Waterford 3

Mr. J.T. Collins U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Suite 1000 Arlington, TX 76011

Mr. D. Crutchfield U.S. Nuclear Regulatory Commission Washington, D C. 20555

Mr. G. Knighton, Chief Licensing Branch No. 3 Division of Licensing Washington, D.C. 20555

Mr. M. Peranich Waterford 3 Investigation and Evaluation Inquiry Report Team Leader 4340 E.W. Hwy. MS-EWS-358 Bethesda, MD 20114

Mr. D. Thatcher Waterford 3 Instrumentation & Control Leader 7920 Norfolk Ave. MS-216 Bethesda, MD 20114

Mr. L. Shao Waterford 3 Civil/Structure Team Leader 5650 Nicholson Ln. Rockville, MD Page 2

Mr. J. Harrison Waterford 3 QA Team Leader Region III 700 Roosevelt Rd. Glen Ellyn, IL 60137

Mr. J.E. Gagliardo Director of Waterford 3 Task Force Region IV 611 Rysee Plaza Suite 1000 Arlington, TX 76011

Mr. S. Levine NUS Corporation 910 Clopper Road Gaithersburg, MD 20878

Mr. R.L. Ferguson UNC Nuclear Industries P.O. Box 490 Richland, WA 99352

Mr. L.L. Humphreys UNC Nuclear Industries 1200 Jadwin, Suite 425 Richland, WA 99352

Mr. G. Charnoff Shaw, Pittman, Potts & Trowbridge 1800 M. St. N.W. Washington, D.C. 20555

Dr. J. Hendrie 50 Bellport Lane Bellport, NY 11713

Mr. R. Douglass Baltimore Gas & Electric 8013 Ft. Smallwood Road Baltimore, MD 21226

Mr. M.K. Yates, Project Manager Ebasco Services, Inc. Two World Trade Center, 80th New York, NY 10048

Mr. R. Christesen, President Ebasco Services, Inc. Two World Trade Center New York, NY 10048

## SUPPLEMENT TO RESPONSE 10 CONCERN NO. 2

## SUBMITTED AUGUST 10, 1984

## DISCUSSION:

In preparation for the reinspection of N1 instrument lines conducted in response to Issue No. 1 (Inspection Personnel Issues), an inconsistency was identified between the Instrument List and a Mercury isometric drawing. A review was therefore conducted consisting of a cross-check between the Instrument List and the Mercury isometric drawings for all N1 instrument lines, and a review of Design Change Notices (DCNs) posted against either the Instrument List or the Isometric Drawings pertaining to the classification of N1 instruments. As a result of the review, the following revisions and additions to the response to Concern No. 2 submitted on August 10, 1984 (W3B84-0467) have been identified.

- ° 10 additional N1 instruments installed prior to April 7, 1982 were identified (for a total of 202 instead of 192).
- Of the 10 additional N1 instruments identified, eight are cabinet mounted (for a total of 110 instead of 102) and two are locally mounted.
- <sup>°</sup> The eight additional cabinet mounted Nl instruments identified underwent QAIRG review and full documentation is available.
- Four cabinet mounted and the two additional locally mounted N1 instruments identified were installed with ASME III/ANSI B31.1 class breaks, and will be reworked to ASME Code requirements.

There is no change to the previously stated Cause, Generic Implications and Safety Significance.

## CORRECTIVE ACTION PLAN/SCHEDULE:

The 12 N1 instrument installations noted in the original response plus the six additional N1 instrument (four cabinet mounted/two locally mounted) will be reworked to ASME Code requirements before fuel load.