

10/02/84

REGION 5  
LICENSEE EVENT REPORT

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	10-10-83	OTHER	S		0		INITIAL HOMB THREAT ON SITE TARGET-CONTROL ROOM
	11-04-83	OTHER	S		0		SHERIFF'S DEPT ARRESTS FIVE SUBCONTRACTOR EMPLOYEES FOR MARIJUANA
	81-08-X1	SPECIAL RPT.	C		0		RY FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	81-10-21	PART 21	C		0		PART 21-(PARSONS PEBLES) DIESEL GENERATOR SYSTEM DEFECT
	84-02-P	PART 21	C		0		PR 21 BY TERRY/ING-RAND AFW TURBINE VALVES NEED NEW SPRINGS

8410220027 841022  
PDR ADCK 05000528  
S PDR

NOTE: CRIB → 1 C4 7320100 V

1005  
1/3

10/02/80

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IB-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV: 1/SIIP: 2
	IB-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-80-16	IE BULLETIN	C	8308	0		
	IB-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNURBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-02	IE BULLETIN	C	8234	0		PORV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IB-82-02	IE BULLETIN	C	8422	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-83-01	IE BULLETIN	C	8422	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	18-83-03	IE BULLETIN	C	8422	0		CHECK VALVE FAILURES IN RAW WATER SYS OF DIESEL GENERATORS
	18-83-04	IE BULLETIN	C	8422	0		FAILURE OF UNDERVOLTAGE TRIP FUNCTION OF REACTOR TRIP BREAKER
	18-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	18-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE HFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONBITF SUPPLY
	IC-80-09	IE CIRCULAR	0		0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
		IE CIRCULAR	0	8308	0		TRANSFER TO OPS PER PJ/PN DISCUSSION 3/21/83
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8422	0		
	IC-81-03	IE CIRCULAR	C	8422	0		INOP SEISMIC INSTRUMENTATION
	IC-81-10	IE CIRCULAR	0	8422	0		STEAM VOIDING IN RCS DURING COOLDOWN
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8422	0		

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-34-09	INSP RPT (DEV)	C	8406	0		ACCEPTANCE CRITERIA FOR VISUAL INSPECTION OF WELDING
		INSP RPT (DEV)	C	8436			TWO FBAR CHANGES NEED NRR APPROVAL TO CLOSE THIS ITEM
	84-25-03	INSP RPT (DEV)	C	8425			NO AUDITS OF SPRAY ON FIREPROOFING
	84-25-04	INSP RPT (DEV)	C	8425	0		FP HGRS DESIGNED TO SEISMIC IX VS I

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	02-30-01	INSP RPT (ENF)	P	0		NONCOMPLIANCE STEAM GENERATOR CHEMICAL
	03-10-01	INSP RPT (ENF)	C	0		TERMINATION CARDS INACCURATE
	03-30-01	INSP RPT (ENF)	C	0436		QC PERSONNEL ACCEPTING CONDITIONS NOT IMA DRAWING
	03-30-06	INSP RPT (ENF)	C	0		UNSATISFACTORY BOLTING ACCEPTED BY QC
	03-30-17	INSP RPT (ENF)	C	0		CABLE TRAY CONNECTIONS DISCONNECTED
	03-30-18	INSP RPT (ENF)	C	0		HANGER WELDS NOT IAW DRAWING
	03-30-19	INSP RPT (ENF)	C	0		WELD OVERLAP ON INSTRUMENT RACK SUPPORT
	03-30-20	INSP RPT (ENF)	C	0		LUMBER IN CHANNEL C ELECTRICAL RACEWAY
	03-00-01	INSP RPT (ENF)	R	0		FAILURE TO FOLLOW PROCEDURES
	04-15-01	INSP RPT (ENF)	C	0436		WELDERS QUALIFIED AFTER THE FACT
	04-15-12	INSP RPT (ENF)	C	0		ALL UNITS MINIMUM THREAD ENGAGEMENT CRITERIA FOR THREADED FASTENERS SEE REPORT 50-530/02-07

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	84-18-01	INSP RPT (ENF)	R		0	0884	NONCOMPLIANCE-NONCONTROL OF EQUIPMENT AND PARTS
	84-18-02	INSP RPT (ENF)	R		0	0884	FAILURE TO TAG NONCOMPLIANCE-NONCONTROL OF NONCONFORMING PARTS
	84-21-01	INSP RPT (ENF)	F		0		FAILURE TO ISSUE AN NCR HONEYWELL'S INSTRUMENTS MADE IMPROPER BY OTHERS
	84-25-01	INSP RPT (ENF)	C	8425	0		SEISMIC ANALYSIS OF THE FIRE PROTECTION SYSTEM IS IMPROPER
	84-28-01	INSP RPT (ENF)	R		0	1084	FAILURE TO PROPERLY DISPOSITION AN SFR

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-02-03	INSP RPT (FOLLOWUP)	C	8317	0		COLD SPRINGING OF ECM PIPE REQUIRES APS ACTION
		INSP RPT (FOLLOWUP)	C	8436	0		
	83-03-05	INSP RPT (FOLLOWUP)	M		0		FUEL BLDG EXHAUST MONITOR RU-145 8146 SAMPLE POINT LESS THAN 5 DUCE DIAM
	83-12-01	INSP RPT (FOLLOWUP)	M		0		FSAR 12.5.2.1.1 ITEM B-HOODS & AIR SUPPLY RESOLUTION ADD OR DELETE
	83-12-12	INSP RPT (FOLLOWUP)	M	8328	0		0737 IIF1 CALIBRATION RECORDS
		INSP RPT (FOLLOWUP)	M	8330	0		
		INSP RPT (FOLLOWUP)	M	8434	0		
	83-12-14	INSP RPT (FOLLOWUP)	M		0		0737 IIF1 VENDOR CALIBRATION DATA
		INSP RPT (FOLLOWUP)	M	8434	0		NRC RESPONSE ANALYSIS NOT COMPLETE
	83-12-15	INSP RPT (FOLLOWUP)	E	8328	0		0737 IIF1 STEAM LINE MONITOR CASE CONSTRUCTION & SHIELDING
		INSP RPT (FOLLOWUP)	E	8330	0		



10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-12-15	INSP RPT (FOLLOWUP)	E	8434	0		COMPLETE EPIP REVISION AND REVIEW FOR ADEQUACY
	83-12-16	INSP RPT (FOLLOWUP)	M		0		0737 IIF1 ATT2 IODINE & PARTICULATE SAMPLING CONSIDERATIONS
		INSP RPT (FOLLOWUP)	M	8434	0		COMPLETE PROCEDURES FOR HANDLING POST ACCIDENT FILTERS
	83-12-18	INSP RPT (FOLLOWUP)	M	8434	0		0737 IIF1 ATT3 HIGH RANGE CONTAINMENT MONITORS
	83-12-19	INSP RPT (FOLLOWUP)	M	8434	0		0737 IIB3 PASS
	83-12-20	INSP RPT (FOLLOWUP)	M		0		0737 IIB3 CLARIFICATION 8&9 OFFSITE LABORATORY
		INSP RPT (FOLLOWUP)	M	8431	0		CHANGE PASS BACKUP LAB TO UNIT 2 PROPOSED-REQUIREMENTS WOULD INCLUDE WASTE HANDLING, VENT., MONITORING
		INSP RPT (FOLLOWUP)	M	8434	0		
	83-12-21	INSP RPT (FOLLOWUP)	M		0		FSAR 12.5.2.2.5-NO PORTABLE CAMS HAVE BEEN PROCURED
		INSP RPT (FOLLOWUP)	M	8405	0		CAM'S NOT ORDERED-LICENSEE TAKING ACTION TO CORRECT
	83-12-22	INSP RPT (FOLLOWUP)	M		0		FSAR 12.5.2.2.5-EXAMINE FIXED & MOVABLE AIR MONITORS

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 9

DOCKET	ITEM-NUH	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-04	INSP RPT (FOLLOWUP)	P	8401	0		EP PLAN & STAFF AUGMENTATION NOT CONSISTENT WITH NUREG-0654
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-14	INSP RPT (FOLLOWUP)	P	8401	0		CR, TSC, OSC & EOC NOT COMPLETED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-17	INSP RPT (FOLLOWUP)	P	8401	0		BACKUP LAB NOT FULLY EQUIPPED AND LICENSED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-21	INSP RPT (FOLLOWUP)	M	8401	C		AREA, PROCESS & EFFLUENT MONITORING SYSTEMS NOT INSTALLED
	83-14-22	INSP RPT (FOLLOWUP)	P	8401	0		NONRADIATION MONITORS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-25	INSP RPT (FOLLOWUP)	P	8401	0		ERFDADS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 10

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-29	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR PAS NOT WRITTEN
	83-14-30	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR EFFLUENT MONITORS NOT WRITTEN
	83-14-32	INSP RPT (FOLLOWUP)	P	8401	0		CARD READER SYSTEM NOT OPERATIONAL
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-17-02	INSP RPT (FOLLOWUP)	C		0		SIT SAFEND TO NOZZLE WELD REQUIRES RT
	83-25-01	INSP RPT (FOLLOWUP)	R		0		FOLLOWUP OF RTD THERMOWELL FAILURES
	83-26-02	INSP RPT (FOLLOWUP)	O		0		RG 1.33 ITEMS APPARENTLY NOT COVERED BY PLANT PROCEDURES
	83-30-01	INSP RPT (FOLLOWUP)	M		0		FUEL BLDG 180 PROBE-SAMPLE LINE PARA. 4.A
	83-33-01	INSP RPT (FOLLOWUP)	M		0		CRACKS RMS INTERFACE REVIEW
	83-3A-01	INSP RPT (FOLLOWUP)	R		0		QUALIFICATION OF CONTAINMENT WATER LEVELS
	83-39-03	INSP RPT (FOLLOWUP)	M		0		BREATHING AIR SUPPLY SYSTEM FOR USE WITH AIRLINE-SUPPLIED MASKS & HOODS

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 11

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-39-03	INSP RPT (FOLLOWUP)	M	8405	0		DIESEL POWERED COMPRESSOR BEING CONSIDERED FOR AIR SUPPLY BACKUP
		INSP RPT (FOLLOWUP)	M	8431	0		60 CFM BREATHING AIR COMPRESSOR- PLANS FOR USE? SUPPORT FOR HOODS AND MASKS?
	83-41-03	INSP RPT (FOLLOWUP)	M		0		CONTROL ROOM RMS ANNUNCIATOR CAPABILITIES & PROCEDURES FOR ALARM RES
	83-41-04	INSP RPT (FOLLOWUP)	M		0		REVIEW UNMONITORED EFFLUENT RELEASE PATHWAYS SUCH AS TURBINE BUILDING
	84-01-01	INSP RPT (FOLLOWUP)	P	8426	0		GRAB SAMPLE CROSS REFERENCE TO SAFETY PRECAUTIONS
	84-04-02	INSP RPT (FOLLOWUP)	C		0		EVALUATION OF STANDARD CONDUIT ELLS
	84-07-01	INSP RPT (FOLLOWUP)	O		0		REEXAMINE COLD LICENSEE TRAINING RECORDS
	84-09-01	INSP RPT (FOLLOWUP)	M		0		DEVELOP QC PROCEDURES FOR GAMMA SPECTROSCOPY & LLD CRITERIA
	84-09-02	INSP RPT (FOLLOWUP)	M		0		TRAINING & PROFICIENCY OF GAMMA SPECTROSCOPY ANALYSTS (SFE PG 5)
	84-10-02	INSP RPT (FOLLOWUP)	C	8425	0		ACTIONS ON FP LOOSE BEAM CLAMPS AND WELDED STUDS
	84-10-04	INSP RPT (FOLLOWUP)	C		0		HVAC WALKDOWN - ADEQUATE FOR SEISMIC INPUT?

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-13-03	INSP RPT (FOLLOWUP)	H		0		3/1/84 RMS TASK FORCE MEETING & JOHN STEVENS RPT OF PROBLEMS PARA 7
	84-13-04	INSP RPT (FOLLOWUP)	H		0		CONTROL OF ACCESS TO SPENT FUEL TUBE BELLOWS
	84-15-02	INSP RPT (FOLLOWUP)	C		0		ALL UNITS-UPDATE DOCUMENTATION TO REFLECT DESIGN CHANGE IN NUMBER OF RV HOLDDOWN BOLTS
	84-18-04	INSP RPT (FOLLOWUP)	R		0	0884	SAFEGUARDS-ANOMALOUS NOISE LPBI PUMP
	84-23-01	INSP RPT (FOLLOWUP)	R		0	1084	THI T.C.S FEEDBACK OF OPS EXPERIENCE-PROCEDURE ISSUANCE
	84-23-02	INSP RPT (FOLLOWUP)	R		0	0984	OPERATOR REGUAL RE-EXAM
	84-28-03	INSP RPT (FOLLOWUP)	R		0	1084	TDAFWP MODIFICATIONS
	84-31-01	INSP RPT (FOLLOWUP)	H		0		VERIFY SAMPLE LINE FLOW RATES IN PRFOP TEST RESULTS-SEE INSPECTION REPORT FOR SAMPLING PROCEDURES

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 13

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IN-83-17	INFO NOTICE			0		DIESEL GENERATOR AUTO-START LOGIC
	IN-83-36	INFO NOTICE			8		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-34	INFO NOTICE			M		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE			M		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE			M		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B
	IN-84-55	INFO NOTICE			M		IE IN 84-55 SEAL TABLE LEAKS AT PWR
	IN-84-56	INFO NOTICE			M		IE IN-84-56 RESPIRATOR USERS NOTICE FOR CERTAIN 5-MINUTE EMERGENCY ESCAPE SCBA
	IN-84-59	INFO NOTICE			M		IN 84-59 DELIBERATE CIRCUMVENTING OF STATION HEALTH PHYSICS PROCEDURES
	IN-84-60	INFO NOTICE			M		IN 84-60 FAILURE OF AIR-PURIFYING RESPIRATOR FILTERS TO MEET EFFICIENCY REQUIREMENT
	IN-84-61	INFO NOTICE			M		IN 84-61 OVEREXPOSURE OF DIVER IN PRESSURIZED WATER REACTOR (PWR) REFUELING CAVITY

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 14

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	PJ-08-24	OTHER	F		0		DETERMINE WHETHER DUCOMMON METAL IS ON APPROVED BIDDER'S LIST
	PJ-09-16	OTHER	0		0	REF	CONDUCT NATL CIRCULATION COOLDWN TEST PRIOR TO FIRST REFUELING REF VAN BRUNT LTR 1/27/83
	PJ-82-02	OTHER	R		0		SER SECTION 7.2.3-CPC SOFTWARE PROCEDURES
	PJ-82-03	OTHER	0		0		SER SECTION 7.3.2.1-I&C PROCEDURES AND TESTING (4 ITEMS)
	PJ-82-04	OTHER	0		0		SER SECTION 7.4.3-IE BULLETIN 79-27 PROCEDURES
	PJ-82-05	OTHER	0		0		SER SECTION 9.5.1-FIRE PROTECTION MODIFICATIONS (3 ITEMS)
	PJ-82-06	OTHER	0		0		SER SECTION 9.5.1.7-FIRE PROTECTION ADMIN CONTROLS & PROCEDURES
	PJ-82-07	OTHER	0		0		SER SECTION 13.1.2.3-TRAINING FOR OPS SUPERINTENDENT (ANSI/ANS 3.1)
	PJ-82-08	OTHER	0		0		SER SECTION 13.5.2-TRAINING OF OPERATORS ON OP/MAINT PROCEDURES
	PJ-82-09	OTHER	0		0		SER SECTION 15.3.9-ATWS PROCEDURES
	PJ-82-10	OTHER	0		0		SER APPENDIX C ITEM A-44-STATION BLACKOUT PROCEDURES

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-35-01	9		0		VA ACCESS USE OF KEYCARDS
	84-35-02	9		0		VA ACCESS-USE OF DNR BUTTON TO EXIT VITAL AREAS
	84-35-03	9		0		INOPERATIVE CCTU CAMERAS
	84-35-04	9		0		SCITY TERMINAL BECOMES INOPERATIVE DURING CASCADING FIRE ALARMS
	84-35-05	9		0		FAILURE TO PROVIDE TWO-CHANNELS FOR SECURITY COMMUNICATIONS



10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 16

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-12-04	TEMP INSTR (TI)	C		0		INTERVIEWS WITH CRAFTSMEN AT CONSTRUCTION SITES
	TI-12-11	TEMP INSTR (TI)	C		0		INCREASE INSPECTION COVERAGE IN AREAS OF CONSTR. FOUND BY PAST EXPERIENCE TO NEED IMPROVEMENT
	TI-15-14	TEMP INSTR (TI)	0		0		SIS RESET PROCEDURES
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-36	TEMP INSTR (TI)	0		0		LICENSEE TRAINING STAFF MEMBERS MUST RECEIVE SRO LICENSES
	TI-15-64	TEMP INSTR (TI)	0		0		FOLLOWUP OF LICENSEE RESPONSE TO -- GL 83-28, REQUIRED ACTIONS BASED ON SALEM ATWS EVENTS
	TI-15-65	TEMP INSTR (TI)	0		0		TMI ACTION PLAN REQUIREMENT FOLLOWUP

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 17

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-04-02	INSP RPT (UNR)	C		0		COMPLIANCE W/AWS STRUCTURAL STEEL PREHEAT & RECORDS REQUIREMENTS
		INSP RPT (UNR)	C	8329	0		
		INSP RPT (UNR)	C	8436	0		CLOSE THIS ITEM ON ISSUANCE OF SSER SUPPL 6
	83-36-01	INSP RPT (UNR)	C	8404	0		CORROSION OF BURIED PIPE
		INSP RPT (UNR)	C	8410	0		
	84-10-01	INSP RPT (UNR)	C	8425	0		QUESTIONS ON VIKING SEISMIC ANALYSIS OF FP MGRS
	84-15-04	INSP RPT (UNR)	C		0		CE REVIEW OF TEST PROCEDURES AND CIPS IS NOT DOCUMENTED OR AUDITABLE
	84-15-05	INSP RPT (UNR)	C		0		ACCEPTANCE CRITERIA FOR HFT AT VARIANCE WITH DRWG, SPECIFICATION
	84-15-06	INSP RPT (UNR)	C		0		TECHNICAL CONCERN FOR SIMULTANEOUS SHIM CLEARANCE VERIFICATION
	84-15-07	INSP RPT (UNR)	C		0		LARGE VOID FOUND IN 1B REACTOR VESSEL SUPPORT PAD
	84-15-08	INSP RPT (UNR)	C		0		DISCREPANCY IN REMARKS FOUND ON 1A REACTOR VESSEL SUPPORT PAD HOLES

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PAIO VERDE 1

PAGE 18

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-15-09	INSP RPT (UNR)	C		0		ERRORS ON CODE DATA SHEETS FOR 1A REACTOR VESSEL SUPPORT PAD REWORK
	84-15-10	INSP RPT (UNR)	C		0		DEBRIS AT BASE OF RV SUPPORT COLUMN BASE
	84-20-01	INSP RPT (UNR)	C		0		RECEIVING INSPECTION DID NOT HAVE CE PD OR SPECS FOR INSPECTION
	84-25-02	INSP RPT (UNR)	C	8425	0		FIRE PROTECTION PIPING IS SUPPORTED BY CABLE TRAY SUPPORTS -VERIFY LOADS WERE INCLUDED
	84-28-02	INSP RPT (UNR)	R		0	1084	FAILURE TO FOLLOW PROCEDURE INVOLVING TRANSFER OF REACTOR COOLANT TO THE RWT

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 19

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-12- C	50.55E RPT	F		0	0130	50.55E-DIESEL GEN CONTROL CABINET WIRING=LACK OF REQ SEP BY COOPER ENERGY SERVICES (DER 81-51)
	81-12- D	50.55E RPT	F		0	0130	50.55E-LOOSE ANTI-ROTATION PINS IN CONTAINMENT SPRAY AND LP8I PUMPS (DER 81-52)
	81-12- E	50.55E RPT	F		0	0130	50.55E-MAIN CONTROL PANZL WIRING=LACK OF REQ SEP BY COMSIP CUSTOM LINE (DER 81-53)
	83-04-06	50.55E RPT	0		0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	84-01-C	50.55E RPT	C		0		50.55(E): CONTROL OF RETESTING ACTIVITIES DETERMINED NOT TO BE REPORTABLE
	84-02-C	50.55E RPT	C		0		50.55(E): EXCESSIVE RUBT 81 AND CH VALVES (ALL UNITS) FINAL RPT EXPECTED 6/21/84
	84-03-C	50.55E RPT	C		0		50.55(E): FEEDWATER ISOLATION VALVE STUCK DURING TESTING - FINAL RPT EXPECTED 5/31/84
	84-06-C	50.55E RPT	C		0		50.55(E): FOXBORO ALARM MODULE DEFECTS (ALL UNITS) - FINAL RPT EXPECTED 6/12/84
	84-08-C	50.55E RPT	C		0		50.55(E): BARTON MDL 763 TRNSMITRS DO NOT MEET SPECS (ALL UNITS) FINAL RPT EXPECTED 5/18/84
	84-10-C	50.55E RPT	C		0		50.55(E): FAILURE OF SINGLE ELEMENT RTD'S (ALL UNITS) FINAL REPORT EXPECTED 6/1/84
	84-11-C	50.55E RPT	C		0		50.55(E): PVMP INSTRUMENTATION CONDUIT CONTAMINATED WITH CHLORIDES FINAL RPT EXPECTED 5/29/84

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 20

BUCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-12-C	50,55E RPT	C		0		50,55(E): ZONE III VIOLATIONS OF RCP IA AND 80 #1 FINAL RPT EXPECTED 6/1/84
	84-13-C	50,55E RPT	C		0		50,55(E): HVAC ACCEPTANCE CRITERIA (ALL UNITS) - FINAL RPT EXPECTED 12/14/84
	84-15-C	50,55E RPT	C		0		50,55(E): UNDERSIZED PIPE RESTRAINT SUPPORT WELDS (ALL UNITS)-FINAL RPT EXP 8/3/84
	84-16-C	50,55E RPT	C		0		50,55(E): UNDERSIZED ESFAS RELAY CABINET BASEPLATS (ALL UNITS) FINAL RPT EXPECTED 6/29/84
	84-18-C	50,55E RPT	C		0		50,55(E): WIRING ERROR ON LPSI B PUMP SWITCH-FINAL RPT EXPECTED 6/12/84
	84-19-C	50,55E RPT	C		0		50,55(E): BLIND FLANGES IMPROPERLY INSTALLED (ALL UNITS)
	84-20-C	50,55E RPT	C		0		50,55(E): CONNECTING LINE TO 818 380 DAMAGED
	84-21-C	50,55E RPT	C		0		50,55(E): ROSEMONT TRANSMITTERS LOOSE NUTS
	84-22-C	50,55E RPT	C		0		50,55(E): CEA SHROUD CONTAMINATED WITH OIL
	84-23-C	50,55E RPT	C		0		50,55(E): APW VALVE LOOSE SLEEVE PIN
	84-24-C	50,55E RPT	C		0		50,55(E): ALL UNITS - LOOSE BOLTS ON LIMITORQUE OPERATORS (ALL UNITS)

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 21

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-25-C	50,55E RPT	C		0		50,55(E): ALL UNITS - CONTAINMENT AIR SUPPLY REGISTERS BY TITUS HAVE FAILED WIRE
	84-26-C	50,55E RPT	C		0		50,55(E): CIRCUIT BRKR INTERLOCK MECHANISM WAS IMPROPERLY ASSEMBLED
	84-27-C	50,55E RPT	C		0		50,55(E): HVAC INSTRUMENTATION WERE MODIFIED AFTER FINAL ACCEPTANCE BY APS MAINTENANCE
	84-28-C	50,55E RPT	C		0		50,55(E): DIESEL FUEL LINES TOUCHING PENETRATION BLEEVE
	84-29-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR HEAT EXCHANGERS HAVE SUBSTANCE BUILDUP
	84-30-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR COOLERS HAVE PARTS THAT DONT MEET ASME REQUIREMENTS
	84-31-C	50,55E RPT	C		0		50,55(E): UNSEALED PENETRATIONS IN M888 BUILDING
	84-33-C	50,55E RPT	C		0		50,55(E): UNIT 1 MISSING WELD ON PIPE SUPPORT I81070H011
	84-34-C	50,55E RPT	C		0		50,55(E): 81Y BOLTING UNDERTORQUED/ WASHERS TOO SMALL
	84-35-C	50,55E RPT	C		0		50,55(E): POTENTIOMETERS ON PPS ARE DRIFTING-THIS AFFECTS SAFETY ANALYSIS
	84-36-C	50,55E RPT	C		0		50,55(E): TWO INCH WPBI VALVE STALL JUST OFF CLOSED POSITION-GUIDE HAS CHATTER - RELATED TO DER 83-63

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 22

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-17-C	50,55E RPT	C		0		50,55(E): UNAUTHORIZED/UNQUALIFIED DUCT SEALANT USED ON HVAC DUCT-NOTE THIS WAS FOUND BY NRC IN 84-10
	84-39-C	50,55E RPT	C		0		50,55E: LP8I PUMP HAS RUMBLING NOISES
	84-40-C	50,55E RPT	C		0		50,55E: APW PUMP IMPELLORS HAVE MIC-DISCOVERED IN US-APPLICABLE TO ALL UNITS
	84-41-C	50,55E RPT	C		0		50,55(E): REG IV INSPECTION CARDINAL INDUSTRY PRODUCTS HAD INDETERMINATE QUALITY
	84-42-C	50,55E RPT	C		0		50,55E: MOTOR OPERATOR TORQUE SWITCHES IMPROPERLY REPLACED NOT QUALIFIED
	84-43-C	50,55E RPT	C		0		50,55(E): 3 INCH BORG WARNER VALVE BIV HV 609 FAILED TO OPEN
	84-44-C	50,55E RPT	C		0		50,55E: PART 21 REPORT ISSUED ON GAULIN CHARGING PUMP BLOCKS FATIGUE FAILURE
	84-45-C	50,55E RPT	C		0		50,55E: KAMAN RADIATION MEASURING INSTRUMENTS ARE IMPROPERLY INSTALLE
	84-46-C	50,55E RPT	C		0		50,55E: NOZZLE LOADS FROM 20 INCH PIPES IN REFUELING WATER TANK NOT PREVIOUSLY EVALUATED
	84-48-C	50,55E RPT	C		0		50,55E: GAULING IN MSIV PLUGS DURING INSTALLATION CAUSE OPERATING LEVERS TO VIBRATE LOOSE
	84-49-C	50,55E RPT	C		0		50,55(F): APW VIBRATES IN MINICIRC ALSO -REFER TO DEP 84-23 FOR SIMILA PROBLEM IN FULL FLOW RECIRC

10/02/80

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 23

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-50-C	50.55E RPT	C		0		50.55E1 TURBINE DRIVEN AUX FEED PUM FAILED TO QUICK START FROM AMBIENT CONDITIONS
	84-51-C	50.55E RPT	C		0		50.55E1 MSIV MADE BY ANCHOR-DARLING FAILED TO CLOSE IN FIVE SECONDS.
	84-52-C	50.55E RPT	C		0		50.55(E)1B8E FLANGE RESISTOR ON ATMOSPHERIC STEAM DUMPS NOT STRONG ENOUGH TO SURVIVE A SEISMIC EVENT
	84-54-C	50.55E RPT	C		0		50.55(E)1BUMP ISOLATION VALVE COULD NOT BE ELECTRICALLY OPENED AFTER BEING MANUALLY CLOSED
	84-55-C	50.55E RPT	C		0		50.55(E)1UNQUALIFIED FOXBORO MODULES HAVE BEEN INSTALLED IN CLASS 1E ELECTRICAL CABINETS
	84-56-C	50.55E RPT	C		0		50.55(E)1HALON & CO2 SYS FIRE DAMPERS DO NOT FULLY CLOSE UNDER NORMAL OPERATING FLOW
	84-57-C	50.55E RPT	C		0		50.55(E)1CONTAINMENT ISOLATION VALVE IN RAD. WASTE DRAIN FAILED TO CLOSE IN 10 SECONDS.
	84-61-C	50.55E RPT	C		0		50.55(E)1POSSIBLE AUXILIARY PRESSURIZER SPRAY FAILURE-IE LOOP CHARGING V-LVE STICKS OPEN
	84-62-C	50.55E RPT	C		0		50.55(E)1SAFLGRD SEQUENCING PRBLMS WITH SIGNALS TO THE MPSI AND 480 VOLT LOAD CTR BREAKERS
	84-63-C	50.55E RPT	C		0		50.55(E)1TARGET ROCK VALVE FAILED TO CLOSE ON SIT WHEN PRESSURE DROPPED TO 200 PSIG DURING A TEST
	84-64-C	50.55E RPT	C		0		50.55(E)1PIPE SUPPORT SNUBBERS FOUND LOCKED UP AFTER HOT PUMP TEST



10/02/80

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 24

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-65-C	50,55E RPT	C		0		50,55E INSTRUMENT LEAD OUTER CABING LOCATED ON UPPER GUIDE STRUCTURE SPLIT EXPOSING CERAMIC INSULATOR
	84-66-C	50,55E RPT	C		0		50,55(E) DOWNCOMER FEEDWATER ISO VALVE FAILED TO COMPLETELY CLOSE UNDER DYNAMIC TEST CONDITIONS
	84-67-C	50,55E RPT	C		0		50,55(E) RED POSITION SWITCH FAILED TO CHANGE STATE W/THE VALVE CHANGE STATE USING REDUCED VOLTAGE
	84-68-C	50,55E RPT	C		0		50,55(E) ESSENTIAL CHILLER 'A' TEMP SWITCH TRIPS OFF AFTER BIAS FOL BY LOSS OF POWER-LOCKING RESTART
	84-69-C	50,55E RPT	C		0		50,55(E) IRPS CHANNEL C, RELAY K-3 FAILED TO CLOSE DURING SAFEGUARDS TESTING

10/02/84

REGION 5  
LICENSEE EVENT REPORT

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	81-08-X1	SPECIAL RPT.	C		0		RY FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	81-10-21	PART 21	C		0		PART 21-(PARSONS PEBBLES) DIESEL GENERATOR SYSTEM DEFECT

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 3

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IA-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REVI 1/8UP1 2
	IB-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-80-06	IE BULLETIN	C		0		ESF RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IA-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SHUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-02	IE BULLETIN	C	8234	0		PORV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IB-82-02	IE BULLETIN	C	8413	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-82-04	IE BULLETIN	C		0		DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IA-83-01	IE BULLETIN	C	8413	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 3

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IB-83-03	IE BULLETIN	C	8413	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEMS OF DG
	IB-83-04	IE BULLETIN	C	8413	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	IB-83-06	IE BULLETIN	C		0		NC MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLD CITY HOUSTON
	IB-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDLENT PRODUCTS SOLD BY RAY MILLER, INC
	IB-83-08	IE BULLETIN	C		0		C/R'S WITH UV TRIP ON SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	IB-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE HFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 3

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-79-21	IE CIRCULAR	C	R231	0		
	IC-80-01	IE CIRCULAR	C	R308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	R308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	R308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	R308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	R413	0		
	IC-80-14	IE CIRCULAR	C	R311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	R413	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	R413	0		STEAM VOIDING IN RCS DURING COOLDOWN

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-81-12	IE CIRCULAR			0		INADEQUATE PERIODIC BREAKER TEST PROCEDURES
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MBIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8413	0		
	83-15-01	IE CIRCULAR	C	8337	0		EXCESSIVE TENSION ON TENDONS

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	84-03-01	INSP RPT (ENF)	C		0		STORAGE OF 480 V.MCC IN LEVEL 0 STORAGE
	84-07-14	INSP RPT (ENF)	C		0		REGEN HEAT EXCHANGER UPPER SUPPORT JAM NUT ADJUSTMENT & TORQUE
	84-07-17	INSP RPT (ENF)	C		0		CABLE REELS NOT TAGGED NONCONFORMING
	84-12-05	INSP RPT (ENF)	C	8425	0		IMPROPER ACCEPTANCE OF HONEYWELL INSTRUMENTS

10/02/80

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-03-02	INSP RPT (FOLLOWUP)	C	8311	0	0303	WATER USED TO COOL STAINLESS STEEL WELDS
		INSP RPT (FOLLOWUP)	C	8317	0		
		INSP RPT (FOLLOWUP)	C	8329	0		
84-07-16		INSP RPT (FOLLOWUP)	C		0		REINSPECTION OF PIPE HANGERS AND SUPPORTS - UNIT 3



10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-82-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCRA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B



10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN-LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING-REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-54	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES-DUE EARLY R2
	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	TI-15-60	TEMP INSTR (II)	C		0		0737 INSPECTION LISTING FOR MONS DUE 7/82
	TI-15-64	TEMP INSTR (TI)			0		INSPECTION FOLLOWUP BASED ON SALEM ATMS EVENTS

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET ITEM NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	62-09-02 INSP RPT (UNR)	C		0		FLARE VEVEL WELDS
86-07-13	INSP RPT (UNR)	C		0		VALVE 3P81EV235 8YUD THREAD ENGAGEMENT INTO BONNET
86-09-01	INSP RPT (UNR)	C		0		SEE 50-528/84-20-01

10/02/84

REGION 3  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-01-28	50.55E RPT	0		0	0228	50.55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50.55E RPT	0		0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50.55E RPT	0		0	0505	50.55E-LP81 PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50.55E RPT	C		0		50.55(E)1 BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84

DOCKET ITEM NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	81-08-X1 SPECIAL RPT.	C		0		RY FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
81-10-21	PART 21	C		0		PART 21-(PARSONS PEEBLES) DIESEL GENERATOR SYSTEM DEFECT

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 2

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IB-79-14	IE BULLETIN	C	8231	0		
	IB-79-21	IE BULLETIN	C	8308	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV 1/SUP 2 TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-12	IE BULLETIN	C	8111	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-81-01	IE BULLETIN	C		0		
	IB-81-02	IE BULLETIN	C	8234	0		SURVEILLANCE OF MECHANICAL SNUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
		IE BULLETIN	C	8305	0		PCRV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
	IB-82-02	IE BULLETIN	C	8420	0		
	IB-82-04	IE BULLETIN	C		0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-83-01	IE BULLETIN	0	8420	0		DEFICIENCIES ON PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
							FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL



10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 2

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IR-83-03	IE BULLETIN	C	8420	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEM OF AG
	IB-83-04	IE BULLETIN	C	8420	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	IB-83-06	IE BULLETIN	C		0		NO MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLAND CITY HOUSTON
	IR-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	IB-83-08	IE BULLETIN	C		0		C/B'S WITH UV TRIP IN SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	IR-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE HPA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8420	0		
	IC-80-14	IE CIRCULAR	C	8311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	8420	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	8420	0		STEAM VOIDING IN RCS DURING COOLDOWN

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 8

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IE CIRCULAR	C	A311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
	IE CIRCULAR	C	8420	0		

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

DOCKET ITEM#	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-08-04	INSP RPT (DEV)		C		DUCT SEALANT NOT QUALIFIED

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-04-01 INSP RPT (ENF)	C		0		CABLE BEND RADIUS WRONG
	84-08-02 INSP RPT (ENF)	C		0		IMPROPER HVAC BOLTING WELDING SHIMMING
	84-16-03 INSP RPT (ENF)	R		0	0884	NONCOMPLIANCE-IMPROPER DRAWING CONTROL IN CONTROL ROOM

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 7

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-04-02	INSP RPT (FOLLOWUP)	C		0		FACTORY EL RADIUS FOR CABLE
	84-08-01	INSP RPT (FOLLOWUP)	C		0		HVAC CRAFT TRAINING REQUIRED?
	84-10-01	INSP RPT (FOLLOWUP)	M		0		CONTROL OF ACCESS TO SPENT FUEL TUBE BELLOWS

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IN-82-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-30	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-BCBA 4500 PSI LUXFER CYLINDERS
	IN-84-86	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90529	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN-LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ABME CERTIFICATION SYSTEM REQUIREMENTS
	TI-13-01	TEMP INSTR (TI)	0		0		TRANSFER OF SRP REVIEW FROM NRR TO IE
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-48	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING-REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-58	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES-DUE EARLY R2



10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 10

DOCKET	ITEM-NU	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82
	TI-15-60	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 7/82
	TI-15-64	TEMP INSTR (TI)	0		0		INSPECTION FOLLOWUP BASED ON SALEM ATWS EVENTS



10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	83-01-28	50,55E RPT	0		0	0228	50,55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50,55E RPT	0		0	0505	50,55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50,55E RPT	0		0	0505	50,55E-LPSI PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50,55E RPT	C		0		50,55(E): BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84
	84-04-C	50,55E RPT	C		0		50,55(E): CAD WELDING FOR CATHODIC PROTECTION SYSTEM NOT DOCUMENTED FINAL RPT EXPECTED 5/4/84
	84-38-C	50,55E RPT	C		0		50,55E: PIPE SUPPORT INSTALLED INCORRECTLY
	84-53-C	50,55E RPT	C		0		50,55(E): MISSING NUTS & LOOSE BOLTS FOUND ON VALVES LOC IN CONTAINMENT & CHARGING SYSTEM
	84-54-C	50,55E RPT	C		0		50,55(E): CABLES ARE IN CONTACT WITH SHARP METAL EDGES OF FIRE STOPS ABOVE THE MCC.
	84-60-C	50,55E RPT	C		0		50,55(E): INCOMPATABLE LUBRICANTS WERE USED ON 50 LIMITORQUE VALVES



10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50920	18-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REVI 1/SUPI 2
	18-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	18-80-04	IE BULLETIN	C		0		EGP RESET CONTROLS - DL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	18-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	18-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	18-80-16	IE BULLETIN	C	8308	0		
	18-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	18-81-02	IE BULLETIN	C	8234	0		POV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	18-82-02	IE BULLETIN	C	8422	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	18-83-01	IE BULLETIN	C	8422	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90520	18-03-03	IE BULLETIN	C	8422	0		CHECK VALVE FAILURES IN RAW WATER SYS OF DIESEL GENERATORS
	18-03-04	IE BULLETIN	C	8422	0		FAILURE OF UNDERVOLTAGE TRIP FUNCTION OF REACTOR TRIP BREAKER
	18-03-07	IE BULLETIN	C		0		APPARENTLY FRAUDLENT PRODUCTS SOLD BY RAY MILLER, INC
	18-04-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90528	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0		0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
		IE CIRCULAR	0	8308	0		TRANSFER TO OPS PER PJ/PN DISCUSSION 3/21/83
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8422	0		
	IC-81-03	IE CIRCULAR	C	8422	0		INOP SEISMIC INSTRUMENTATION
	IC-81-10	IE CIRCULAR	0	8422	0		STEAM VOIDING IN RCS DURING COOLDOWN
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8422	0		





REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	82-30-01	INSP RPT (ENP)	F		0		NONCOMPLIANCE STEAM GENERATOR CHEMICAL
	83-10-01	INSP RPT (ENP)	C		0		TERMINATION CARDS INACCURATE
	83-38-01	INSP RPT (ENP)	C	8436	0		QC PERSONNEL ACCEPTING CONDITIONS NOT IN DRAWING
	83-38-08	INSP RPT (ENP)	C		0		UNSATISFACTORY BOLTING ACCEPTED BY QC
	83-38-17	INSP RPT (ENP)	C		0		CABLE TRAY CONNECTIONS DISCONNECTED
	83-38-18	INSP RPT (ENP)	C		0		HANGER WELDS NOT IN DRAWING
	83-38-19	INSP RPT (ENP)	C		0		WELD OVERLAP ON INSTRUMENT RACK SUPPORT
	83-38-20	INSP RPT (ENP)	C		0		LUMBER IN CHANNEL C ELECTRICAL RACEWAY
	83-40-01	INSP RPT (ENP)	R		0		FAILURE TO FOLLOW PROCEDURES
	84-15-01	INSP RPT (ENP)	C	8436	0		WELDERS QUALIFIED AFTER THE FACT
	84-15-12	INSP RPT (ENP)	C		0		ALL UNITS MINIMUM THREAD ENGAGEMENT CRITERIA FOR THREADED FASTENERS SEE REPORT 50-530/84-07

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

```

.....
DOCKET ITEM-NUM TYPE FOLLOWUP FOLLOWUP STATUS ACTION DATE DESCRIPTIVE
.....
BRANCH REPORT NO. TITLE
.....

```

```

.....
S0226 84-18-01 INSP RPT (ENF) R 0 0884 NONCOMPLIANCE-NONCONTROL OF
EQUIPMENT AND PARTS
84-18-02 INSP RPT (ENF) R 0 0884 FAILURE TO TAG
NONCOMPLIANCE-NONCONTROL OF
NONCONFORMING PARTS
84-21-01 INSP RPT (ENF) F 0 FAILURE TO ISSUE AN NCR
MONEYWELL'S INSTRUMENTS MADE
IMPROPER BY OTHERS
84-25-01 INSP RPT (ENF) C 0 8425 BEISMIC ANALYSIS OF THE FIRE
PROTECTION SYSTEM IS IMPROPER
84-28-01 INSP RPT (ENF) R 0 1084 FAILURE TO PROPERLY DISPOSITION AN
SPR
.....

```

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

```

.....
DOCKET ITEM-NUM      TYPE      FOLLOWUP FOLLOWUP STATUS ACTION DATE  DESCRIPTIVE
.....              .....      .....      .....      .....      .....      .....
BRANCH REPORT NO.
.....

```

```

.....
50528 83-02-03 INSP RPT (FOLLOWUP)  C      8317  0      COLD SPRING OF ECM PIPE
.....
REQUIRES APS ACTION

```

```

.....
INSP RPT (FOLLOWUP)  C      8436  0

```

```

.....
83-03-05 INSP RPT (FOLLOWUP)  M      0      0      FUEL BLDG EXHAUST MONITOR RU-143
.....
8146 SAMPLE POINT LESS THAN 5
.....
DUCT DIAM

```

```

.....
83-12-01 INSP RPT (FOLLOWUP)  M      0      0      F84R 12.5.2.1.1 ITEM 8-ROODS
.....
8 AIR SUPPLY RESOLUTION ADD
.....
OR DELETE
.....
0737 IIFI CALIBRATION RECORDS

```

```

.....
83-12-12 INSP RPT (FOLLOWUP)  M      8328  0

```

```

.....
INSP RPT (FOLLOWUP)  M      8330  0

```

```

.....
INSP RPT (FOLLOWUP)  M      8434  0

```

```

.....
83-12-14 INSP RPT (FOLLOWUP)  M      0      0      0737 IIFI VENDOR CALIBRATION
.....
DATA

```

```

.....
INSP RPT (FOLLOWUP)  M      8434  0      NRC RESPONSE ANALYSIS NOT COMPLETE

```

```

.....
83-12-15 INSP RPT (FOLLOWUP)  E      8328  0      0737 IIFI STEAM LINE MONITOR
.....
CASE CONSTRUCTION & SHIELDING

```

```

.....
INSP RPT (FOLLOWUP)  E      8330  0

```

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

```

.....
DOCKET ITEM-NUM      TYPE      FOLLOWUP FOLLOWUP STATUS ACTION DATE  DESCRIPTIVE
.....              .....      .....      .....      .....      .....      .....
BRANCH              REPORT NO.
.....
.....
.....

```

```

.....
80528 83-12-18 INSP RPT (FOLLOWUP) E 8434 0      0      COMPLETE EPID REVISION AND REVIEW
FOR ADEQUACY
.....
83-12-18 INSP RPT (FOLLOWUP) M      0      0737 IIF1 AT12 IODINE &
PARTICULATE SAMPLING
CONSIDERATIONS
.....
INSP RPT (FOLLOWUP) M 8434 0      0      COMPLETE PROCEDURES FOR HANDLING
POST ACCIDENT FILTERS
.....
83-12-18 INSP RPT (FOLLOWUP) M 8434 0      0      0737 IIF1 AT13 HIGH RANGE
CONTAINMENT MONITOR
.....
83-12-19 INSP RPT (FOLLOWUP) M 8434 0      0      0737 IIB3 PASS
.....
83-12-20 INSP RPT (FOLLOWUP) M      0      0737 IIB3 CLARIFICATION 8&9
OFFSITE LABORATORY
.....
INSP RPT (FOLLOWUP) M 8431 0      0      CHANGE PASS BACKUP LAB TO UNIT 2
PROPOSED-REQUIREMENTS SHOULD INCLUDE
WASTE HANDLING,VENT,MONITORING
.....
INSP RPT (FOLLOWUP) M 8434 0      0
.....
83-12-21 INSP RPT (FOLLOWUP) M      0      0      PSAR 12.5.2.2.5-NO PORTABLE
CAMS HAVE BEEN PROCURED
.....
INSP RPT (FOLLOWUP) M 8405 0      0      CAM'S NOT ORDERED-LICENSEE TAKING
ACTION TO CORRECT
.....
83-12-22 INSP RPT (FOLLOWUP) M      0      0      PSAR 12.5.2.2.5-EXAMINE FIXED
& MOVABLE AIR MONITORS
.....

```

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-04	INSP RPT (FOLLOWUP)	P	8401	0		EP PLAN & STAFF AUGMENTATION NOT CONSISTENT WITH NUREG-0454
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-14	INSP RPT (FOLLOWUP)	P	8401	0		CR, TSC, OSC & EOC NOT COMPLETED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-17	INSP RPT (FOLLOWUP)	P	8401	0		BACKUP LAB NOT FULLY EQUIPPED AND LICENSED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-21	INSP RPT (FOLLOWUP)	M	8401	0		AREA, PROCESS & EFFLUENT MONITORING SYSTEMS NOT INSTALLED
	83-14-22	INSP RPT (FOLLOWUP)	P	8401	0		NONRADIATION MONITORS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-14-25	INSP RPT (FOLLOWUP)	P	8401	0		ERFDADS NOT INSTALLED
		INSP RPT (FOLLOWUP)	P	8426	0		

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

SOCKET ITEM-NUM	TYPE	FOLLOWUP	BRANCH	STATUS	ACTION DATE	REPORT NO.	DESCRIPTIVE TITLE
50529	83-14-29	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR PAB NOT WRITTEN
	83-16-30	INSP RPT (FOLLOWUP)	M	8401	0		PROCEDURES FOR EFFLUENT MONITORS NOT WRITTEN
	83-16-32	INSP RPT (FOLLOWUP)	P	8401	0		CARD READER SYSTEM NOT OPERATIONAL
		INSP RPT (FOLLOWUP)	P	8426	0		
	83-17-02	INSP RPT (FOLLOWUP)	C		0		BIT SAFEND TO NOZZLE WELD REQUIRES RT
	83-25-01	INSP RPT (FOLLOWUP)	R		0		FOLLOWUP OF RTD THERMOWELL - ATURES
	83-26-02	INSP RPT (FOLLOWUP)	O		0		PG 1.33 ITEMS APPARENTLY NOT COVERED BY PLANT PROCEDURES
	83-30-01	INSP RPT (FOLLOWUP)	M		0		FUEL MLOG 160 PROBE-SAMPLE LINE PARA. 8.4
	83-33-01	INSP RPT (FOLLOWUP)	M		0		CRACKS RMS INTERFACE REVIEW
	83-38-01	INSP RPT (FOLLOWUP)	R		0		QUALIFICATION OF CONTAINMENT WATER LEVELS
	83-39-03	INSP RPT (FOLLOWUP)	M		0		BREATHING AIR SUPPLY SYSTEM FOR USE WITH AIRLINE-SUPPLIED MASKS & MOODS

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET ITEM#	NUM	TYPE	FOLLOWUP	STATUS	ACTION DATE	DESCRIPTIVE TITLE
		BRANCH REPORT NO.				
8026	81-19-03	INSP RPT (FOLLOWUP)	M	0	8405	DIESEL POWERED COMPRESSOR BEING CONSIDERED FOR AIR SUPPLY JACKUP
		INSP RPT (FOLLOWUP)	M	0	8431	60 CFM BREATHING AIR COMPRESSOR- PLANS FOR USEY SUPPORT FOR HOODS AND MASKS?
	83-41-03	INSP RPT (FOLLOWUP)	M	0		CONTROL ROOM RMS ANNUNCIATOR CAPABILITIES & PROCEDURES FOR ALARM RES
	83-41-04	INSP RPT (FOLLOWUP)	M	0		REVIEW UNMONITORED EFFLUENT RELEASE PATHWAYS SUCH AS TURBINE BUILDING
	84-01-01	INSP RPT (FOLLOWUP)	P	0	8426	GRAB SAMPLE CROSS REFERENCE TO SAFETY PRECAUTIONS
	84-04-02	INSP RPT (FOLLOWUP)	C	0		EVALUATION OF STANDARD CONDUITY BELLS
	84-07-01	INSP RPT (FOLLOWUP)	O	0		REEXAMINE COLD LICENSEE TRAINING RECORDS
	84-09-01	INSP RPT (FOLLOWUP)	M	0		DEVELOP QC PROCEDURES FOR GAMMA SPECTROSCOPY & LLD CRITERIA
	84-09-02	INSP RPT (FOLLOWUP)	M	0		TRAINING & PROFICIENCY OF GAMMA SPECTROSCOPY ANALYSTS (SFE PG 5)
	84-10-02	INSP RPT (FOLLOWUP)	C	0	8425	ACTIONS ON FP LOOSE BEAM CLAMPS AND WELDED STUDS
	84-10-04	INSP RPT (FOLLOWUP)	C	0		HVAC WALKDOWN - ADEQUATE FOR SEISMIC INPUT?

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

```

.....
DOCKET ITEM#NUM      TYPE      FOLLOWUP FOLLOWUP STATUS ACTION DATE      DESCRIPTIVE
.....              .....
BRANCH REPORT NO.
.....

```

```

.....

```

```

.....
50520 84-13-03 INSP RPT (FOLLOWUP) M 0 3/1/84 RMB TASK FORCE MEETING

```

```

      & JOHN STEVENS RPT OF PROBLEMS
      PARA 7
      CONTROL OF ACCESS TO SPENT FUEL
      TUBE BELLOW

```

```

.....
84-13-04 INSP RPT (FOLLOWUP) M 0

```

```

.....
84-15-02 INSP RPT (FOLLOWUP) C 0

```

```

      ALL UNITS-UPDATE DOCUMENTATION TO
      REFLECT DESIGN CHANGE IN NUMBER
      OF RV MOLODOWN BOLTS

```

```

.....
84-18-04 INSP RPT (FOLLOWUP) R 0 0884 SAFEGUARDS-AMALGAMOUS NOISE

```

```

      LPSI PUMP

```

```

.....
84-23-01 INSP RPT (FOLLOWUP) R 0 1084 THE I.C.S FEEDBACK OF OPR

```

```

      EXPERIENCE-PROCEDURE ISSUANCE

```

```

.....
84-23-02 INSP RPT (FOLLOWUP) R 0 0984 OPERATOR REGUAL RE-EXAM

```

```

.....
84-28-03 INSP RPT (FOLLOWUP) R 0 1084 TDAFNP MODIFICATIONS

```

```

      VERIFY SAMPLE LINE FLOW RATES IN
      PREOP TEST RESULTS-SEE INSPECTION
      REPORT FOR SAMPLING PROCEDURES

```

```

.....
84-31-01 INSP RPT (FOLLOWUP) M 0

```



REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	IN-83-17	INFO NOTICE	0		0		DIESEL GENERATOR AUTO-START LOGIC
	IN-83-36	INFO NOTICE	8		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B
	IN-84-55	INFO NOTICE	M		0		IE IN 84-55 SEAL TABLE LEAKS AT PWR
	IN-84-56	INFO NOTICE	M		0		IE IN-84-56 RESPIRATOR USERS NOTICE FOR CERTAIN 5-MINUTE EMERGENCY ESCAPE SCBA
	IN-84-59	INFO NOTICE	M		0		IN 84-59 DELIBERATE CIRCUMVENTING OF STATION HEALTH PHYSICS PROCEDURES
	IN-84-60	INFO NOTICE	M		0		IN 84-60 FAILURE OF AIR-PURIFYING RESPIRATOR FILTERS TO MEET EFFICIENCY REQUIREMENT
	IN-84-61	INFO NOTICE	M		0		IN 84-61 OVEREXPOSURE OF DIVER IN PRESSURIZED WATER REACTOR (PWR) REFUELING CAVITY

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
5052b	PJ-00-24	OTHER	F		0		DETERMINE WHETHER DUCOMMON METAL IS ON APPROVED BIDDER'S LIST
	PJ-09-16	OTHER	0		0	REF	CONDUCT NATL CIRCULATION COOLDOWN TEST PRIOR TO FIRST REFUELING REF VAN BRUNT LTR 1/27/83
	PJ-82-02	OTHER	R		0		SER SECTION 7.2.3-CPC SOFTWARE PROCEDURES
	PJ-82-03	OTHER	0		0		SER SECTION 7.3.2.1-I&C PROCEDURES AND TESTING (4 ITEMS)
	PJ-82-04	OTHER	0		0		SER SECTION 7.4.3-IE BULLETIN 70-27 PROCEDURES
	PJ-82-05	OTHER	0		0		SER SECTION 9.5.1-FIRE PROTECTION MODIFICATIONS (3 ITEMS)
	PJ-82-06	OTHER	0		0		SER SECTION 9.5.1.7-FIRE PROTECTION ADMIN CONTROLS & PROCEDURES
	PJ-82-07	OTHER	0		0		SER SECTION 13.1.2.3-TRAINING FOR OPS SUPERINTENDENT (ANSI/ANS 3.1)
	PJ-82-08	OTHER	0		0		SER SECTION 13.5.2-TRAINING OF OPERATORS ON OP/MAINT PROCEDURES
	PJ-82-09	OTHER	0		0		SER SECTION 15.3.9-ATMS PROCEDURES
	PJ-82-10	OTHER	0		0		SER APPENDIX C ITEM 4-44-STATION BLACKOUT PROCEDURES

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

PAGE 15

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50320	84-35-01	OTHER	S		0		VA ACCESS USE OF KEYCARDS
	84-35-02	OTHER	S		0		VA ACCESS-USE OF D&R BUTTON TO EXIT VITAL AREAS
	84-35-03	OTHER	S		0		INOPERATIVE CCTV CAMERAS
	84-35-04	OTHER	S		0		SCTY TERMINAL BECAME INOPERATIVE DURING CASCADING FIRE ALARMS
	84-35-05	OTHER	S		0		FAILURE TO PROVIDE TWO-CHANNELS FOR SECURITY COMMUNICATIONS

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50526	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-12-04	TEMP INSTR (TI)	C		0		INTERVIEWS WITH CRAFTSMEN AT CONSTRUCTION SITES
	TI-12-11	TEMP INSTR (TI)	C		0		INCREASE INSPECTION COVERAGE IN AREAS OF CONSTR. FOUND BY PAST EXPERIENCE TO NEED IMPROVEMENT
	TI-15-14	TEMP INSTR (TI)	0		0		SIS RESET PROCEDURES
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-36	TEMP INSTR (TI)	0		0		LICENSEE TRAINING STAFF MEMBERS MUST RECEIVE SRO LICENSES
	TI-15-64	TEMP INSTR (TI)	0		0		FOLLOWUP OF LICENSEE RESPONSE TO -- GL 83-28, REQUIRED ACTIONS BASED ON SALEM ATWS EVENTS
	TI-15-65	TEMP INSTR (TI)	0		0		TMI ACTION PLAN REQUIREMENT FOLLOWUP

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

DOCKET ITEM#	NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50526	81-04-02	INSP RPT (UNR)	C		0		COMPLIANCE W/AWS STRUCTURAL STEEL PREHEAT & RECORDS REQUIREMENTS
		INSP RPT (UNR)	C	8329	0		
		INSP RPT (UNR)	C	8436	0		CLOSE THIS ITEM ON ISSUANCE OF SSER SUPPL 6
	03-36-61	INSP RPT (UNR)	C	8404	0		CORROSION OF BURIED PIPE
		INSP RPT (UNR)	C	8410	0		
	84-10-01	INSP RPT (UNR)	C	8425	0		QUESTIONS ON VIKING SEISMIC ANALYSIS OF FP MGRS
		INSP RPT (UNR)	C		0		CE REVIEW OF TEST PROCEDURES AND CIPB IS NOT DOCUMENTED OR AUDITABLE
	84-15-05	INSP RPT (UNR)	C		0		ACCEPTANCE CRITERIA FOR HPT AT VARIANCE WITH DRMG. SPECIFICATION
		INSP RPT (UNR)	C		0		TECHNICAL CONCERN FOR SIMULTANEOUS SM CLEARANCE VERIFICATION
	84-15-07	INSP RPT (UNR)	C		0		LARGE VOID FOUND IN 1B REACTOR VESSEL SUPPORT PAD
	84-15-08	INSP RPT (UNR)	C		0		DISCREPANCY IN REMORK FOUND ON 1A REACTOR VESSEL SUPPORT PAD HOLES

REGION 3  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET ITEM#	NUM	TYPE	FOLLOWUP	BRANCH	REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50328	84-15-09	INSP RPT (UNR)	C			0		ERRORS ON CODE DATA SHEETS FOR 1A REACTOR VESSEL SUPPORT PAD REMORK
	84-15-10	INSP RPT (UNR)	C			0		DEBRIS AT BASE OF RV SUPPORT COLUMN BASE
	84-20-01	INSP RPT (UNR)	C			0		RECEIVING INSPECTION DID NOT HAVE CE PO OR SPECS FOR INSPECTION
	84-25-02	INSP RPT (UNR)	C		8425	0		PIPE PROTECTION PIPING IS SUPPORTED BY CABLE TRAY SUPPORTS - VERIFY LOADS WERE INC'USED
	84-28-02	INSP RPT (UNR)	R			0	1084	FAILURE TO FOLLOW PROCEDURE INVOLVING TRANSFER OF REACTOR COOLANT TO THE RMT

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-12- C	50,55E RPT	F		0	0130	50,55E-DIESEL GEN CONTROL CABINET WIRING=LACK OF REQ SEP BY COOPER ENERGY SERVICES (DER 81-51)
	81-12- D	50,55E RPT	F		0	0130	50,55E-LOOSE ANTI-ROTATION PINS IN CONTAINMENT SPRAY AND LPBI PUMPS (DER 81-52)
	81-12- E	50,55E RPT	F		0	0130	50,55E-MAIN CONTROL PANEL WIRING=LACK OF REQ SEP BY COMBIP CUSTOM LINE (DER 81-53)
	83-04-06	50,55E RPT	0		0	0505	50,55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	84-01-C	50,55E RPT	C		0		50,55(E): CONTROL OF RETESTING ACTIVITIES DETERMINED NOT TO BE REPORTABLE
	84-02-C	50,55E RPT	C		0		50,55(E): EXCESSIVE RUST 81 AND CH VALVES (ALL UNITS) FINAL RPT EXPECTED 6/21/84
	84-03-C	50,55E RPT	C		0		50,55(E): FEEDWATER ISOLATION VALVE STUCK DURING TESTING = FINAL RPT EXPECTED 5/31/84
	84-06-C	50,55E RPT	C		0		50,55(E): FOXBORO ALARM MODULE DEFECTS (ALL UNITS) = FINAL RPT EXPECTED 6/12/84
	84-08-C	50,55E RPT	C		0		50,55(E): BARTON MDL 763 TRNSMTR8 DO NOT MEET SPECS (ALL UNITS) FINAL RPT EXPECTED 5/18/84
	84-10-C	50,55E RPT	C		0		50,55(E): FAILURE OF SINGLE ELEMENT RTD'S (ALL UNITS) FINAL REPORT EXPECTED 6/1/84
	84-11-C	50,55E RPT	C		0		50,55(E): PUMP INSTRUMENTATION CONDUIT CONTAMINATED WITH CHLORIDES FINAL RPT EXPECTED 5/29/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	84-12-C	50,55E RPT	C		0		50,55(E): ZONE III VIOLATIONS OF RCP IA AND SG #1 FINAL RPT EXPECTED 6/1/84
	84-13-C	50,55E RPT	C		0		50,55(E): HVAC ACCEPTANCE CRITERIA (ALL UNITS) - FINAL RPT EXPECTED 12/14/84
	84-15-C	50,55E RPT	C		0		50,55(E): UNDERIZED PIPE RESTRAINT SUPPORT WELDS (ALL UNITS)-FINAL RPT EXP 8/3/84
	84-16-C	50,55E RPT	C		0		50,55(E): UNDERIZED EOPAS RELAY CABINET BASEPLATS (ALL UNITS) FINAL RPT EXPECTED 6/29/84
	84-18-C	50,55E RPT	C		0		50,55(E): WIRING ERROR ON LPS: B PUMP SWITCH-FINAL RPT EXPECTED 6/12/84
	84-19-C	50,55E RPT	C		0		50,55(E): BLIND FLANGES IMPROPERLY INSTALLED (ALL UNITS)
	84-20-C	50,55E RPT	C		0		50,55(E): CONNECTING LINE TO 818 380 DAMAGED
	84-21-C	50,55E RPT	C		0		50,55(E): ROSEMONT TRANSMITTERS LOOSE NUTS
	84-22-C	50,55E RPT	C		0		50,55(E): CEA SHROUD CONTAMINATED WITH OIL
	84-23-C	50,55E RPT	C		0		50,55(E): APW VALVE LOOSE SLEEVE PIN
	84-24-C	50,55E RPT	C		0		50,55(E): ALL UNITS - LOOSE BOLTS ON LIMITORQUE OPERATORS (ALL UNITS)



REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	84-25-C	50,55E RPT	C		0		50,55(E): ALL UNITS - CONTAINMENT AIR SUPPLY REGISTERS BY TITUS HAVE FAILED WIRE
	84-26-C	50,55E RPT	C		0		50,55(E): CIRCUIT BRKR INTERLOCK MECHANISM WAS IMPROPERLY ASSEMBLED
	84-27-C	50,55E RPT	C		0		50,55(E): HVAC INSTRUMENTATION WERE MODIFIED AFTER FINAL ACCEPTANCE BY APS MAINTENANCE
	84-28-C	50,55E RPT	C		0		50,55(E): DIESEL FUEL LINES TOUCHING PENETRATION SLEEVE
	84-29-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR HEAT EXCHANGERS HAVE SUBSTANCE BUILDUP
	84-30-C	50,55E RPT	C		0		50,55(E): DIESEL GENERATOR COOLERS HAVE PARTS THAT DONT MEET ASME REQUIREMENTS
	84-31-C	50,55E RPT	C		0		50,55(E): UNSEALED PENETRATIONS IN H888 BUILDING
	84-33-C	50,55E RPT	C		0		50,55(E): UNIT 1 MISSING WELD ON PIPE SUPPORT 1810Y0H011
	84-34-C	50,55E RPT	C		0		50,55(E): BIT BOLTING UNDERTORQUED/ WASHERS TOO SMALL
	84-35-C	50,55E RPT	C		0		50,55(E): POTENTIOMETERS ON PPS ARE DRIFTING-THIS AFFECTS SAFETY ANALYSIS
	84-36-C	50,55E RPT	C		0		50,55(E): TWO INCH WP81 VALVE STALL JUST OFF CLOSED POSITION-GUIDE HAS CHATTER - RELATED TO DER 83-63

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
5052R	84-37-C	50,55E RPT	C		0		50,55(E) UNAUTHORIZED/UNQUALIFIED DUCT SEALANT USED ON HVAC DUCT-NOTE THIS WAS FOUND BY NRC IN 84-10
	84-39-C	50,55E RPT	C		0		50,55E LPSI PUMP HAS RUMBLING NOISES
	84-40-C	50,55E RPT	C		0		50,55E APF PUMP IMPELLORS HAVE MIC-DISCOVERED IN US-APPLICABLE TO ALL UNITS
	84-41-C	50,55E RPT	C		0		50,55(E) REG IV INSPECTION CARDINAL INDUSTRY PRODUCTS HAD INDETERMINATE QUALITY
	84-42-C	50,55E RPT	C		0		50,55E MOTOR OPERATOR TORQUE SWITCHES IMPROPERLY REPLACED NOT QUALIFIED
	84-43-C	50,55E RPT	C		0		50,55(E) 3 INCH BORG WARNER VALVE BIV MV 609 FAILED TO OPEN
	84-44-C	50,55E RPT	C		0		50,55E PART 21 REPORT ISSUED ON GAULIN CHARGING PUMP BLOCKS FATIGUE FAILURE
	84-45-C	50,55E RPT	C		0		50,55E KAMAN RADIATION MEASURING INSTRUMENTS ARE IMPROPERLY INSTALLE
	84-46-C	50,55E RPT	C		0		50,55E NOZZLE LOADS FROM 20 INCH PIPES IN REFUELING WATER TANK NOT PREVIOUSLY EVALUATED
	84-48-C	50,55E RPT	C		0		50,55E GAULING IN MBIV PLUGS DURING INSTALLATION CAUSE OPERATING LEVERS TO VIBRATE LOOSE
	84-49-C	50,55E RPT	C		0		50,55(E) APF VIBRATES IN MINICIRC ALSO -REFER TO DER 84-23 FOR SIMILA PROBLE IN FULL FLOW RECIRC

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALC VERDE 1

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-50-C	50,55E RPT	C		0		50,55E1 TURBINE DRIVEN AUX FEED PUM FAILED TO QUICK START FROM AMBIENT CONDITIONS
	84-51-C	50,55E RPT	C		0		50,55E2 MBIV MADE BY ANCHOR-DARLING FAILED TO CLOSE IN FIVE SECONDS.
	84-52-C	50,55E RPT	C		0		50,55(E)1BASE FLANGE RESISTOR ON ATMOSPHERIC STEAM DUMPS NOT STRONG ENOUGH TO SURVIVE A SEISMIC EVENT
	84-54-C	50,55E RPT	C		0		50,55(E)1BUMP ISOLATION VALVE COULD NOT BE ELECTRICALLY OPENED AFTER BEING MANUALLY CLOSED
	84-55-C	50,55E RPT	C		0		50,55(E)1UNQUALIFIED FOXBORD MODULES HAVE BEEN INSTALLED IN CLASS 1E ELECTRICAL CABINETS
	84-56-C	50,55E RPT	C		0		50,55(E)1HALON & CO2 SYS FIRE DAMPERS DO NOT FULLY CLOSE UNDER NORMAL OPERATING FLOW
	84-57-C	50,55E RPT	C		0		50,55(E)1CONTAINMENT ISOLATION VALVE IN RAD. WASTE DRAIN FAILED TO CLOSE IN 10 SECONDS.
	84-61-C	50,55E RPT	C		0		50,55(E)1POSSIBLE AUXILIARY PRESSURIZER SPRAY FAILURE-IE LOOP CHARGING VALVE STICKS OPEN
	84-62-C	50,55E RPT	C		0		50,55(E)1SAFEGRD SEQUENCING PRBLMS WITH SIGNALS TO THE MPBI AND 480 VOLT LOAD CTR BREAKERS
	84-63-C	50,55E RPT	C		0		50,55(E)1TARGET ROCK VALVE FAILED TO CLOSE ON SIT WHEN PRESSURE DROPPED TO 200 PSIG DURING A TEST
	84-64-C	50,55E RPT	C		0		50,55(E)1PIPE SUPPORT SNUBBERS FOUND LOCKED UP AFTER HOT PUMP TEST

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-65-C	50,55E RPT	C		0		50,55E INSTRUMENT LEAD OUTER CABING LOCATED ON UPPER GUIDE STRUCTURE SPLIT EXPOSING CERAMIC INSULATOR
	84-66-C	50,55E RPT	C		0		50,55(E) DOWNCOMER FEEDWATER ISO VALVE FAILED TO COMPLETELY CLOSE UNDER DYNAMIC TEST CONDITIONS
	84-67-C	50,55E RPT	C		3		50,55(E) RED POSITION SWITCH FAILED TO CHANGE STATE W/THE VALVE CHANGE STATE USING REDUCED VOLTAGE
	84-68-C	50,55E RPT	C		0		50,55(E) ESSENTIAL CHILLER 'A' TEMP SWITCH TRIPS OFF AFTER BIAS FOL BY LOSS OF POWER-BLOCKING RESTART
	84-69-C	50,55E RPT	C		0		50,55(E) IRPS CHANNEL C, RELAY K-3 FAILED TO CLOSE DURING SAFEGUARDS TESTING



10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 2

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IB-79-18	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REVI 1/SUPI 2
	IB-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 8, 1980
	IB-80-12	IE BULLETIN	C	8111	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SHUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-02	IE BULLETIN	C	8234	0		PORV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IB-82-02	IE BULLETIN	C	8420	0		DEGREATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-82-04	IE BULLETIN	C		0		DEFICIENCIES ON PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IB-83-01	IE BULLETIN	0	8420	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
59529	18-83-03	IE BULLETIN	C	8420	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEM OF AG
	18-83-04	IE BULLETIN	C	8420	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	18-83-06	IE BULLETIN	C		0		NC MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLD CITY HOUSTON
	18-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDLENT PRODUCTS SOLD BY RAY MILLER, INC
	18-83-08	IE BULLETIN	C		0		C/B'S WITH UV TRIP IN SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	18-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MPA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

10/02/84

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 2

PAGE 3

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8420	0		
	IC-80-14	IE CIRCULAR	C	8311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	8420	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	8420	0		STEAM VOIDING IN RCS DURING COOLDOWN



REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

DOCKET ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
-----------------	------	--------------------	------------------------	--------	-------------	----------------------

59529	IE CIRCULAR	C	6311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
-------	-------------	---	------	---	--	---

	IE CIRCULAR	C	6420	0		
--	-------------	---	------	---	--	--



DO-KEY	ITEM#NUM	TYPE	FOLLOWUP	BRANCH	REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-04-01	INSP RPT (ENF)	C			0		CABLE BEND RADIUS WRONG
	84-08-02	INSP RPT (ENF)	C			0		IMPROPER HVAC BOLTING WELDING SHIMMING
	84-10-03	INSP RPT (ENF)	R			0	0884	NONCOMPLIANCE-IMPROPER DRAWING CONTROL IN CONTROL ROOM

```

.....
DOCKET ITEM NUM      TYPE      FOLLOWUP FOLLOWUP STATUS ACTION DATE  DESCRIPTIVE
.....
                                BRANCH  REPORT NO.
                                TITLE
.....

```

```

.....

```

```

.....
59529 84-04-02 INSP RPT (FOLLOWUP) C 0 FACTORY EL RADIUS FOR CABLE
.....

```

```

84-06-01 INSP RPT (FOLLOWUP) C 0 HVAC CRAFT TRAINING REQUIRED?
.....

```

```

84-10-01 INSP RPT (FOLLOWUP) M 0 CONTROL OF ACCESS TO SPENT
FUEL TUBE BELLOW
.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

```

.....

```

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

DOCKET ITEM NUM	TYPE	FOLLOWUP	FOLLOWUP	STATUS	ACTION DATE	DESCRIPTIVE TITLE
		BRANCH	REPORT NO.			
5029	IN-92-05	INFO NOTICE	3	0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	3	0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	3	0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S & O)
	IN-83-28	INFO NOTICE	3	0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	3	0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	3	0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-34	INFO NOTICE	M	0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M	0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M	0		CLARIFICATION OF SCOPE OF GA PROGRAMS P/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90929	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN=LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-13-01	TEMP INSTR (TI)	0		0		TRANSFER OF SRP REVIEW FROM NRR TO IE
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RGTS MP & EMERGENCY PLANNING-REV, 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RGTS FOR SYSTEM RGTS
	TI-15-54	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES=DUE EARLY 82

```

.....
DOCKET ITEM#NUM TYPE FOLLOWUP FOLLOWUP STATUS ACTION DATE DESCRIPTIVE
.....
BRANCH REPORT NO. TITLE
.....

```

```

.....
50580 TI-15-59 TEMP INSTR (TI) C 0 0737 INSPECTION LISTING FOR
.....
MODS DUE 1/82

```

```

.....
TI-15-64 TEMP INSTR (TI) C 0 0737 INSPECTION LISTING FOR
.....
MODS DUE 7/82

```

```

.....
TI-15-64 TEMP INSTR (TI) 0 0 INSPECTION FOLLOWUP BASED ON SALEM
.....
ATMS EVENTS

```

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

DOCKET ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	84-08-03 INSP RPT (UNR)	C		0		DUCT SEALANT ON GASKETED JOINT
	84-12-11 INSP RPT (UNR)	C		0		UGS REMORK PROCEDURE CONTAINS DIMENSION INCONSISTENT WITH DRGGS SEE 50-528/84-20-01
	84-15-01 INSP RPT (UNR)	C		0		



REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	83-01-28	50,55E RPT	0	0	0	0228	50,55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50,55E RPT	0	0	0	0505	50,55E-AP8 STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50,55E RPT	0	0	0	0505	50,55E-LP81 PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50,55E RPT	C	0	0		50,55(E): BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84
	84-09-C	50,55E RPT	C	0	0		50,55(E): CAD WELDING FOR CATHODIC PROTECTION SYSTEM NOT DOCUMENTED FINAL RPT EXPECTED 5/4/84
	84-38-C	50,55E RPT	C	0	0		50,55E: PIPE SUPPORT INSTALLED INCORRECTLY
	84-53-C	50,55E RPT	C	0	0		50,55(E): MISSING NUTS & LOOSE BOLTS FOUND ON VALVES LOC IN CONTAINMENT & CHARGING SYSTEM
	84-59-C	50,55E RPT	C	0	0		50,55(E): CABLES ARE IN CONTACT WITH SHARP METAL EDGES OF FIRE STOPS ABOVE THE MCC.
	84-60-C	50,55E RPT	C	0	0		50,55(E): INCOMPATABLE LUBRICANTS WERE USED ON 50 LIMITORQUE VALVES



REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IB-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV: 1/BUPI 2
	IB-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IB-80-06	IE BULLETIN	C		0		ESP RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IB-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IB-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IB-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SHUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	IB-81-02	IE BULLETIN	C	8234	0		PORV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	8305	0		
	IB-82-02	IE BULLETIN	C	8413	0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IB-82-04	IE BULLETIN	C		0		DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IB-83-01	IE BULLETIN	0	8413	0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IB-83-03	IE BULLETIN	C	8413	0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEMS OF DG
	IB-83-04	IE BULLETIN	C	8413	0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	IB-83-06	IE BULLETIN	C		0		HC MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLD CITY HOUSTON
	IB-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDLENT PRODUCTS SOLD BY RAY MILLER, INC
	IB-83-08	IE BULLETIN	C		0		C/B'S WITH UV TRIP ON SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	IB-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE HFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-79-21	IE CIRCULAR	C	8231	0		
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-09	IE CIRCULAR	0	8308	0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
		IE CIRCULAR	C	8413	0		
	IC-80-14	IE CIRCULAR	C	8311	0		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-81-02	IE CIRCULAR	0		0		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	0	8413	0		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	0		0		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-10	IE CIRCULAR	0	8413	0		STEAM VOIDING IN RCS DURING COOLDOWN

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-81-12	IE CIRCULAR	0		0		INADEQUATE PERIODIC BREAKER TEST PROCEDURES
	IC-81-14	IE CIRCULAR	C	8311	0		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
		IE CIRCULAR	C	8413	0		
	83-15-01	IE CIRCULAR	C	8337	0		EXCESSIVE TENSION ON TENDONS

10/02/84

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	84-03-01	INSP RPT (ENF)	C		0		STORAGE OF 480 V. MCC IN LEVEL D STORAGE
	84-07-14	INSP RPT (ENF)	C		0		REGEN HEAT EXCHANGER UPPER SUPPORT JAM NUT ADJUSTMENT & TORQUE
	84-07-17	INSP RPT (ENF)	C		0		CABLE REELS NOT TAGGED NONCONFORMING
	84-12-05	INSP RPT (ENF)	C	8425	0		IMPROPER ACCEPTANCE OF HONEYWELL INSTRUMENTS





REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-82-05	INFO NOTICE	S		0		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		0		SCREENING OF ONSITE PERSONNEL
	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR M/B & O)
	IN-83-28	INFO NOTICE	S		0		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS
	IN-84-40	INFO NOTICE	M		0		EMERGENCY WORKER DOSES-VERIFY RECEIPT, PROPER DISTRIBUTION AND UNDERSTANDING
	IN-84-50	INFO NOTICE	M		0		CLARIFICATION OF SCOPE OF QA PROGRAMS F/TRANSPORT PACKAGES PURSUANT TO PT. 50, APPENDIX B

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50550	DB-03-10	OTHER	3	0		ADDITIONAL 3 HIRES FOUND CUT (COMPUTER RM) ON 03/30/83 (PND-V-88-18)

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
90530	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN=LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING=REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-54	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES=DUE EARLY 82
	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82



REGION 5  
OUTSTANDING ITEMS REPORT  
ALL OPEN ITEMS (SORTED BY TYPE)  
PALO VERDE 3

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50830	82-09-02 INSP RPT (UNR)	C		0		FLARE LEVEL WELD
	84-07-13 INSP RPT (UNR)	C		0		VALVE 3P81EV235 STUD THREAD ENGAGEMENT INTO BONNET
	84-09-01 INSP RPT (UNR)	C		0		SEE 50-520/84-20-01

REGION 5  
 OUTSTANDING ITEMS REPORT  
 ALL OPEN ITEMS (SORTED BY TYPE)  
 PALO VERDE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-01-28	50,55E RPT	0	0	0	0228	50,55E-HVAC TEST PROCED DD NOT MFCT ANBI N 510 DER 83-4
	83-04-06	50,55E RPT	0	0	0	0505	50,55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50,55E RPT	0	0	0	0505	50,55E-LPBI PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50,55E RPT	C	0	0		50,55(E) BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84