Commonwealth Edison Company Braidwood Generating Station Route #1, Box 84 Braceville, IL 60407-9619 Tel 815-458-2801

ComEd

A047 .

October 24, 1995 BW/95-0101

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: ComEd Braidwood Station Unit 2 Fourth Refuel Outage Steam Generator Inservice Inspection Report Docket No. STN 50-457

References: (1) NUREG-1276, Technical Specifications, Braidwood Station Unit Nos. 1 and 2


Gentlemen:

Specification 4.4.5.5.b of reference (1) requires that within 12 months following the completion of each inservice inspection of steam generator tubes the complete results of the inspection shall be submitted to the Commission in a Special Report pursuant to Specification 6.9.2. This report shall include the number and extent of tubes inspected, location and percent of wall-thickness penetration for each indication of an imperfection, and identification of tubes plugged or repaired. The Braidwood Unit 2 steam generator eddy current inspection was completed October 25, 1994.

During this inspection, 100% of the tubing in the 2B and 2C steam generators received a full length bobbin coil eddy current inspection. A 3-coil Rotating Pancake Coil (RPC) probe was used to confirm and characterize all distorted indications found through bobbin coil examination. In addition, a random sample of 10% of the tubes in the 2B and 2C steam generators was inspected at the roll transition region at the top of the tube sheet with the RPC probe to inspect for circumferential cracks. No circumferential cracks were identified.

The enclosure summarizes the inspection results. Included are indication lists and maps, a guide to abbreviations used in the indication list, and the qualification requirements of the certified personnel performing the eddy current examinations.

510270004 951024 DR ADDCK 05000457



A Unicom Company

U.S. Nuclear Regulatory Commission October 24, 1995 Page Two

Please direct any questions regarding this submittal to Doug Huston, Braidwood Licensing Supervisor, (815) 458-2801, extension 2511.

Yours truly,

T.J. Tulon

Station Manager Braidwood Nuclear Station

TJT/DH/dla o:\corresp\zcsteno\bwdletrs.doc

Attachments

- cc:
- S. Ray, Senior Resident Inspector Braidwood
- R. R. Assa, Braidwood Project Manager NRR
- H. Miller, Regional Administrator RIII