

## APPENDIX A

Diversified Threaded Products Company  
Docket No. 99900823/83-01

### NOTICE OF VIOLATION

As a result of the inspection conducted on June 13-17, 1983, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix B), 47 FR 9987 (March 9, 1982):

Section 21.6 of 10 CFR Part 21 dated December 30, 1982, states, in part, "(a) Each . . . corporation . . . subject to the regulations in this part, shall post current copies of the following documents . . . (1) the regulations in this part, (2) Section 206 of the Energy Reorganization Act of 1974, and (3) procedures pursuant to the regulations in this part."

Section 21.21 states, in part: "(a) Each . . . corporation . . . subject to the regulations in this part shall adopt appropriate procedures to: (1) provide for; (i) evaluating deviations; or (ii) informing the licensee or purchaser of the deviation in order that the licensee or purchaser may cause the deviation to be evaluated unless the deviation has been corrected . . . ."

Contrary to the above:

1. A copy of 10 CFR Part 21 that was posted was not the current copy dated December 30, 1982.
2. Procedures to evaluate deviations or inform the licensee or purchaser of the deviation did not exist.

This is a Severity Level V Violation (Supplement VII).