

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

19 AUG 05
July 17, 1984

BLRD-50-438/82-48
BLRD-50-439/82-43

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENT STEAM GENERATOR SUPPORT
BOLTS - BLRD-50-438/82-48, BLRD-50-439/82-43 - SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
R. V. Crlenjak on July 23, 1982 in accordance with 10 CFR 50.55(e) as NCR
1887. This was followed by our interim reports dated August 19 and
December 21, 1982 and March 29 and August 5, 1983 and our final report
dated December 21, 1983. Below is our supplemental report.

As discussed with NRC-OIE Inspector P. E. Fredrickson on July 3, 1984,
the date of July 9, 1984 for completion of corrective actions indicated
in our final report on this matter would not be met. Thirty-six bolts
still need to be pulled out and their shims need to be remachined. After
this is done, all bolts will be torqued. The corrective action on this
matter will be completed by August 29, 1984.

If you have any questions concerning this matter, please get in touch with
R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

LE 27 10