

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station	DOCKET NUMBER (2) 0 5 0 0 0 2 3 7	PAGE (3) 1 OF 0 2
--	--------------------------------------	----------------------

TITLE (4)
Surveillance Interval Exceeded for Pumping D/W Equipment Drain and Floor Drain Pumps

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 6	2 7	8 4	8 4	0 1 5	0 0	0 8	0 2	8 4	N/A		0 5 0 0 0
									N/A		0 5 0 0 0

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 0 1 1	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(a)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.38(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)						
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.38(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)								

LICENSEE CONTACT FOR THIS LER (12)									
NAME Gary L. Smith (X-610)							TELEPHONE NUMBER 8 1 6 9 4 2 - 2 9 2 0		

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS		
A											

SUPPLEMENTAL REPORT EXPECTED (14)								MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO										
								EXPECTED SUBMISSION DATE (15)		

ABSTRACT (Limit to 1400 spaces, i.e., sporadically fifteen single-space typewritten lines) (16)

During startup operation, the 2000 time pumpdown of the drywell equipment and floor drain sumps was not performed until 2210. The previous pumpdown had been at 1600 therefore exceeding the required surveillance interval per T.S. 4.6.D.1. As soon as the error was realized the sumps were pumped down. Calculated leakage rates were within specified limits and indicated on appreciable increase in leakage, therefore making this event of minimal safety significance. Last previous occurrence was reported by DVR 12-2-84-34.

Originally, this event was misclassified as non-reportable due to Station personnel not understanding the new 10 CFR 50.73 rules.

8408090052 840802
PDR ADOCK 05000237
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Dresden Nuclear Power Station Unit 2	DOCKET NUMBER (2) 205000237	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		84	015	00	02	OF 02

TEXT (If more space is required, use additional NRC Form 388A's) (17)

According to T.S. 4.6.D.1, the pumping down of the drywell equipment drain and floor drain sumps must be performed every 4 hours. However, the surveillance interval was exceeded by more than 25 percent since it was 6 hours and 10 minutes between successive pumpings. The computer select time interval alarm that normally sounds on four hour intervals to remind the Operator to pump the sumps, had been inadvertently acknowledged simultaneously with other alarms alarming from other surveillance testing being done during the startup. Once the error was realized, the sumps were pumped and the calculated leakage was within specified limits. To prevent recurrence, the shift operation personnel will be briefed as to the importance of complying with station procedures and proper alarm acknowledgement.

This event was originally classified as non-reportable, but due to station personnel not being completely familiar with the new 10 CFR 50.73 rules it should be reclassified as reportable due to 10 CFR 50.73 (a)(2)(i)(B).

Review of the circumstance which led to the misclassification indicates that station personnel were not completely familiar with recent changes to 10 CFR 50.73. All personnel directly involved in determining reportability were given additional training on this subject during the month of July. This training should prevent recurrence of misclassification in the future.



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

August 2, 1984

DJS Ltr #84-757

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report #84-015-0, Docket #050237 is being submitted
as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73
(a)(2)(i)(B).

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IE22
1/1