UNITED STATES



NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064

NOV 20 1995

Omaha Public Power District
ATTN: T. L. Patterson, Division Manager
Nuclear Operations
Fort Calhoun Station FC-2-4 Adm.
P.O. Box 399, Hwy. 75 - North of Fort Calhoun
Fort Calhoun, Nebraska 68023-0399

SUBJECT: NRC INSPECTION REPORT 50-285/95-12

Thank you for your letter of October 11, 1995, in response to our letter and Notice of Violation dated September 11, 1995. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

J. E. Dyer Director

Division of Reactor Projects

Docket: 50-285 License: DPR-40

CC:

Winston & Strawn ATTN: Mr. James R. Curtiss 1400 L. Street, N.W. Washington, D.C. 20005-3502

Washington County Board of Supervisors ATTN: Jack Jensen, Chairman Blair, Nebraska 68008 Nebraska Department of Health ATTN: Cheryl Rcgers, LLRW Program Manager Environmental Protection Section 301 Centennial Mall, South P.O. Box 95007 Lincoln, Nebraska 68509-5007

Nebraska Department of Health ATTN: Dr. Mark B. Horton, M.S.P.H. Director P.O. Box 950070 Lincoln, Nebraska 68509-5007

Fort Calhoun Station ATTN: James W. Chase, Manager P.O. Box 399 Fort Calhoun, Nebraska 68023 E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan

DRSS-FIPB

Branch Chief (DRP/A)

RIV File

Resident Inspector

MIS System

Project Engineer (DRP/A)

Branch Chief (DRP/TSS)

Senior Resident Inspector - Cooper Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ FCS\FC512AK.WCW

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV: DRP/A RAN	AC:DRP/A N	D:DRP out
RAKopriva; df	JLPellet 00 11/ 9/95	JEDyer
11/8/95	11/9/95	11/16/950

OFFICIAL RECORD COPY

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV: L. J. Callan

DRSS-FIPB

Branch Chief (DRP/A)

RIV File

Resident Inspector

MIS System

Project Engineer (DRP/A)

Branch Chief (DRP/TSS)

Senior Resident Inspector - Cooper Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ FCS\FC512AK.WCW

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy


RIV: DRP/A RAN	AC:DRP/A N	D:DRP at	
RAKopriva;df		JEDyer	
11/8/95	11/9/95	11/14/95	

OFFICIAL RECORD COPY

Omaha Public Power District

October 11, 1995 LIC-95-0183 444 South 16th Street Mall Omaha, Nebraska 68102-2247 402/636-2000

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Station P1-137 Washington, DC 20555



References: 1.

. Docket No. 50-285

2. Letter from NRC (J. E. Dyer) to OPPD (T. L. Patterson) dated

September 11, 1995

SUBJECT:

NRC Inspection Report No. 50-285/95-12, Reply to a Notice of

Violation

The subject report transmitted a Notice of Violation (NOV) resulting from an NRC inspection conducted July 2 through August 12, 1995 at the Fort Calhoun Station. Attached is the Omaha Public Power District (OPPD) response to this NOV.

Your comment in the NOV stated "It [the NOV] was also of concern because maintenance personnel failed to take prompt corrective action when the deficiency was initially brought to their attention." It is the Fort Calhoun Station (FCS) management expectation that prompt corrective action is taken anytime a deficiency is identified. This includes concerns identified by station staff members as well as those identified by NRC Inspectors.

If you should have any questions, please contact me.

Sincerely.

T. L. Patterson For

Division Manager

Nuclear Operations Division

TLP/grc

Attachment

c: Winston and Strawn

L. J. Callan, NRC Regional Administrator, Region IV

S. D. Bloom, NRC Project Manager

W. C. Walker, NRC Senior Resident Inspector

96-0086

REPLY TO A NOTICE OF VIOLATION

Omaha Public Power District Fort Calhoun Station Docket: 50-285 License: DPR-40

During an NRC inspection conducted on July 2 through August 12, 1995, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (60 FR 34381; June 30, 1995), the violation is listed below:

Technical Specification (TS) 5.8.1 states, in part, that written procedures and administrative policies shall be established, implemented, and maintained that meet or exceed the minimum requirements of Regulatory Guide 1.33.

Regulatory Guide 1.33, Appendix A, Section 9.a, states, in part, that maintenance that can affect the performance of safety-related equipment shall be performed in accordance with written procedures or documented instructions appropriate to the circumstances.

Construction Work Order 95-175, Step 2.7, states, in part, that all open piping systems are to be covered during periods of inactivity to preclude the introduction of foreign materials into the system.

Standing Order SO-M-103, "System Cleanliness," Revision 2, Section 7.2.2, states, in part, that system openings shall be covered when work activity is not actively in progress in the vicinity of the opening.

Contrary to the above, the inspectors observed that maintenance personnel did not cover the open piping of a control room air conditioner during a period of inactivity.

This is a Severity Level IV Violation (285/9512-01) (Supplement I).

OPPD Response

A. The Reason for the Violation

This violation occurred during the installation of new piping components in the oil bypass line from the freon compressor for VA-46B. This

installation was included under Modification Request MR-FC-94-020, "VA-46A/B Improved Reliability". The portion of the system involved in this violation is designated as safety related.

The individuals associated with this action had received formal training on Standing Order (SO) SO-M-103 under "Conduct of Maintenance" training sessions. In this training, the contractor steam fitter mechanics were provided instruction on cleanliness requirements identified in SO-M-103. Additionally, the system cleanliness requirements were noted in a specific installation step in the Construction Work Order (CWO), 95-0175, which had been prepared for this job.

The OPPD Manager responsible for the contractor personnel involved in the modification and the supervisor of the contract steam fitter mechanics completed an evaluation of this event. The evaluation results concluded that this event resulted from a lack of attention-to-detail by OPPD Construction Management personnel and the contractor steam fitter mechanics. In Section 7.2.2, SO-M-103 states, "System openings shall be covered when work is not actively in progress in the vicinity of the opening." This violation occurred when the contractor steam fitter mechanics left the work area to secure additional components.

A contributing cause of this event was that SO-M-103 did not clearly delineate when it was acceptable to leave the system open. The procedure did not state what would constitute when work is "... not actively in progress in the vicinity of the opening." As a result, the procedural requirement was perceived to be ambiguous and subject to misinterpretation.

B. Corrective Steps Which Have Been Taken and the Results Achieved

- 1. Contractor steam fitter mechanics were presented a training session on July 19, 1995. This training session was provided to ensure that the contractor steam fitter mechanics clearly understood OPPD management expectations concerning SO-M-103. The contractors were briefed on the following:
 - Procedural compliance. The training reiterated that when other procedures are referenced, even if not specifically noted on a particular step within the procedure, they still apply (i. e. SO-M-103).
 - OPPD management expectations related to the covering of open

systems during periods of inactivity. The term when work is " . . . not actively in progress in the vicinity of the opening" was specifically defined to indicate that whenever the work area is left unattended, the system must be covered.

- 2. An additional training session was completed for Nuclear Construction Management Department Field/Testing Engineers, contractor steam fitter mechanics supervision and contractor steam fitter mechanics on October 6, 1995. This training highlighted the following:
 - Affirmation of OPPD Management expectations regarding selfchecking and attention-to-detail when performing work.
 - Review of the proposed revision to SO-M-103.
- Standing Order SO-M-103, Step 7.2.2, was revised to clearly describe conditions that are unacceptable for leaving the system open. This procedure change was approved on October 10, 1995.

C. Corrective Steps Which Will be Taken to Avoid Further Violations

- 1. A brief synopsis of this event, lessons learned and management expectations of site personnel will be distributed to FCS personnel (except for administrative personnel) via a supervisory briefing Training "Hotline." The Hotline will discuss management expectations concerning cleanliness requirements detailed in SO-M-103. In addition, the importance of responsiveness to identified concerns, attention-to-detail, verbatim compliance to procedures and quality workmanship will be outlined. This Hotline will be issued by October 27, 1995.
- This event will be added to the Industry Events portion of the Conduct of Maintenance Training. This training will presented to Nuclear Construction Management (CM) craft and supervision, Fort Calhoun Station (FCS) maintenance personnel, OPPD (non-FCS) maintenance personnel and non-FCS utility maintenance personnel (craft and supervision). This training will be added to the Conduct of Maintenance Lesson Plan by May 31, 1996.

D. Date When Full Compliance Will Be Achieved

OPPD is currently in full compliance.