We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original Signed by Brent Clayton"

Brent Clayton, Chief Reactor Projects Branch 1

Enclosures: Inspection Report Nos. 50-454/92006(DRP); 50-455/92006(DRP)

Distribution

cc w/enclosures:

M. Wallace, Vice President, PWR Operations

T. Kovach, Nuclear Licensing Manager

T. Schuster, Nuclear Licensing Administrator

R. Pleniewicz, Station Manager

D. Brindle, Regulatory Assurance Supervisor

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspectors, Byron, Braidwood, Zion

R. Hubbard

J. W. McCaffrey, Chief, Public Utilities Division

D. Chavez, DAARE/SAFE

Licensing Project Manager, NRR

R. Newmann, Office of Public

Counsel, State of Illinois Center

R. M. Thompson, Administrator, Wisconsin Division of Emergency Government

State Liaison Officer

Landsman



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD

GLEN ELLYN ILLINOIS 60137

MAR 3 0 1992

Docket No. 50-454 Docket No. 50-455

License No. NPF-37 License No. NPF-66

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Opus West III 1400 Opus Place Downers Grove, IL 60515

Dear Mr. Reed:

This refers to the routine safety inspection conducted by Messrs. W. J. Kropp, C. H. Brown and D. E. Jones of this office from February 19, 1992 through March 23, 1992. The inspection included a review of activities at your Byron Station, Units 1 and 2. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

Two Unresolved Items were identified in Paragraphs 4.b.2 and 4.b.3 that pertained to the replacement of a pressure transmitter and inservice testing of check valves. To facilitate a timely resolution of these issues, a 60 day response time was agreed to by the Byron Staff. If your understanding is different than ours, please contact this office immediately.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

The responses directed by this letter are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 36-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Brent Clayton, Chief Reactor Projects Branch I

Enclosures:

Inspection Report Nos. 50-454/92006(DRP); 50-455/92006(DRP)

Distribution

cc w/enclosures:

M. Wallace, Vice President, PWR Operations

T. Kovach, Nuclear Licensing Manager

T. Schuster, Nuclear Licensing Administrator

R. Pleniewicz, Station Manager D. Brindle, Regulatory Assurance

Supervisor DCD/DCB (RIDS)

OC/LFDCB

Resident Inspectors, Byron, Braidwood, Zion

R. Hubbard

J. W. McCaffrey, Chief, Public Utilities Division

D. Chavez, DAARE/SAFE

Licensing Project Manager, NRR

R. Newmann, Office of Public Counsel, State of Illinois Center

R. M. Thompson, Administrator, Wisconsin Division of Emergency Government

State Liaison Officer