

Scw Public Meeting 2-9-84

# 68-71

Pete - <sup>general</sup> lifting of stop work Jan 19<sup>th</sup>

Joe Springer - cracks

685 cracks due to Shrink<sup>age</sup> Moments

\* How come other <sup>similar</sup> slabs aren't cracking similarly

704  
674

Wayne - jacking criteria on w8

JIM BOB - crack monitoring

1) crack mapping program - historical

SSEER ~~is~~ only documentation

X its not only - CPCO  
submittals state:

" cracks will be mapped  
no indication that only  
critical areas"

new criteria  
5 mils

for  
audit

X in slabs 5 mils <sup>at least</sup> of 24 inches { if larger than 5 mils  
& less than 24 will not  
be mapped }

2) EL. 685 slab - found Jan 5, 1984

\* no effect on slab structurally - static

- 1 (what about seismic margin rebar study)  
vertical movement
- 2 (why is post tensioning up there)

3) crack survey - 10 mils

CIO

Paul - general

Public

Barb - Board notification on cracks

Billie - 5 questions  
- crack monitoring program changes