Commonwealth Edison Company Braidwood Generating Station Route #1, Box 84 Braceville, IL 60407-9619 Tel 815-458-2801

November 27, 1995 BW/95-0115



U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject:

ComEd Braidwood Station Unit 1 Fifth Refuel Outage

Steam Generator Inservice Inspection Report

Docket No. STN 50-456

References:

 Letter BW/95-0110 from ComEd's Braidwood Station to U.S. Nuclear Regulatory Commission, Category C-3 Report per Specification 4.4.5.5.c dated November 13, 1995

Gentlemen:

In the "Corrective Measures to Prevent Recurrence" section of the referenced letter, ComEd indicated it will not continue the Secondary Side Boric Acid program for Braidwood Unit 1 Cycle 6. Since this time, ComEd has reversed this decision. Braidwood Unit 1 will continue the Secondary Side Boric Acid program at least until its mid-cycle outage. This program will include boric acid soaks during unit startup along with on-line addition during normal power operation. ComEd's evaluation of the Secondary Side Boric Acid program during Unit 1 Cycle 5 determined that the program is not detrimental to the Steam Generator tubes.

Please direct any questions regarding this decision to Doug Huston, Braidwood Licensing Supervisor, (815) 458-2801, extension 2511.

Very truly yours,

V. J. Tulon Station Manager

Braidwood Nuclear Station

TJT/DG/dla

o:\corresp\zcsteno\bwdletrs.doc

oc: Sr. Resident Inspector - Braidwood

01011 3 Braidwood Project Manager, NRR
Regional Administrator, Region III

9512010256 951127 PDR ADOCK 05000456 PDR A047