U.S. NUCLEAR REGULATORY COMMISSION REGION IV

NRC Inspection Report Nos. 50-313/92-06 50-368/92-06

Operating Licenses Nos. DPR-51 NPF-6

Licensee: Entergy Operations, Inc.

Route 3, Box 1376

Russellville, Arkansas 72801

Facility Name: Arkansas Nuclear One, Units 1 and 2 (ANO)

Inspection At: ANO, Russellville, Arkansas

Inspection Conducted: February 18-21, 1992

Inspector: A. B. Earnest, Physical Security Specialist

Facility Inspection Program Section

Approved:

B. Murray, Chief, Fagility Inspection

Program Section

Inspection Summary

Inspection Conducted February 18-21, 1992 (Report No. 50-313/92-06; 50-368/92-06)

Areas Inspected: Routine, unannounced inspection of the licensee's physical security program including: access control-personnel, training and qualifications, audits, and testing and maintenance.

Results: Within the program areas inspected, two violations were identified. The two violations were licensee identified and classified as noncited violations (see paragraphs 3.1 and 3.2). No deviations were identified. One unresolved item is identified in paragraph 3.1.

Significant inspection findings were:

- An unresolved item was identified involving:
 - Metal detectors at the access points that were not capable of adequately detecting the test device under certain conditions, and

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION UPON SEPARATION THIS PAGE IS DECONTROLLED

9204100039 920406 PDR ADDCK 05000313 Q PDR

- (2) x-ray machines which did not detect the test device under certain conditions (see paragraph 3.1).
- Ten employees were given unescorted access without successfully completing the site training requirements. This was classified as a noncited violation (see paragraph 3.1).
- Security officers were not tested to determine that they were free of glaucoma. This was classified as a noncited violation (see paragraph 3.2).
- An excellent training program had been established for security officers.
- A new firing range complex was near completion.
- An excellent equipment maintenance program existed; however, an unresolved item was identified involving the testing program for the x-ray and metal detection equipment.
- An excellent audit program had been established.
- Management provided strong support for the security program.

DOCUMENT CONTAINS SAFEGUARDS INFORMATION ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Entergy O; rations, Inc.

bcc copy of entire report:

RIV Security File
Elaine Koup, RSGB/NRR (9D24)
R. D. Martin. RA
Resident Inspector
Security File
G. F. Sanborn, EO
M. Virgilo, NRR (13E4)

bcc copy of letter and inspection summary only:
DMB 1E-D4 DRP

DRS
Lisa Shea, RM/ALF (4503)
Section Chief, DRP/A
RIV File
MIS
RSTS Coordinator
Project Engineer, DRP/A