

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company
Turkey Point

Docket No. 50-251
License No. DPR-41

The following violation was identified during an inspection conducted on June 4 - 6, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires written procedures be implemented that meet the requirements of Regulatory Guide 1.33. Administrative Procedure 0103.3, Control and Use of Temporary System Alterations, meets the requirements of Regulatory Guide 1.33 and requires the proper documentation of temporary system alterations.

Contrary to the above, the licensee failed to implement Administrative Procedure 0103.3 for the temporary alteration of the circuitry to Temperature Indicator TI-4-465 in that a resistor was relocated without completing temporary change documentation as specified by Administrative Procedure 0103.3.

This is a Severity Level IV violation (Supplement I.D.).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUL 05 1984