

LICENSEE EVENT REPORT (LER)

Updated report. Date of previous report 6/26/84.

FACILITY NAME (1) Dresden Nuclear Power Station Unit 2						DOCKET NUMBER (2) 0 5 0 0 0 2 3 7			PAGE (3) 1 OF 0 2	
-----------------------------------------------------------	--	--	--	--	--	----------------------------------------------------	--	--	----------------------	--

TITLE (4)
East LPCI Corner Room Submarine Door Not Closed

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	2	0	8	8	4	0	1	0	N/A		0 5 0 0 0
0	2	0	8	8	4	0	1	0			0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)

OPERATING MODE (8) N	20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 110.10	20.406(a)(1)(i)	50.36(e)(1)	50.73(a)(2)(v)	73.71(e)
	20.406(a)(1)(ii)	50.36(e)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)	
	20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)	
	20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Mark Leahy	TELEPHONE NUMBER AREA CODE 8 1 5 9 4 2 - 2 9 2 0
--------------------	----------------------------------------------------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A				N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO X

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During normal operation, the east LPCI corner room submarine door to the torus basement was found open and unattended, in violation of the Technical Specifications. Safety significance was minimal since the operability of LPCI or Core Spray was not affected.

The door was probably left open by contractor personnel.

The door was immediately closed and secured, and signs were hung emphasizing the Technical Specification requirements.

This report is submitted as a result of an investigation which revealed that the event is reportable per 10 CFR 50.73 (a)(2)(i)(B). Originally the event was mistakenly classified as non-reportable.

Review of the circumstances which led to the misclassification indicate that station personnel involved were not completely familiar with the recent changes to 10 CFR 50.73. All personnel directly involved in determining reportability will receive additional training.

8408310067 840809
PDR ADOCK 05000237
S PDR

IEZZ
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Dresden Nuclear Power Station Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 2 3 7 8 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			0 0 6	0 1	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

During normal operation, the east LPCI corner room submarine door to the torus basement was found open and unattended. Safety significance was minimal since the operability of the LPCI and Core Spray was not affected. Previous similar occurrence was reported by R.O. 83-81 on Docket #050-237.

Probable cause of the event was a contractor who was in the area prior to that time. The Station Construction Department has reminded the contractors of the requirement to keep the bulkhead door closed at all times. Also, additional signs have been hung on both sides of these doors, including the Unit 2 and 3 CCSW vaults, which state this requirement. The door in question was immediately closed and secured.

This report is submitted as a result of an investigation which revealed that the event is reportable per 10 CFR 50.73 (a)(2)(i)(B). Originally the event was mistakenly classified as non-reportable.

Review of the circumstances which led to the misclassification indicate that station personnel involved were not completely familiar with the recent changes to 10 CFR 50.73. All personnel directly involved in determining reportability will receive additional training.

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D -	12 -	2 -	84 -	15

PART 1	TITLE OF EVENT	OCCURRED	
	East LPCI Corner Room Submarine Door Not Closed	<u>2/8/84</u>	<u>1605</u>
		DATE	TIME
	REASON FOR SUPPLEMENTAL REPORT		
	Correction to power level.		
PART 2			
	ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>John M. Allen</u>
	DATE	<u>8/13/84</u>	<u>8/22/84</u>
	SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>P.M. Pagan Jr</u>	<u>8/25/84</u>
		STATION SUPERINTENDENT	DATE



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

August 9, 1984

DJS Ltr #84-790

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Update to Licensee Event Report #84-006-1, Docket #050237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(i)(B). This update is submitted to correct the power level entry (10).

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

LE22
1/1