

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Joseph M. Farley - Unit 2

DOCKET NUMBER (2)
0 5 0 0 0 3 6 4

PAGE (3)
1 OF 0 2

TITLE (4)
Continuous Fire Watch Not Maintained As Required

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)			
0	8	01	84	84	-	0	0	7	-	0	0	082484		0 5 0 0 0
														0 5 0 0 0

OPERATING MODE (9) 1

POWER LEVEL (10) 1,0,0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

20.402(b)	20.406(c)	80.73(a)(2)(iv)	73.71(b)
20.406(a)(1)(i)	80.36(c)(1)	80.73(a)(2)(v)	73.71(c)
20.406(a)(1)(ii)	X 80.36(c)(2)	80.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.406(a)(1)(iii)	X 80.73(a)(2)(i)	80.73(a)(2)(vii)(A)	
20.406(a)(1)(iv)	80.73(a)(2)(ii)	80.73(a)(2)(vii)(B)	
20.406(a)(1)(v)	80.73(a)(2)(iii)	80.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: J. D. Woodard

TELEPHONE NUMBER: AREA CODE 205 899-5156

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 1830 on 8-1-84, it was determined that a continuous fire watch had not been maintained as required by Technical Specification 3.7.11.2. A fire watch was posted immediately and maintained until no longer required. Health/Safety of the public was not affected.

8409050183 840824
PDR ADDCK 05000364
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Joseph M. Farley - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 6 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 4	- 0 0 7	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

Fire protection sprinkler system 2A-25 was removed from service for surveillance testing at 0809 on 8-1-84. A continuous fire watch was posted in accordance with Technical Specification 3.7.11.2. However, at 1830 on 8-1-84 it was determined that the fire watch had not been maintained as required although maintenance personnel had been in the area intermittently (working on 2A-25). A continuous fire watch was posted immediately and maintained until no longer required. Investigation revealed that the fire watch had been maintained until approximately 1130 when it was mistakenly discontinued.

This event was due to personnel error. The Shift Foreman did not provide adequate fire watch instructions and did not ensure that the fire watch requirements were met. The individual has been counseled. The fire watch system has been reviewed and a system to provide more positive control over fire watches is being implemented. This incident will be discussed with operations group supervision responsible for establishing fire watches.

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6090

R. P. McDonald
Senior Vice President
Flintridge Building



Alabama Power
the southern electric system

August 24, 1984

Docket No. 364


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 2, Licensee Event Report No. LER 84-007-00 is forwarded in accordance with 10CFR50.73 to provide 30 day written notification of this occurrence.

If you have any questions, please advise.

Yours very truly,



R. P. McDonald

RPM/DSM:sam

Enclosure

xc: IE, Region II

IE22
11