

unsatisfactory rating requiring further review. Additionally, the evaluators and the operations department management also considered individual performance of some of the operators to be marginal and warranting remediation.

The scenario for which the crew and some of its members were rated unsatisfactory involved a loss of off-site electrical power while operating at 100 percent reactor power due to a plane crash in the switchyard. The scenario was further complicated by the loss of the remaining diesel generators and all AC electrical power, and seal failures on the "A" and "C" reactor coolant pumps. The crew did not manually initiate a safety injection based upon the loss of subcooling margin below 35 degrees F. The subcooling margin temperature criteria was part of an emergency operating procedure continuing information page which the crew failed to utilize. Additionally, a member of the crew did not recognize the failed reactor coolant pump seals. While the crew successfully mitigated the accident scenario and satisfied the evaluation critical tasks, the evaluators and operations management believed further training and remediation was warranted. This conclusion was reached after detailed review of the crew's performance by watching video tapes of the scenario and discussions with the operations management.

The inspectors observed, with minor exception, good communications exhibited by the crews during the dynamic simulator portion of the examination. Two of three crews passed the dynamic simulator portion of the examination.

1.3 Walkthrough Examinations

The inspectors observed the licensee evaluators and the requalification examinees during the conduct of system-oriented JPMs. This included nonlicensed equipment operator tasks outside the control room and the performance of some tasks in the simulator in the dynamic mode.

Communications between the examinees and the evaluators were observed to be good, as were the communications practiced by the observed on-shift operating crew. The inspectors noted that the evaluators thoroughly reviewed the results of the individual walkthroughs and that none of the examinees failed the JPM portion of the examination.

During the walkthrough, the inspectors observed plant cleanliness and housekeeping to be excellent. The inspectors noted that the licensee has made continual improvement in this area.

All requalification examinees passed the JPM portion of the operating examination.