

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

August 28, 1984

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 1  
Docket No. 50-369  
LER 369/84-05

Gentlemen:

My letter dated April 2, 1984 submitted License Event Report 369/84-05. On page 3 of that report it was incorrectly stated that "After the blackout signal was cleared, ND pump 1B was returned to service for core cooling". As indicated elsewhere in the report, the ND pump was actually returned to service within three minutes of the blackout signal which had caused it to stop due to Load Shedding (The blackout signal wasn't cleared until about 5 hours later). Therefore the affected paragraph should read "ND pump 1B was returned to service for core cooling. After the blackout signal was cleared, NV pump 1B and D/G 1B were returned to standby readiness". We regret any confusion or inconvenience this may have caused.

Very truly yours,

*Hal B. Tucker*  
Hal B. Tucker

PBN:glb

cc: Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

M&M Nuclear Consultants  
1221 Avenue of the Americas  
New York, New York 10020

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange, Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

8409110075 840828  
PDR ADOCK 05000369  
S PDR

IE-22  
1/0