

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

September 5, 1984

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket Number 50-370
LER 370-84-17

Gentlemen:

On August 6, 1984 a separation of a 2" pipe weld in the Residual Heat Removal/Chemical and Volume Control System Heat Exchanger occurred. This event has been determined to be reportable under the criteria of 10 CFR 50.73(a)(z)(vi), with the report due on September 5, 1984. However, due to the extensive investigation, analysis, and review of this event, License Event Report 370-84-17 is still being prepared. The LER will be submitted by October 5, 1984. If there are any questions, please call Scott Gewehr at (704) 373-7581.

Very truly yours,

H B Tucker by WAH

H. B. Tucker

SAG/ibh

cc: Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Reg. Comm. - Region II
101 Marietta Street Suite 3100
Atlanta, Georgia 30323

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Framington Avenue
Framington, CT. 06032

8409130414 840905
PDR ADCK 05000370
S PDR

*IE22
/o*