

August 23, 1984  
(NMP2L 0141)

Mr. R. W. Starostecki, Director  
U.S. Nuclear Regulatory Commission  
Region I  
Division of Project and Resident Programs  
631 Park Avenue  
King of Prussia, PA 19406

Re: Nine Mile Point Unit 2  
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report in accordance with 10CFR50.55(e) for the problem concerning installation of Quality Assurance Category I bolted flanged piping joints without a documented procedure. This problem was reported via telecon to S. Collins of your staff on July 23, 1984.

Very truly yours,

*C. V. Mangano*

C. V. Mangano  
Vice President

Nuclear Engineering & Licensing

NLR:ja  
Enclosure  
xc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Project File (2)

NIAGARA MOHAWK POWER CORPORATION  
NINE MILE POINT UNIT 2  
DOCKET NO. 50-410

Interim Report for a Problem  
Concerning Bolted Flanged Piping Joints  
(55(e)-84-28)

Description of the Problem

The problem concerns the installation of Quality Assurance Category I bolted flanged piping joints by ITT Grinnell without a documented procedure. 10CFR50, Appendix B, Criterion V states, in part, that the activities affecting quality shall be prescribed by documented instructions and procedures. The matter is still under investigation, and a final report will be submitted by November 15, 1984.