

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30303

Report Nos.: 50-321/84-24 and 50-366/84-24

Licensee: Georgia Power Company

P. O. Box 4545 Atlanta, GA 30302

Docket Nos.: 50-321 and 50-366

License Nos.: DPR-57 and NPF-5

Facility Name: Hatch 1 and 2

Inspection Dates: June 21 - July 20, 1984

Inspection at Hatch site pear Baxley, Georgia

Inspectors

R.V. Crienjak, Senfor Resident Inspector

8/6/84

P. Holmes-Resident Inspe

Date Signed

Approved by:

V. W. Panciera, Chief, Project Section 2B

Division of Reactor Projects

Date Signed

SUMMARY

Areas Inspected

This inspection involved 167 inspector-hours on site in the areas of Technical Specification compliance, operator performance, overall plant operations, quality assurance practices, station and corporate management practices, corrective and preventive maintenance activities, site security procedures, radiation control activities, and surveillance activities.

Results

Of the areas inspected, no violations or deviations were identified.

REPORT DETAILS

1. Persons Contacted

Licensee Employees

H. C. Nix, Site General Manager

*T. Greene, Deputy Site General Manager

*L. Sumner, Operations Manager

*P. Fornel, Site QA Manager

S. B. Tipps, Superintendent of Regulatory Compliance

Other licensee employees contacted included technicians, operators, mechanics, security force members and office personnel.

*Attended exit interview

2. Exit Interview

The inspection scope and findings were summarized on July 26, 1984, with those persons indicated in paragraph 1 above.

Licensee Action on Previous Inspection Findings

Not inspected.

4. Unresolved Items

Unresolved items were not identified during this inspection.

5. Plant Tours (Units 1 and 2)

The inspectors conducted plant tours periodically during the inspection interval to verify that monitoring equipment was recording as required, equipment was properly tagged, operations personnel were aware of plant conditions, and plant housekeeping efforts were adequate. The inspectors also determined that appropriate radiation controls were properly established, critical clean areas were being controlled in accordance with procedures, excess equipment or material was stored properly and combustible material and debris were disposed of expeditiously. During tours the inspectors looked for the existence of unusual fluid leaks, piping vibrations, pipe hanger and seismic restraint settings, various valve and breaker positions, equipment caution and danger tags, component positions, adequacy of fire fighting equipment, and instrument calibration dates. Some tours were conducted on backshifts.

The inspectors routinely conduct partial walkdowns of ECCS systems. Valve and breaker/switch lineups and equipment conditions are randomely verified both locally and in the control room. During the inspection period the

inspectors conducted a complete walkdown in the accessable areas of the Unit 1 Train B Low Pressure Core Injection to verify that the lineups were in accordance with licensee requirements for operability and equipment material conditions were satisfactory.

Within the areas inspected, no violations or deviations were identified.

6. Plant Operations Review (Units 1 and 2)

The inspectors periodically during the inspection interval reviewed shift logs and operations records, including data sheets, instrument traces, and records of equipment malfunctions. This review included control room logs and auxiliary logs, operating orders, standing orders, jumper logs and equipment tagout records. The inspectors routinely observed operator alertness and demeanor during plant tours. During normal events, operator performance and response actions were observed and evaluated. The inspectors conducted random off-hours inspection during the reporting interval to assure that operations and security remained at an acceptable level. Shift turnovers were observed to verify that they were conducted in coordance with approved licensee procedures.

Within the areas inspected, no violations or deviations were identified.

7. Technical Specification Compliance (Units 1 and 2)

During this reporting interval, the inspectors verified compliance with selected limiting conditions for operations (LCO's) and results of selected surveillance tests. These verifications were accomplished by direct observation of monitoring instrumentation, valve positions, switch positions, and review of completed logs and records. The licensee's compliance with selected LCO action statements were reviewed on selected occurrences as they happened.

Within the areas inspected, no violations or deviations were identified.

8. Physical Protection (Units 1 and 2)

The inspectors verified by observation and interviews during the reporting interval that measures taken to assure the physical protection of the facility met current requirements. Areas inspected included the organization of the security force, the establishment and maintenance of gates, doors and isolation zones in the proper condition, that access control and badging was proper, and procedures were followed.

Within the areas inspected, no violations or deviations were identified.

9. Review of Nonroutine Events Reported by the Licensee (Units 1 and 2)

The following Licensee Event Reports (LERs) were reviewed for potential generic impact, to detect trends, and to determine whether corrective actions appeared appropriate. Events which were reported immediately were

also reviewed as they occurred to determine that Technical Specifications were being met and that the public health and safety were of utmost consideration. The following LER's are considered closed:

Unit 1: 82-73, 84-06 and 84-07