

TENNESSEE VALLEY AUTHORITY

P R P
OFFICIAL COPY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

84 AUG 30 P August 28, 1984
1:22

BLRD-50-438/83-30
BLRD-50-439/83-26

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DEFECTS IN PIPE CLAMPS BY ITT
GRINNELL - BLRD-50-438/83-30, BLRD-50-439/83-26 - THIRD INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Linda Watson on April 6, 1983 in accordance with 10 CFR 50.55(e) as NCR 2318. This was followed by our interim report dated May 6, 1983. Related NCR 2917 was later initiated and is now being reported on with NCR 2318. Our second interim report was submitted on May 24, 1983. Below is our third interim report. We expect to submit our next report by November 16, 1984. We consider 10 CFR Part 21 to be applicable to this deficiency.

TVA has scheduled a meeting with ITT-Grinnell at ITT-Grinnell's Warren, Ohio, facility to inspect the 64 four-inch clamps which TVA returned for rework. The intent of the meeting is to develop a consensus on the deficient condition and required corrective actions. TVA will document the results of this meeting in our next report.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8409240223 840828
PDR ADOCK 05000438
S PDR

OFFICIAL COPY
110
TE 27