ILLINOIS POWER COMPANY



0981-L U-10187

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

August 13, 1984

Docket No. 50-461

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject:

Revised Response to Notice of Violation, NRC IE Inspection Report Number 50-461/81-25

Dear Mr. Keppler:

This letter is in reference to the Illinois Power Company response U-0396, dated January 8, 1982, to your Notice of Violation dated December 9, 1981, NRC IE Inspection Report Number 50-461/81-25.

The violation identified by the NRC inspector was that "physical and environmental protection from nearby construction activity was not provided for...numerous precut, coiled, temporarily stored Class IE electrical cables." The response contained in Illinois Power Company letter U-0396 stated in part:

With regard to cable protection, four (4) enclosed staging areas are being constructed in the plant to provide a suitable controlled environment for cables temporarily stored near the construction activity.

Illinois Power Company provides the following revised response:

1. Baldwin Associates procedure BAP 3.3.2, Cable Installation, will incorporate the requirement that cable be stored in designated areas for protection from potential damage. Cable storage prior to installation shall be in accordance with procedure BAP 2.4, Storage and Maintenance.

August 13, 1984

 Baldwin Associates Quality Control shall perform in-plant storage inspections on a periodic basis to assure storage requirements are maintained.

I trust that our response is satisfactory to maintain compliance with regulatory requirements.

Sincerely yours,

D. P. Hall Vice President

JRS/cbs (NRC2)

cc: Director, Office of I&E, US NRC, Washington, DC 20555 NRC Resident Office Illinois Department of Nuclear Safety