NOTICE OF VIOLATION

Georgia Power Company Hatch Unit 1 and 2

Docket No. 50-321,366 License No. DPR-57, NPF-5

During the NRC inspection conducted on August 6 - September 2, 1995, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy) (60 FR 34381, June 30, 1995), the violation is listed below:

10 CFR 50, Appendix B, Criteria V, Instructions, Procedures and Drawings, requires that activities affecting quality shall be prescribed by documented instructions and shall be accomplished in accordance with these instructions.

Procedure 52PM-MME-006-0S: Intake Structure Pit Inspection, Revision 3, delineates the requirements, precautions/limitations, and prerequisites for performing underwater inspection activities in the intake structure.

Procedure 34SO-P73-001-IS: Hydrogen Water Chemistry Hydrogen Injection System, Revision 11, Section 7.3.4, Manual Operation of Hydrogen Controller, delineates the necessary steps for reducing the hydrogen injection flow rate.

Contrary to the above:

- On August 23, 1995, inspection of the intake structure pit was not accomplished in accordance with procedure 52PM-MME-006-0S in that a diver entered the intake structure and performed work activities without the use of the procedure. This contributed to the diver's support line entering the Residual Heat Removal Plant Service Water pump, rendering it inoperable.
- 2. On August 27, 1995, a reduction in the Unit 1 hydrogen injection flow rate was not accomplished in accordance with procedure 34S0-P73-001-1S in that an operator performed a step not delineated in the procedure. This caused the hydrogen flow to increase beyond the desired value, and resulted in unnecessary exposure to personnel performing maintenance in the condenser bay.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Georgia Power Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, Hatch Nuclear Plant, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for

each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or demand for information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia this 29day of SEPT. 1995