## ENCLOSURE 1

## NOTICE OF VIOLATION

Omaha Public Power District Fort Calhoun Station Docket: 50-285 License: DPR-40

During an NRC inspection conducted on August 13 through September 23, 1995, two examples of a violation of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (60 FR 34381; June 30, 1995), the violation is listed below:

Criterion V of Appendix B to 10 CFR Part 50 states, in part, that activities affecting quality shall be prescribed by documented procedures, of a type appropriate to the circumstances, and shall be accomplished in accordance with these procedures.

1. Standing Order SO-G-107, Revision O, "Storage of Transient Equipment and Material to Prevent Seismic Interactions," requires in Step 5.1.4.b that ladders may be secured to cable trays, heating, ventilation, and air conditioning ductwork, piping or conduit greater than 2 inches nominal diameter, or any associated structural support hardware.

Contrary to the above, on August 16, 1995, the inspector observed that maintenance personnel had secured a ladder to an electrical conduit that was less than 2 inches in nominal diameter.

2. Preventive Maintenance Procedure IC-PM-DSS-1001, Revision 4, "Diverse Scram System Actuation Relay Operability," requires that the operator manipulate Manual Trip Switch DSS (B/TS-DSS).

Contrary to the above, on August 24, 1995, a reactor operator failed to accomplish an activity prescribed by Procedure IC-PM-DSS-1001 in that the operator manipulated the wrong switch as specified in the surveillance procedure for performance of the diverse scram system test, resulting in a plant trip.

This is a Severity Level IV violation (285/9514-01) (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Omaha Public Power District is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous

docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because the response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if it is necessary to include such information, it should clearly indicate the specific information that should not be placed in the PDR and provide the legal basis to support the request for withholding the information from the public.

Dated at Arlington, Texas, this 4th day of October 1995