

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT I DOCKET NUMBER (2) 050003211 PAGE (3) 1 OF 01

TITLE (4) Inoperable Fire Barrier Penetration Seals

EVENT DATE (5)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)		
08	24	84	84	018	00	09	24	84	E. I. HATCH, UNIT II	05000366		
									05000			

OPERATING MODE (9) 1
 POWER LEVEL (10) 0910
 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(e)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)
 NAME: T. L. Elton, Acting Superintendent of Regulatory Compliance
 TELEPHONE NUMBER: 9112 3167 + 1781511
 AREA CODE: 9112

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
N/A									

SUPPLEMENTAL REPORT EXPECTED (14)
 YES (If yes, complete EXPECTED SUBMISSION DATE)
 NO
 EXPECTED SUBMISSION DATE (15) 040886
 MONTH: 04, DAY: 08, YEAR: 86

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 08/24/84, during a fire barrier penetration walkdown, contract personnel noted that numerous fire barrier penetration seals for Unit 1 and Unit 2 were not functional as required by Unit 1 Tech. Specs. section 3.13.6 and Unit 2 Tech. Specs. section 3.7.7.

The cause of this event is personnel error due to the fire barrier penetrations' seals not being installed as required. The fire barrier penetration walkdown is still in progress at this time.

8410050405 840924
 PDR ADOCK 05000366
 S PDR

IE22
 1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) EDWIN I. HATCH, UNIT I	DOCKET NUMBER (2) 0 5 0 0 0 3 2 1	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 4	- 0 1 8	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On 08/24/84, with Unit 1 at 2204 MWT (approximately 90% power) and Unit 2 in cold shutdown for the recirculation pipe replacement outage, during a fire barrier penetration walkdown, contract personnel found numerous fire barrier penetration seals for Unit 1 and Unit 2 inoperable. Upon discovery of the inoperable seals, firewatches were established as required by Unit 1's Tech. Specs. section 3.13.6, ACTION a., and Unit 2's Tech. Specs. section 3.7.7, ACTION a., until the necessary repairs were made. The walkdown is still in progress.

The health and safety of the public were not affected by this repetitive event as last reported on LER 50-321/1983-092.

An update report will be submitted which will include a summary assessment of actual and potential safety consequences and implications due to these events, and the corrective action taken to prevent recurrence of these events. This LER was signed one day late.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin I. Hatch Nuclear Plant

September 24, 1984
GM-84-837

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1984-018. This report is required by 10CFR 50.73(a)(2)(i).



H. C. Nix
General Manager

JCC
HCN/TLE/vlz

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

1522
1/1