

ENCLOSURE 1

NOTICE OF VIOLATION

Alabama Power Company
Farley Unit 2

Docket No. 50-364
License No. NPF-8

The following violation was identified during an inspection conducted on January 14 - 17, 1985. The Severity Level was assigned in accordance with the MRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification (TS) 6.8.1(b) requires that procedures be established, implemented and maintained covering refueling activities.

Contrary to the above, on January 16, 1985, the licensee was performing a video inspection to determine possible fuel damage during cycle 3 operation in the spent fuel pool with no procedure governing that activity. This violated TS requirement 6.8.1(b).

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: FEB 11 1985

8503070112 850211
PDR ADOCK 05000348
Q PDR