LICENSEE EVENT REPORT (LER)											U.S. A	NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85													
PACILITY	NAME (1)				_			-	-	-				DOC	KET	UMBE	R (2)		-		F	P	AGE	(3)
	ED	WIN I	. н	ATC	H, UNIT	I									0	5	0 10	0 10	13	2	11	1	0	F	0 2
TITLE IA		SPEC	S.	REO	UIRED S	URV	EILL	ANCE	PE	RF	ORI	MED	LATE												
TECH. SPECS. REQUIRED SURVEILLANCE PERFORMED I											OTHER *ACILITIES INVOLVED (8)														
MONTH	DAY	YEAR	YEAR		SEQUENTIAL	T	REVISION	MONTH	T	DAY	T	YEAR	FACILITY NAMES				DOCKET NUMBER(S)								
					- AUMBER	-	NUMBE	1	+		-:-						0	15	0	10	10	1	1	1	
0 1	2 8	8 5	8	5 -	0 1 1 4	-	00	0 2	2	1:	7 8	15						0	15	10	10	10		1	1
01.4	RATING	0 3	-	-	T IS SUBMITTE	D PU			REGI	UIRE	MEN	TS OF	0 CFR 8: 10	heck one or more	e of th	ne falla	wing)	(11)	-	-	-	_	_	_	-
	R L	910	20.405(a)(1)(i) 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iv)					50.38(c) 50.38(c) 50.73(c)	20.405(c) 50.38(e)(1) 50.38(e)(2) 60.73(a)(2)(i) 50.73(a)(2)(ii)					50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A) 50.73(a)(2)(viii)(B)				73,71(b) 73,71(c) OTHER (Specify in Abstract below and in Text, NRC Form 366A)							
			20.406(a)(1)(v)					80.73(4	50.73(a)(2)(iii)					50.73(a)(2)(x)											
	-							LICENSEE	CO	NTA	CT F	OR THI	LER (12)												
T.	. El	ton,	Act	ing	Superi		THE RESERVE OF THE PARTY OF THE	700 A 11 000 TO 1000		-	32.15			iance	ORT (1	91	1 2	T	[6				18	1	5 1
CAUSE	SYSTEM	YSTEM COMP		ONENT MANUFACTURER			ORTABLI NPRDS	E				CAUSE	SYSTEM	COMPONENT		MANUFAC TURER			TO	RTAB					
	1	1	ш	1	111									111		_									

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) [16]

YES (If yes, complete EXPECTED SUBMISSION DATE)

SUPPLEMENTAL REPORT EXPECTED (14)

On 02/04/85, plant instrumentation and controls (I & C) personnel determined that the "RCIC PUMP SUCTION PRESSURE INSTRUMENT FT&C" procedure (HNP-1-3417) had not been performed by its latest date of 01/28/85 (i.e., its due date of 01/21/85 plus the 25% grace period allowed by Tech. Specs. definition II). This procedure satisfies the surveillance requirement for item 4 of Tech. Specs. Table 4.2-3.

X NO

DAY

EXPECTED

YEAR

The cause of this event is personnel error. The surveillance computer tracking sheet (shows the dates between which the procedure must be performed) had been signed off indicating that this procedure had been performed. Thus, I & C personnel thought the procedure had been performed since the sign off section of the tracking sheet was completed. However, the personnel who signed off the procedure on the tracking sheet realized that he had inadvertently signed off the wrong procedure, and he put a single line thru the completion date for HNP-1-3417. This line was meant to denote that the procedure had not been performed; however, the line was very fine in comparison to the size of the sign off. Therefore, the line was overlooked, and other I & C personnel were not aware that the procedure had not been performed until 02/04/85.

Both supervision and the technicians involved have reviewed the serious nature and the root cause of this incident and taken steps to prevent recurrence. I & C personnel have been instructed on how to correct mistakes on plant documents so that the correction is readily apparant.

8503110010 850227 PDR ADOCK 05000321 S PDR

U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OMB NO 3150-0104 EXPIRES 8/31/86 FACILITY NAME (1) DOCKET NUMBER (2) PAGE (3) LER NUMBER (8) SEQUENTIAL NUMBER YEAR NUMBER

0 |5 |0 |0 |0 |3 |2 |1 8 |5

0 1 15

10 0 12 OFD

TEXT (If more space is required, use additional NRC Form 366A's/ (17)

EDWIN I. HATCH, UNIT I

On 02/04/85, plant instrumentation and controls (I & C) personnel determined that the "RCIC PUMP SUCTION PRESSURE INSTRUMENT FT&C" procedure (HNP-1-3417) had not been performed by its latest date of 01/28/85 (i.e., its due date of 01/21/85 plus the 25% grace period allowed by Tech. Specs. definition II). This procedure satisfies the surveillance requirement for item 4 of Tech. Specs. Table 4.2-3.

The cause of this event is personnel error. The surveillance computer tracking sheet (shows the dates between which the procedure must be performed) had been signed off indicating that this procedure had been performed. Thus, I & C personnel thought the procedure had been performed since the sign off section of the tracking sheet was completed. However, the personnel who signed off the procedure on the tracking sheet realized that he had inadvertently signed off the wrong procedure, and ne put a single line thru the completion date for HNP-1-3417. This line was meant co denote that the procedure had not been performed; however, the line was very fine in comparison to the size of the sign off. Therefore, the line was overlooked, and other I & C personnel were not aware that the procedure had not been performed until 02/04/85.

Both supervision and the technicians involved have reviewed the serious nature and the root cause of this incident and taken steps to prevent recurrence. I & C personnel have been instructed on how to correct mistakes on plant documents so that the correction is readily apparant.

Georgia Power Company Post Office Box 439 Baxley, Georgia 31513 Telephone 912 367-7781 912 537-9444



Edwin I. Hatch Nuclear Plant

February 27, 1985 GM-85-170

PLANT E. I. HATCH Licensee Event Report Docket No. 50-321

United States Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1985-014. This report is required by 10CFR 50.73(a)(2)(i).

General Manager

of JEC HCN/TLE/ulz

XC:

R. J. Kelly

R. E. Conway

J. T. Beckham, Jr.

P. D. Rice

K. M. Gillespie

Superintendent of Regulatory Compliance

R. D. Baker Control Room

Document Control