### Bypass of Leakage Detection System    EVENT DATE (8)	UCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85			
### Bypass of Leakage Detection System    EVENT DATE (8)	PAGE (3)			
Bypass of Leakage Detection System	OF 0 12			
EVENT DATE (6)   LER NUMBER (6)   REPORT DATE (7)   OTHER FACILITIES INVOLVED (8)	101.			
EVENT DATE (8)   LER NUMBER (6)   REPORT DATE (7)   OTHER FACILITIES INVOLVED (8)				
1 0 1 8 8 4 8 4 0 4 7 0 0 1 1 1 6 8 4   0 4 7 0 0 0 1 1 1 1 6 8 4   0 4 7 0 0 0 1 1 1 1 6 8 4   0 4 7 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
NA 0 5 0 0 0  1 0 1 8 8 4 8 4 0 4 7 0 0 1 1 1 6 8 4  OPERATING MODE (8)  THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR \$:  Check one or more of the following! (11)  POWER LEVEL   20.405(a)   2				
1 0 1 8 8 4 8 4 0 4 7 0 0 1 1 1 6 8 4 0 0 5 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1 1 1			
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR \$: (Check one or more of the following) (11)				
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR \$: (Check one or more of the following) (11)	1 1 1			
MODE (8) 1 20.402(b) 20.406(c) 30.73(a)(2)(iv) 72.71(b) 72.71(b) 90.36(c)(1) 80.36(c)(1) 80.73(a)(2)(v) 73.71(c) 73.71(c				
POWER LEVEL (19) 20.406(a)(1)(i) 80.36(a)(2) 80.73(a)(2)(vii) OTHER (Specify in Delay and in Text 3,66A) 90.406(a)(1)(iv) 80.73(a)(2)(iii) 80.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(B) 80.73(a)(2)(viii)				
So. 73(a) (2) (vii)   So. 73(a) (2) (vii)   So. 73(a) (2) (vii)   So. 73(a) (2) (viii)   So. 73(a) (2) (viii) (A)   So. 73(a) (2) (viii) (A)   So. 73(a) (2) (viii) (A)   So. 73(a) (2) (viii) (B)   So. 73(a) (				
20.406(a)(1)(iii)  20.406(a)(1)(iv)  20.406(a)(1)(iv)  20.406(a)(1)(v)  20	OTHER (Specify in Abstract			
20.405(a)(1)(iv)  20.405(a)(1)(iv)  50.73(a)(2)(iii)  EICENSEE CONTACT FOR YHIS LER (12)  TELEPHONE NUMBER AREA CODE AREA CODE COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE	below and in Text, NRC Form			
20.405(a)(1)(v) 50.73(a)(2)(lil) 50.73(a)(2)(x)  LICENSEE CONTACT FOR THIS LER (12)  TELEPHONE NUMBER AREA CODE AREA CODE COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE				
Ronald W. Byrd/Licensing Engineer  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  LICENSEE CONTACT FOR YHIS LER (12)  TELEPHONE NUMBER  AREA CODE  6   0   1   4   3   7   -   2  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE				
Ronald W. Byrd/Licensing Engineer  COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE				
Ronald W. Byrd/Licensing Engineer  COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE  CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE				
CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE				
CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE	1 1 1 4 19			
CAUSE ISYSTEM! COMPONENT   CAUSE ISYSTEM! COMPONENT   CAUSE ISYSTEM!	11417			
CAUSE ISYSTEM! COMPONENT   CAUSE ISYSTEM! COMPONENT   CAUSE ISYSTEM!				
	AY YEAR			
EXPECTED SUBMISSION				
YES (If yes, complete EXPECTED SUBMISSION DATE) X NO	1 1			

On October 18, 1984, the bypass switches of the Leakage Detection System on the Reactor Water Cleanup (RWCU), the Residual Heat Removal (RHR), and the Reactor Core Isolation Cooling (RCIC) Systems were placed in bypass for maintenance troubleshooting. This violated Technical Specification 3.3.2 due to exceeding the one hour time limit the switches are allowed to be in bypass.

8411280319 841116 PDR ADOCK 05000416 PDR

IE22

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION  LICENSEE EVENT REPORT (LER) TEXT CONTINUATION  APPROVED 06/2/ NO 3150-0104  EXPIRES. 8/31/85								
FACILITY NAME (1)	DOCKET NUMBER (2)	L	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Grand Gulf Nuclear Station - Unit	0  5  0  0  0   4   1   6	8 4 -	0 4 7	- 0 10	0 2	OF	0   2	

On October 18, 1984, between 0757 hours and 0945 hours, the bypass switches of the Leakage Detection System on the Reactor Water Cleanup, the Residual Heat Removal and the Reactor Core Isolation Cooling Systems were placed in bypass to troubleshoot an inadvertent Reactor Water Cleanup containment isolation which occurred on October 17, 1984.

In order to comply with Technical Specification 3.3.2, the Leak Detection System can only be bypassed for a minimum of one hour without isolating the affected system.

The operator had erroneously assumed that the bypass switches could be placed in bypass for up to two hours according to Technical Specification Table 3.3.2-1 note (b). This only applies if there is another operable channel in the same system to monitor the parameters. Because of the assumption, an action statement entrance was not realized, therefore, an LCO was not written.

The error was corrected immediately upon discovery. A change has been initiated to the Alarm Response Instructions for the bypass alarms of these leak detection switches to make the operator aware of the one hour limit of Technical Specification 3.3.2.



## MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

November 16, 1984

NUCLEAR LICENSING & SAFETY DEPARTMENT

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-29 File: 0260/L-835.0

Bypass of Leakage Detection System

LER 84-047-0 AECM-84/0516

Attached is Licensee Event Report (LER) 84-047-0 which is a final report.

Yours truly,

Director

EBS/SHH:vog Attachment

cc: Mr. J. B. Richard (w/a)

Mr. R. B. McGehee (w/a)

Mr. N. S. Reynolds (w/a)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. P. O'Reilly, Regional Administrator (w/a) U.S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30323