

NUCLEAR REGULATORY COMMISSION REGION V

D. Kirsch

1450 MARIA LANE, SUITE 210 WALNUT CREEK, CALIFORNIA 94596

DESIGNATED ORIGINAL

Certified By Ot nock

April 27, 1984

J. D. Schuyler, Vice President Nuclear Power Generation Pacific Gas and Electric Company 77 Beale Street San Francisco, Ca 94106

Dear Sir:

Enclosed in "Appendix A" is a list of 146 allegations or concerns to be turned over to PG&E for evaluation, investigation and response.

The above mentioned allegations and concerns are identified in "Appendix A" by NRC allegation number and Corresponding Government Accountability Project and Joint Intervenor's petition numbers dated 2/2/84; 2/22/84; 3/2/84; 3/23/84; and 4/6/84. The referenced source documents contain the applicable background information compiled by this office.

For each specific allegation or concern forwarded by this letter, the NRC must be appraised, in writing, of the results of the PG&E investigation, the necessary corrective action, and the expected completion date. We request that your responses be titled with the appropriate allegation or petition number. Your responses will be evaluated by the staff for clarity, comprehensiveness, and substance. You will be advised of the staff's position upon completion of the staff's evaluation. Your written response is required within 30 days of receipt of this letter.

We will be happy to answer any questions you may have regarding this matter.

Sincerely,

T. W. Bishon, Direct

T. W. Bishop, Director Division of Reactor Safety & Projects

Enclosure: As Stated

8411290605 840427 PDR ADOCK 05000275 Countlease tof DR"
HOOS
84-395

22 - 85 34 22

21 - 8: 4 21

NRC	A	LLEGATIO	N S'NIRCE	DOCUM	ENT		CHARACTERIZATION
LLEGATION	2/2/84	12/22/94	613/2/841	3/2/84	13/23/84	4/16/84	
NUMBER	GAP	1 11	I GUP	JI	GAP	D.Kirsch	
225	52	52					PROCEDURES FOR INSPECTIONS MAY HAVE BEEN AS UNCONTROLLED AS FOR THE WELDS THEMSELVES
227	57	57					WELDS HAVE BEEN REPAIRED WITHOUT REVISING THE RELEVANT DRAWINGS 70 NOTE THE DIFFERENCES
234	100	100					PULLMAN'S APPROVED VENDORS LIST IS DEFICIENT IN THAT "MICROSURFACE ENGINEERING" DID NOT HAVE ADEQUATE QA PER MR. HUDSON'S OCTOBER 1981
235	101	101					EFFECTS OF LACK OF "MICROSURFACE ENGINEERING" QA UPON CALIBRATIONS, TOOLS, AND MEASUREMENTS NOT DETERMINED
236	105	105					CONTRACTOR FOLEY DID NOT USE RIGHT PARTS (I.E. BEAM CLAMPS)
237	106	106					WRONG SIZE BEAM CLAMPS USED BY FOLEY TECHNICALLY INADEQUATE
239	112	112					PROCEDURES UNRELIABLE - COPPER AND STAINLESS TUBING INSTALLATION
240 .	113	113,					RESUBMITTED TEST PROCEDURES QUESTIONABLE (TUBING)
241 -	114	114					WELDING AND NDE PROCEDURES QUALIFIED AFTER THE FACT QUESTIONABLE
242	118.	11.8					NO REJECTION CRITERIA (PIPE RUPTURE RESTRAINT BOLTS) .
243	119	1119					QA INSPECTORS NOT PROMPTLY NOTIFIED OF SPECIFICATION CHANGES

22 - 85 34 22

21 - S! A 21

NRC:	A	LLEGATIO	N S'XURCI	E DOCUM	ENT	4/16/84	CHARACTERIZATION
LLEGATION	2/2/84	12/22/94	13/2/84	3/2/84	3/23/84	14/16/84	
NUMBER	GAP		CIP	1 31	UNF	P.Kirsch	
244	123	123					TECHNICIAN NPPR'S REQUIRED FOREMAN APPROVAL
245	1,24	124					PG&E VOIDED NPPR'S WITHOUT EXPLANATION
246	125	125					CONSTRUCTION PERSONNEL ORDERED NOT TO WRITE NPPR'S
251	139	139					PULLMAN QA HAD TO MEET ITS SCHEDULE WITH INADEQUATE RESOURCES
253,	B147						MANAGEMENT DID, NOT SUPPLY BLANK DISCREPANCY REPORT FORMS
255	B149						PG&E TECHNICIANS "WERE ROUTINELY DENIED ACCESS TO NECESSARY INFORMATION TO PERFORM THEIR JOBS"
257	B151						TECHNICIANS WERE DENIED CURRENT DRAWINGS AND OTHER REFERENCE MATERIALS
258	152						PG&E FOREMAN PURGED THE TECHNICIANS FILES OF UNCONTROLLED DRAWINGS
259 *	166						PG&E DOES NOT NOTIFY THE ORIGINATOR OF A DEFICIENCY REPORT THAT A DECISION HAS BEEN REACHED
261	169		1			-	PG&E CONTENTION THAT THIS SYSTEM (MAH) IS NOT SAFETY RELATED IS INCORRECT (BASED ON TMI)
263			180	180			REVISED PULLMAN ESD223 ALLOWS EXTRA WELDINGS NOT REQUIRED BY THE DESIGN THUS CREATED UNACCOUNTED RESIDUAL STRESS

22 - S5 sa 22

21 - S! SR 21

NRC	Al	LECATIO	N S'NURCE	DOCUM	ENT		CHARACTERIZATION
LEGATION	2/2/84	2/22/94	13/2/841	3/2/84	13/23/84	4/16/84	
NUMBER	GAP	11_	GUP !	JI_	GAP	D.Kirscht	
264			181 '	181 '			THE ABOVE REVISION SUGGESTS QA STANDARDS HAVE COLLAPSED
265			182	182			PG&E ACCEPTED THE ABOVE REVISION OF PULLMAN
266			183	183			PGSE ACCEPTED WELDS THAT FAILED MT
267			184	184			PGAE DIRECTED PULLMAN TO ACCEPT WELDS THAT WERE NOT TESTED PROPERLY
268			185	185			WELD PROCEDURES ARE NOT APPLIED CONSISTENTLY
269			186	186			IGNORANCE OF INSTALLATION PROCEDURES DUE TO MANAGEMENT POLICY
270			187	187			PULLMAN QC MANAGER PROHIBITED INSPECTORS CHECKING A-490 BOLTS CARBON CONTENT SPECIFICATION WHICH IS NOT PART OF INSPECTOR'S JOB
274			191	191			THE ABOVE INDIVIDUAL WAS LAID OFF DESPITE HIS FOREMAN'S REQUEST TO KEEP HIM
278			197	197			PULLMAN QC MANAGER UNSATISFACTORILY DISPOSITIONED A DCN OF UNMARKED TOOLS USED ON STAINLESS STEEL
284			215				THE PLANT IS BEING DESIGNED AND BUILT THROUGH MEMORANDA RATHER THAN UNDER CONTROLLED PROCEDURES (SEE #8)
294			237		!		FIELD ENGINEERING PERSONNEL ARE CONSISTENTLY UNTRAINED AND ARE NOT CONSISTENTLY KNOWLEDGEABLE ABOUT WELD SYMBOLS

22 - 8534 22

21 - S! SR 21

NRC		LLEGATIO	M S'NIRC	E DOCUM	ENT		CHARACTERIZATION
LLEGATION	2/2/84	12/22/94	13/2/84	13/2/84	13/23/84	14/16/84 D.Kirsch	
295`			240				THE WORD "TYPICAL" HAS BEEN UTILIZED TOO EXTENSIVELY IN VARIOUS INTERPRETATIONS
352							PG&E'S FAILURE ANALYSIS OF F.W.212 PERFORMED BY PULLMAN
353							INCONSISTANCIES IN THE INSPECTION COVERAGE BETWEEN WELDS F.W.197-
354							PG&E FAILED TO REPORT WELDING DEFICIENCIES PER 50.55 (e)
355 ·							PG&E FAILED TO REPORT REJECTABLE INDICATIONS STATED IN DR3370 TO
356							A RADIOGRAPHIC LEVEL II INSPECTOR ACCEPTED RADIOGRAPHS BEFORE HE WAS CERTIFIED AND THIS NON-CONFORMANCE WAS NOT REPORTED VIA QA SYSTEM
357							F.W.197 WAS NOT REPAIRED ACCORDING TO THE DIRECTION OF DR 3484. ANIINTEROFFICE CORRESPONDENCE WAS USED INSTEAD. INITIATED BY UNQUALIFIED PERSON
: 358							DR 3484 FAILED TO INCLUDE PROPER WELDING PROCEDURE IN THE RECOMMENDED DISPOSITION
359 •							CRACK WAS IMPROPERLY REFERRED AS LINEAR INDICATION ON F.W. 212, AND PROPER CORRECTIVE ACTION TAKEN IS UNKNOWN
338	1.						FAILURE TO REPORT CRACK ON F.W. 212 TO NRC PER 50.55 (e). CORRECTION TO CRACKS UNDETERMINED
339		1			1		Q.A. BREAKDOWN DUE TO FAILURE TO DISCOVER WELDING DEFECTS

22 - SS 34 22

21 - S: SR 21

NRC	1 7	ALLEGATIO	N S'NURC	E DOCU	ENT		CHARACTERIZATION
LLEGATION	2/2/84	412/22/34	413/2/84	613/2/84	413/23/84	4/16/84	
NUMBER	GAP	1 11	GUP	JI	GAP	P.Kirsch	
340							FAILURE TO NOTIFY NRC PER 10 CFR 21/50.55 (a) WHEN 100% REINSPECTION OF RADIOGRAPHS REVEALED PREVIOUS MISINTERPRETATION
360					PAGE 2		FIVE WELD INSPECTORS WITH LEVEL II STAMPS WITHOUT APPROPRIATE PAPERWOR
361					PAGE 2	1 1	WELDING INSPECTOR NOT CERTIFIED TO CERTIFY OTHER WELDERS
362					PAGE 3		WELDERS DID NOT HAVE UNIQUE STAMPS AS REQUIRED BY AWS
363-					ATT.12 PAGE 3	1	MANAGEMENT ROUTINELY ALLOWED WELDERS TO TAKE REQUALIFICATION TESTS DAILY UNTIL THEY PASSED
364					PAGE 4	!!!	INADEQUATE TRAINING FOR QC INSPECTORS
365					PAGE 5		TRACEABILITY (HEAT NUMBERS) LOST AFTER MATERIAL
366		1			ATT.12 PAGE 5		STAINLESS STEEL T-SECTION OF PIPE WITH A FOUR INCH LINEAR UNDERCUT LEFT UNREPAIRED
367					PAGE 6	.	GUIDED BEND TEST MACHINE DID NOT SATISFY AWS REQUIREMENTS CONCERNING TOLERANCES BETWEEN SHOE AND DIE IN THE HYDRAULIC JACK
368	1.		1.		ATT.12 PAGE 6	1.	QUICK FIXES NOT BEING REVIEWED BY QA AND HAD NO SERIOUS ENGINEERING ANALYSIS
369		1			PAGE 7		PROFESSIONAL CODES NOT AVAILABLE FOR RESEARCH

22 - 85 34 22

21 - 8: 4 21

NRC:	1	LLEGAT LOS	S NIRC	F DOCU	ENT		CHARACTERIZATION
LLEGATION	2/2/8	12/22/94	13/2/84	13/2/8/	13/23/84	14/16/84	
NUMBER	CAP	131	GUP	i JI	GAP	D. Kirsch	
NULLION		-			ATT.12		
		1	4	i	PAGE 7	1	UP-TO-DATE COPIES OF QUALITY CONTROL PROCEDURES NOT AVAILABLE
370	1	i	1	1	PARA 2	1	
				1	ATT.11	1	QC LEVEL I INSPECTOR QUALIFIED TO ACCEPT WORK WITHOUT A LEVEL II
271		1	1	1	PAGE 1	1	INSPECTOR IN ATTENDANCE
371		i	İ		PARA 3	1	INST BOTOK IN MITTAGE
				1	ATT.11	1	
272		.1	1	1	PAGE 2.	1	LEVEL II QC INSPECTOR SIGNING INSPECTION REPORTS WITHOUT PERSONALLY
372		i			PARA*5		VERIFYING WELLING
		1		1	ATT.11	1	M _ TO THE TOP THE TOP THE THE
373		1	1	1	PAGE 3	1	QC INSPECTORS WERE NOT GIVEN TESTS AT THE END OF ON-THE-JOB TRAINING
		i			PARA 4		
Marie Ma		1		•	ATT.11		The same of the same and the same same same same same same same sam
374		1	1	1	PAGE 4		LESS THAN 50% OF WELDING QC INSPECTORS KNEW NOW TO WELD.
3/4				1	PARA 3		me)
		1		1	ATT.11		THE PRODUCTION
375		1	1	1	PAGE 5		SUPERVISION FROWNED UPON THE USE OF RED TAGS BECAUSE OF THE PRODUCTION
313		1			PARA 2		SCHEDULE
		1		1	PAGE 5	!	MANGEMENT ADVOCATED THAT THE QC INSPECTORS PERFORM "COMPLIMENTARY
		1	1	!			INSPECTIONS"
376				<u> </u>	PARA 3	-	
		1			ATT 11		ELECTRICAL RACEWAY SUPPORT SUPPORTED BY A PIECE OF UNISTRUT THAT HAD
377		1 .		!	PAGE 5		BEEN IMPROPERLY CUT AND INSTALLED
311				<u> </u>	PARA 4	ļ	
		1		!	ATT.11		QC INSPECTOR WAS NEVER PROVIDED WITH THE SUPPORT TO PERFORM HIS DUTIES
378		1		!	IPAGE 6		NOR PROVIDED WITH ADEQUATE TRAINING .
3.0				<u> </u>	IPARA 2	-	NOR PROVIDES WITH ADEQUATE TRAITER
			1.	1	ATT.11		LACK OF AN UP-TO-DATE "HEAT NUMBER" LOG
	1 .	1 .	1	1	PAGE 6		LACK OF AN OF-10-DATE HEALT HOUSEN
379	1_	-			PARA 3	THE R. P. LEWIS CO., LANSING, MICH. 49-140-1-1-1-1	
	1	1.		!	MTT. 12		A LIONA MITHOUT LOOKING AT THE WELD
380			1	!	PAGE 1		LEVEL II INSPECTOR CO-SIGNING LEVEL I WORK WITHOUT LOOKING AT THE WELD

22 - 8534 22

21 - S! SR 21

·mo	-	LLEGATIO	W CHIRC	E DOCUM	ENT		CHARACTERIZATION
NRC LLEGATION	2/2/86	12/22/9/	13/2/84	13/2/84	13/23/84	14/16/84	
NUMBER	CAP	1 41	IGIP	I JI	GAP	D.Kirsch	
381					PAGE 2	#2	UP TO 30% OF THE WELD INSPECTORS WERE NOT QUALIFIED
382					ATT. 10	THE RESIDENCE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAME	ATKINSON-ILLEGALLY PERFORMED INFORMAL WELD REPAIRS COVERED UP INITIA DEFICIENCIES WHOSE EFFECTS WILL REMAIN AS DORMANT HAZARDS
383					ATT.10		ATKINSON - DURING 1979 THE QA INSPECTION PROGRAM ONLY POORLY ENFORCE
384					ATT.10 36		ATKINSON - INVESTIGATION OF WELDING PREHEAT TREATMENT ONLY COVERED WORK IN PROGRESS NOT COMPLETED WELDING
385					ATT.10		ATKINSON - INSPECTOR CONCERNED WITH INADEQUATE PREHEATING OF STEEL GREATER THAN TWO INCHES THICK
386					ATT.10		ATKINSON - PROBLEM WITH LACK OF WELD ROD CONTROL
387					ATT.10		ATKINSON - MANAGEMENT INTRODUCED ERRORS INTO THE BLUEPRINTS BY SWITING IDENTIFICATION CODE ON BLUEPRINTS AND FAILING TO KEEP TRACK OF CHANGES
388					ATT.10 40		ATKINSON - PROPER TORQUING OF BOLTS QUESTION
389			-		ATT. 10	d .	ATKINSON - THREE TURBINE BUILDING CAISSONS WERE IMPROPERLY INSTALL
390	1.	1.	1.		ATT. 1	d.	ATKINSON - TENSION CABLES TO ANCHOR TURBINE PEDESTALS INCORRECTLY ANCHORED TO SANDSTONE INSTEAD OF GRANITE
391	1				ATT. 1	19	ATKINSON- MANAGEMENT DISPLAYED A LACK OF COMMITMENT OF QUALITY INSPECTION

22 = 8534 22

21 - St SR 21

Alleria	And the state of			- 410	-	-	CHARACTERIZATION	
NRC LLEGATION	2 212104	LLECATION	13/7/84	613/2/84	13/23/84	14/16/84 D.Kirach		
NUMBER 396	GAP	31		-	ATT.10	P.KII OCH	ATKINSON - WELDERS REWORK CREATED AN UNKNOWN DEGREE OF EXTRA STRESS OF STRUCTURAL WELDS	
396	-	<u> </u>	-	1	ATT.10 28		ATKINSON - INSPECTORS FOUND IT ALMOST IMPOSSIBLE TO GET UNQUALIFIED WELDERS OFF JOB	
399	-	-	-		ATT.10		ATKINSON - MANAGEMENT DID NOT SATISFACTORILY ADDRESS REPORTS OF . UNDOCUMENTED WELDS	
400	+	-	-		ATT.10		ATKINSON - TACK WELDING PROCEDURE USED, NOT AUTHORIZED IN APPLICABLE WELD SPECIFICATIONS OR PROCEDURES	
	-	1	-	-	ATT.10 32		ATKINSON - INFORMAL OR UNDOCUMENTED WELD REPAIRS CREATED MORE DAMAGE THAN EXISTED INITIALLY IN SOME CASES	
461	-	1	-	1	ATT.10		ATKINSON - EFFECT OF UNCONTROLLED WELD REPAIRS WAS TO DESTROY WELD IN SOME CASES - CREATED UNEVEN STRESS	
402	+	-	+	+	ATT. 10	-	ATKINSON - QA MANAGER DIRECTED QA VIOLATIONS BE INITIALLY REPORTED B MEMORANDA INSTEAD OF FORMAL NONCONFORMANCE REPORTING SYSTEM	
403	-	-	+	+	ATT.10		ATKINSON - MANAGEMENT PREVENTED INSPECTOR FROM INSPECTING SENSITIVE AREAS OF PLANT, BECAUSE HIS INSPECTIONS WERE TOO THOROUGH	
: 404	+	 	+	-	ATT.10	, .	ATKINSON - MANAGEMENT IGNORED QA INSPECTOR MEMORANDUM ON HOLD TAC FALSIFICATION	
408	+	-	1.	+	ATT.10	,	ATKINSON - MANAGEMENT DENIED INSPECTOR AUTHORITY TO ISSUE HOLD TAGE DIRECTLY	
409	1	-	+-	1	ATT.10		ATKINSON - REMOVAL OF QA HOLD TAGS COINCIDED WITH ATTEMPTS TO COVER THE FLAWS THAT HAD BEEN CITED	

22 - 8534 22

21 - 8: 4 21

	-			e pocinery	7		CHARACTERIZATION
NRC	A	LLEGATIO	N S'NUNCI	E DOCUMEN	/23/84	4/16/84	
	2/2/84	2/22/54	3/2/84	1 11	GAP	4/16/84 D.Kirsch	
NUMBER	GAP			1 !	ATT.10		HE QUESTIONED WHETHER PULLMAN COMPLIED WITH LASTEST REVISION TO DESIGN SPECIFICATIONS AND WELDING PROCEDURES
414					ATT.10		ATKINSON-DIRECTED INSPECTOR TO ONLY LOOK AT THE INDIVIDUAL WELD ASSIGNED FOR INSPECTION-NOTHING ELSE
416		-	-		ATT.10		ATKINSON-INCONSISTENT WELD ACCEPTANCE STANDARDS USED BY DAY AND NIGHT SHIFT INSPECTORS
417		-	-		ATT.10		ATKINSON-INCONSISTENT WELD ACCEPTANCE BETWEEN DAY AND NIGHT SHIFT INSPECTORS, BASED ON INFORMAL TOLERANCES ESTABLISHED BY MANAGEMENT
418		-	-		ATT.10		ATKINSON-QUALITY OF EARLY INSPECTORS WAS ERRATIC AND INSPECTION RECORDS SUPERFICIAL
420		-	-		ATT.10		ATKINSON-MANAGEMENT INSTRUCTED WELD INSPECTORS TO EMPHASIZE CERTAIN SECTIONS OF ACCEPTANCE STANDARDS AND IGNORE OTHERS
		-	-		ATT.10		ATKINSON-INCONSISTENT ACCEPTANCE AND REJECTION OF SIMILAR WELDS
421	1	1	-		ATT - 10		ATKINSON-INSPECTOR FOUND A 60% FAILURE RATE DURING REINSPECTION OF PREVIOUSLY ACCEPTED WELDS
423	1	-	-	1	ATT.10		ATKINSON-QA MANAGER RESTRICTED ISSUE OF FORMAL NONCONFORMANCE FORMS ON UNACCEPTABLE WELDS
424	\	1.	 		ATT.10		ATKINSON-QA MANAGER ACCEPTED WELDS WITHOUT A DETAILED/CLOSE UP INSPECTION
426	1	1-	+-	i 1	ATT.9 PAGE 3	1	PULLMAN WAS FORCED TO HIRE PEOPLE WHO HAD NO QC EXPERIENCE IN ORDER TO PROVIDE A REQUIRED MINIMUM NUMBER OF INSPECTORS

22 - 85 sa 22

21 - 8: 4 21

IR - Ir spection Report

A - The staff has previously addressed the issue

	1115017	TON C. WID!	E POCIMENT		CHARACTERIZATION		
NRC ALLEGATION NUMBER	2/2/8412/22/9	8413/2/84	E DOCUMENT 13/2/84 3/23/84 JI GAP	14/16/84 D.Kirsch			
427			PAGE 3		NO FORMAL TRAINING FOR NEW QC INSPECTORS IN 1982		
428			ATT.9 PAGE 3 PARA 3		QC INSPECTORS WORK BETWEEN JANUARY 1983 AND SEPTEMBER 1983 IS SUSPECT BECAUSE OF INADEQUATE TRAINING		
429	-	+-	PAGE 4.		QA WAS NOT DOING ITS JOB ADEQUATELY BECAUSE ALLEGER FOUND MORE REJECTED DRAWINGS THAN QA DID		
	+-	+	PARA 3	1	TRAINING WAS NONEXISTANT FOR PULLMAN CRAFT PERSONNEL		
430	-	+	PARA 1 ATT.9 PAGE 5	1	PULLMAN STARTED WORK FIRST AND TRIED TO RECTIFY PROBLEMS AFTER THE FAC WITHOUT GOING BACK TO CORRECT ORIGINAL PROBLEM e.g. WELDING WAS		
.431		-	PARA 3 ATT.9 PAGE 8	+	PERFORMED WITHOUT REQUIRED WELDING PROCEDURE MANAGEMENT IS NOT RESPONSIVE TO QC INSPECTORS CONCERNS		
434		-	PARA 3		THE SAME QA BREAKDOWN THAT OCCURRED AT PULLMAN ALSO OCCURRED		
435			PAGE 1 PARA 2		AT GUY F. ATKINSON COMPANY		
440			PAGE 3 PARA 3		ALLEGER NOTED A WELDER PERFORMING WORK WITHOUT PROPER PRE-HEAT		
441			PAGE 4	· i	NO ONE INFORMED WELDER OF THE REQUIREMENTS HE WAS TO WORK TO		
443	1		ATT.1		GUARDS DO NOT PAY ATTEMTION TO X-RAY SCREENS, AND ONLY GO THROUGH MOTIONS ON THE PATDOWNS		
444			ATT.1		SECURITY DEPARTMENT OVERWORKED		

.

22 - 8534 22

21 - St & 21

		1864210	E-MIRC	E DOCUME!	T		CHARACTERIZATION
NRC	A/2/94	12/22/84	13/2/84	13/2/861	3/23/84	4/16/84	
	2/2/84	11	GIP	JI I	GAP	D.Kirsch	
NUMBER 445	Long				ATT.1		SECURITY BREAKING DOWN DUE TO POOR MORALE AMONG GUARDS
446					ATT.1 10		MANAGEMENT HAS NOT INFORMED SECURITY WHAT THEY CAN AND CANNOT DO TO
447	-4,				ATT.1.		SECURITY COMPUTER IS UNRELIABLE AND IN LAST SEVERAL MONTHS HAS ERRON- EQUILY PERMITTED AROUND A DOZEN HOLDERS OF EXPIRED KEY CARDS TO PASS THROUGH SECURITY
448					ATT.1		PINKERTON DOES NOT ALLOW GUARDS TO RAISE QUESTIONS ABOUT PLANT SECURIT
449					ATT.1		IT IS A PUNISHABLE OFFENSE TO RAISE QUESTIONS OUTSIDE OF THE CHAIN OF COMMAND e.g. GO TO PG&E SECURITY WITH A PROBLEM
450				i i	ATT.6 067/068 P14PAR3	-	PULLMAN FAILED TO RECOGNIZE CODE NON-COMPLIANCE
453	-		-		ATT.1		LACK OF PROPER ATMOSPHERE INSIDE THE CONTAINMENT
454	-	-	-		ATT.1		EXCESSIVE PIPING LEAKS E.A. AT THE 85 FOOT LEVEL IN THE TURBINE BUILDING SOUTHEAST SIDE NORTH OF DOOR 129 AND 2 LEAKS AT THE 115 FOOT LEVEL EAST PENETRATION AREA BY DOOR 365
455			1		ATT.1	1	SECURITY INADEQUATE AS EVIDENCED BY A CHANTING PROTESTOR ENTERING THE
456	1.	-	1.		ATT.2	1	PG&E IS NOT APPROVING THE DESIGN OF ANY 2" AND UNDER HANGERS DESPITE FEBRUARY 17, 1984 LETTER TO NRC STATING THAT THEY HAVE PREPARED THE FINAL APPROVED DRAWINGS
457	1	-	1	1	ATT.6 082	1	PULLMAN'S TRAINING PROGRAM DID NOT ADDRESS THE TECHNICAL OBJECTIVES OF THE PROJECT

22 - 85 34 22

21 - S! SR 21

		-		- Almanta	-	CHARACTERIZATION
NRC	- 10 10 11	4 / 6 4 / 8 4 1	2/2/84	3/2/84 3/2	3/84 4/16/84 AP D.Kirsch	
NUMBER 458	GAP	- 1	CIP	08:	2	PULLMAN'S TRAINING PROGRAM DID NOT EXPLAIN THE GOADITY ADDRESS.
459				ATT 08	.6	PULLMAN QC INSPECTORS WERE INSTRUCTED TO CONSULT ONLY PULLMAN PROCEDURES FOR COMPONENT EVALUATION AND TO ACCEPT ALL CONDITIONS OUTSIDE OF THE PROCEDURAL SCOPE
460				1067	.6 /078	PULLMAN DID NOT HAVE A WELDING PROCEDURE TO COVER WELDING MECHANICAL FASTENERS
462				ATT	ARA3	TWO NDE TECHNICIANS WERE CERTIFIED LEVEL 11 DESPITE LETTERS IN THEIR FILES STATING THAT THEY WERE NOT QUALIFIED
463				ATT	3	QA MANAGER HAROLD KARNER CERTIFIED LEVEL II FOR MP, RT, LPT, AND LEVEL I UT WITHOUT MEETING REQUIREMENTS
464	-		-	ATT	7.2	314 WELDS INSPECTED WITH MAGNETIC PARTICLE TEST IN 4 DAYS BY ONE INSPECTOR
466	-		-	AT		QA/QC PERSONNEL INTERMINGLED RESPONSIBILITIES WITH PRODUCTION PERSONNEL DURING 1971-1972
46.7			-	AT	r.2	(ITEM 17) PRACTICE OF MIXING QA/QC AND PRODUCTION RESPONSIBILITIES CONTINUED IN 1976
468	+			TA	T.2 .	MR. MULLIS USED ONE PROCESS SHEET FOR FIVE WELD JOINTS
470	1.	1.	1.	IAT	T.2	THERE WAS NO FORMAL QA PROGRAM FOR PIPE SUPPORTS AND PIPE RUPTURE RESTRAINTS
471	1	-	1	AT	T.2	RESTRAINTS ALTHOUGH PULLMAN IDENTIFIED MANY DEFICIENCIES OF ESD 223 IN 1973, THE COMPANY DID NOT LEARN ITS LESSON. THE NSC AUDIT REPEATED SIMILAR FINDINGS IN 1977

22 - S534 22

21 - 8: 4 21

				- BOCIE	CHT		CHARACTERIZATION
NRC	A	LEGATION	S'NUNCI	DUCUN	12/22/84	14/16/84	
LLEGATION	2/2/84	2/22/94	3/2/84	3/2/84	3/23/04	4/16/84	
NUMBER 472	GAP	_31	<u>GUP</u>	JI	ATT.2	D.Kirsch	PRE-DECEMBER 1973 PIPE SUPPORTS WERE INSTALLED "PRIOR TO IMPLEMENTING THE INSPECTION PROGRAM"
473					ATT.2		IN THE PAST, PULLMAN DID NOT CONDUCT AUDITS OR PRACTICES TO ASME OR 10 CFR 50
474					ATT.2		UNTIL NOVEMBER 1978, SOME PARTS OF THE QA PROGRAM HAD NEVER BEEN AUDITED
475					ATT.2		MAGNETIC PARTICLE ELAMS FOR AN NDE SUPERVISOR DO NOT SHOW HIS GRADE
351							SLOTTED HOLES, ON RUPTURE RESTRAINTS NOT IN ACCORDANCE WITH ASTM A-325
476					ATT.2 PAGE 1		INADEQUATE DOCUMENTATION ON A-325 AND A-307 USAGE-STOKES REBUTTAL TO PG&E'S RESPONSE DCL-84-067, DCL-84-078
477	-		-		ATT.2 PAGE 2		INADEQUATE MATERIAL TRACEABILITY BACK TO CERTIFICATE OF COMPLIANCE . FOR THE ABOVE BOLTS-STOKES REBUTTAL TO PG&E'S RESPONSE DCL-84-067
478	1	-	 		ATT.2		INADEQUATE TRAINING FOR QA INSPECTORS-STOKE'S REBUTTAL TO FG&E'S
479	-	-	-	-	PAGE 4		MODIFICATIONS PERFORMED DURING THE HOT FUNCTIONAL TEST WAS NOT REPORTED TO NRC-STOKE'S REBUTTAL TO PG&E'S RESPONSE DCL-84-094
480	1.	1.	1.		ATT.2	1	CLAMPING PLATE INSTALLATIONS MAY NOT BE ALL CORRECT-STOKE'S REBUTTAL TO PG&E'S RESPONSE
481	1	1.	-	-	ATT.2	1	NO ENGINEERING DOCUMENTS AVAILABLE TO SUPPORT TO PRACTICE OF WELDING UNISTRUTS-STOKE'S REBUTTAL TO PG&E'S RESPONSE

LECEND

22 = S534 22 21 = Sf SR 21 IR = Irspection Report A = The staff has previously addressed the issue

		20010	THE WAY	CHARACTERIZATION	-
NECATION	ALECAT	4 2/22/94 3/2/64 3/2/64 3/	23/84	14/16/84	
NUMBER 482	**		ATT.2	UNQUALIFIED BRAZING PROCEDURE-STOKE'S REBUTTAL TO PG&E'S REPLY	E'S REPLY
483	-	ļ		NO PROCESS SHEETS ISSUED FOR THE REMOVAL OF STANCHIONS AND NO U.T. WAS PERFORMED AFTERWARDS	4S AND NO
484	-		ATT.2 . PAGE. 9	RECHTEL'S FIELD ENGINEER POCKET HANGER REFERENCE WAS NOT FOLLOWED	NOT POLLOWED
1	-				
1	-	I			
	+	-			
	+	1	-		
	-	-			
1					
	-	ļ. 			
	1	1			