November 29, 1984

W3P84-3318 3-A1.01.04 A4.05

Director of Nuclear Reactor Regulation Attention: Mr. G. W. Knighton, Chief Licensing Branch No. 3 Division of Licensing U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Knighton:

Subject: Waterford 3 SES

Docket No. 50-382

IMPLEMENTATION OF REGULATORY GUIDE 1.97, REVISION 2

Reference: LP&L Letter W3P84-3029, dated November 6, 1984

As stated in the referenced letter, LP&L indicated that Control Room indication was not provided for valves CVR-401A and CVR-401B.

Pursuant to discussions held between NRC and LP&L, LP&L will install continuous and direct indication of these valves, consistent with Regulatory Guide 1.97, Revision 2, prior to startup following the first refueling outage at Waterford 3.

Please contact R.J. Murillo at (504) 595-2838 if there are any questions on the letter.

Very truly yours,

7W Cook

K.W. Cook

Nuclear Support & Licensing Manager

KWC: RWP: sms

cc: E.L. Blake, W.M. Stevenson, J.T. Collins, D.M. Crutchfield, J.H. Wilson, G.L. Constable, T.A. Flippo

PDR ADDCK 05000382 A PDR A003