Mr. Michael B. Roche Vice President and Director GPU Nuclear Corporation Oyster Creek Nuclear Generating Station P.O. Box 388 Forked River, NJ 08731

SUBJECT:

CHANGES IN THE DRYWELL CORROSION MONITORING PROGRAM

(TAC NO. M92688)

Dear Mr. Roche:

In a letter dated November 1, 1995, NRC informed GPU Nuclear Corporation (GPUN) that the changes to the previously committed Drywell Corrosion Monitoring Program as delineated in GPUN's letter dated September 15, 1995, are acceptable. However, GPUN is required to make a commitment to perform additional inspections of the drywell 3 months after the discovery of any water leakage. GPUN felt such a requirement is too broad to be cost effective. In a letter dated December 15, 1995, GPUN clarified its commitment and an understanding between the NRC staff and GPUN has been reached. The requirement is to address water leakage discovered during power operation between scheduled drywell inspections. The requirement was not meant to apply to minor leakage associated with normal refueling activities where minor leakage is defined as less than 12 GPM (gallons per minute). GPUN indicated that prior to each refueling outage, a refueling cavity and equipment pool inspection and leak assessment plan is put in place and the plan has been found to be successful in prior outages. For leakages not associated with refueling activities, GPUN will investigate the source of leakage, take corrective actions, evaluate the impact of the leakage and, if necessary, perform an additional drywell inspection about 3 months after the discovery of the water leakage.

Based on the additional information provided by GPUN, the staff finds GPUN's commitment to perform the inspections acceptable.

Sincerely.

Original signed by:

9602220207 960215 PDR ADDCK 05000219

Docket No. 50-219 cc: See next page DISTRIBUTION:

Docket File CTan PUBLIC. ACRS PDI-3 Plant OGC

PEselgroth, RGI SVarga

JZwolinski JStolz **ADromerick** SNorris

DOCUMENT NAME: G:\DROMERIC\M92688.LET

OFFICE LA: DRPE PM:PDI-2// D: PDI-2 NAME SNorris pm ADromen/ck:bf JStolz DATE 02/4/96 02/ /96 02/ /96 02/13/96 02/2/96

OFFICIAL RECORD COPY

Alexander W. Dromerick, Senior Project Manager Project Directorate I-2 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Mr. Michael B. Roche Vice President and Director GPU Nuclear Corporation Oyster Creek Nuclear Generating Station P.O. Box 388 Forked River, NJ 08731

SUBJECT:

CHANGES IN THE DRYWELL CORROSION MONITORING PROGRAM

(TAC NO. M92688)

Dear Mr. Roche:

In a letter dated November 1, 1995, NRC informed GPU Nuclear Corporation (GPUN) that the changes to the previously committed Drywell Corrosion Monitoring Program as delineated in GPUN's letter dated September 15, 1995, are acceptable. However, GPUN is required to make a commitment to perform additional inspections of the drywell 3 months after the discovery of any water leakage. GPUN felt such a requirement is too broad to be cost effective. In a letter dated December 15, 1995, GPUN clarified its commitment and an understanding between the NRC staff and GPUN has been reached. The requirement is to address water leakage discovered during power operation between scheduled drywell inspections. The requirement was not meant to apply to minor leakage associated with normal refueling activities where minor leakage is defined as less than 12 GPM (gallons per minute). GPUN indicated that prior to each refueling outage, a refueling cavity and equipment pool inspection and leak assessment plan is put in place and the plan has been found to be successful in prior outages. For leakages not associated with refueling activities. GPUN will investigate the source of leakage, take corrective actions, evaluate the impact of the leakage and, if necessary, perform an additional drywell inspection about 3 months after the discovery of the water leakage.

Based on the additional information provided by GPUN, the staff finds GPUN's commitment to perform the inspections acceptable.

Sincerely,

Original signed by:

Alexander W. Dromerick, Senior Project Manager Project Directorate I-2 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-219 cc: See next page

DISTRIBUTION: Docket File

CTan ACRS

PUBLIC PDI-3 Plant

OGC

SVarga

JZwolinski JSto1z

PEselgroth, RGI

ADromerick SNorris

DOCUMENT	MAME: G: DRUMEKT	C/Wa5000.FEI			
OFFICE	LA: DRPE	PM:PDI-2/	D:PUI-2		
NAME	SNorris Am	ADromerack: bf	JStolz		
C. TE	02/13/96	02/13/96	02/196	02/ /96	02/ /96

OFFICIAL RECORD COPY



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

February 15, 1996

Mr. Michael B. Roche Vice President and Director GPU Nuclear Corporation Oyster Creek Nuclear Generating Station P.O. Box 388 Forked River, NJ 08731

SUBJECT:

CHANGES IN THE DRYWELL CORROSION MONITORING PROGRAM

(TAC NO. M92688)

Dear Mr. Roche:

In a letter dated November 1, 1995, NRC informed GPU Nuclear Corporation (GPUN) that the changes to the previously committed Drywell Corrosion Monitoring Program as delineated in GPUN's letter dated September 15, 1995, are acceptable. However, GPUN is required to make a commitment to perform additional inspections of the drywell 3 months after the discovery of any water leakage. GPUN felt such a requirement is too broad to be cost effective. In a letter dated December 15, 1995, GPUN clarified its commitment and an understanding between the NRC staff and GPUN has been reached. The requirement is to address water leakage discovered during power operation between scheduled drywell inspections. The requirement was not meant to apply to minor leakage associated with normal refueling activities where minor leakage is defined as less than 12 GPM (gallons per minute). GPUN indicated that prior to each refueling outage, a refueling cavity and equipment pool inspection and leak assessment plan is put in place and the plan has been found to be successful in prior outages. For leakages not associated with refueling activities, GPUN will investigate the source of leakage, take corrective actions, evaluate the impact of the leakage and, if necessary, perform an additional drywell inspection about 3 months after the discovery of the water leakage.

Based on the additional information provided by GPUN, the staff finds GPUN's commitment to perform the inspections acceptable.

Sincerely,

Alexander W. Dromerick, Senior Project Manager

Aufaly W Deomerul

Project Directorate I-2

Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-219

cc: See next page

cc:

Ernest L. Blake, Jr., Esquire Shaw, Pittman, Potts & Trowbridge 2300 N Street, NW. Washington, DC 20037

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

BWR Licensing Manager GPU Nuclear Corporation 1 Upper Pond Road Parsippany, NJ 07054

Mayor Lacey Township 818 West Lacey Road Forked River, NJ 08731

Licensing Manager Oyster Creek Nuclear Generating Station Mail Stop: Site Emergency Bldg. P.O. Box 388 Forked River, NJ 08731

Resident Inspector c/o U.S. Nuclear Regulatory Commission P.O. Box 445 Forked River, NJ 08731

Kent Tosch, Chief
New Jersey Department of
Environmental Protection
Bureau of Nuclear Engineering
CN 415
Trenton, NJ 08625