



SAFEGUARDS INFORMATION

NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA STREET, N.W., SUITE 2900
ATLANTA, GEORGIA 30323-0199

Report Nos.: 50-348/96-01 and 50-364/96-01

Licensee: Southern Nuclear Operating Company, Inc.
600 North 18th Street
Birmingham, AL 35291-0400

Docket Nos.: 50-348 and 50-364

License Nos.: NPF-2 and NPF-8

Facility Name: Joseph M. Farley Nuclear Plant Units 1 and 2

Inspection Conducted: January 22 - 26, 1996

Inspector:

for W. W. Stansberry

W. W. Stansberry, Safeguards Inspector

2/23/96

Date Signed

Approved by:

for P. E. Fredrickson

P. E. Fredrickson, Chief
Special Inspection Branch
Division of Reactor Safety

2/23/96

Date Signed

9602290086 960223
PDR ADOCK 05000348
Q PDR

SUMMARY

Scope:

This routine inspection was conducted onsite in the functional area of Physical Security Program For Power Reactors (81700). Specific areas evaluated were: audits, corrective actions, management support, effectiveness of management controls, and security program plans.

Results:

In the areas inspected, one citable violation and one non-citable violation were identified. They are respectively:

1. Failure to physically check randomly selected vital areas (see Paragraph 3).
2. Failure to ensure that all individuals granted unescorted access will be subject to a random screening program (see Paragraph 4).

Corrective actions, management support, effectiveness of management control, and security program plans were found to be adequate. Corrective actions were thorough. Management support and the effectiveness of management control of the security program were timely, competent and responsive. Security program plans reviewed met regulatory requirements. The failure to check designated vital areas was personnel/human error in complying with the commitment in the Security Plan (SP). The fitness for duty problem was also personnel/human error created in the software of the site's random testing program. This error only involved contract personnel at the site.

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosure(s) this document is decontrolled.