



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

Report Nos.: 50-321/92-11 and 50-366/92-11

Licensee: Georgia Power Company  
P. O. Box 1295  
Birmingham, AL 35201

Docket Nos.: 50-321 and 50-366 License Nos.: DPR-57 and NPF-5

Facility Name: Hatch 1 and 2

Inspection Conducted: April 27 - May 1, 1992

Inspector: William J. Tobin 5/27/92  
W. J. Tobin, Senior Safeguards Inspector Date Signed

A. Tillman 5/27/92  
A. Tillman, Safeguards Inspector Date Signed

Approved by: D. R. McGuire 5/27/92  
D. R. McGuire, Chief Date Signed  
Safeguards Section  
Nuclear Materials Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

## SUMMARY

### Scope:

This routine, unannounced inspection was conducted in the areas of the Physical Security Program for Power Reactors. Specifically; Audit, Barriers, Alarms, Assessment, Maintenance, Compensatory Measures, Power Supply, Alarm Station and Communications were reviewed. The licensee's corrective actions to two prior items were also reviewed.

### Results:

The two prior items were "closed" (91-12-01 and 91-19-01), a Non-cited Violation (92-11-02) was identified relative to the isolation zone of the protected area barrier (Paragraph 3.b), an issue (92-11-03) was identified relative to radio communications (Paragraph 3.e), and an apparent violation was identified relative to redundant Alarm Stations (92-11-01) (Paragraph 3.d).

The licensee has completed its Security Equipment Upgrade which has improved lighting, cameras, alarms, card readers, computers, and alarm stations.

Document transmitted herewith  
contains sensitive unclassified  
information. When separated from  
enclosures, this document is decontrolled.

9206050221 920529  
PDR ADOCK 05000321  
G PDR

## SAFEGUARDS INFORMATION

## SAFEGUARDS INFORMATION

2

Audits were thorough, barrier integrity was acceptable, alarms and their assessment have improved, maintenance has reduced compensatory measures, power supplies were adequate and alarm stations and communications (with the exception as noted above) were as required.

The licensee continues to adequately protect its safety-related equipment.

SAFEGUARDS INFORMATION

Document transmitted herewith  
remains an active unclassified  
information. If separated from  
this document, the information  
is uncontrolled.