



NIAGARA MOHAWK POWER CORPORATION / 300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202 / TELEPHONE (315) 474-1511

December 10, 1984  
(NMP2L 0286)

Mr. R. W. Starostecki, Director  
U.S. Nuclear Regulatory Commission  
Region I  
Division of Project and Resident Programs  
631 Park Avenue  
King of Prussia, PA 19406

Re: Nine Mile Point Unit 2  
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report, in accordance with 10CFR50.55(e), for the problem concerning tube-fitting nonconformance which were installed by Johnson Controls, Incorporated. This problem was reported via telecon to T. Silko of your staff on November 9, 1984.

Very truly yours,

C. V. Mangan  
Vice President  
Nuclear Engineering & Licensing

CVM/GG/ca

cc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector  
Project File (2)

8412270218 841210  
PDR ADOCK 05000410  
S PDR

NIAGARA MOHAWK POWER CORPORATION  
NINE MILE POINT UNIT 2  
DOCKET NO. 50-410

Interim Report for a  
Problem Concerning Tube-Fitting  
Nonconformance - Johnson Controls, Incorporated  
(55(e)-84-50)

Description of the Problem

Tubing fittings which possibly do not meet minimum wall thickness requirements have been identified. Verification (that minimum wall thickness has not been violated after the performance of grinding) has not been performed as required in Nonconformance and Disposition Report #JC226. The acceptability of the existing wall thickness and the need for corrective action will be evaluated. A final report will be provided by April 30, 1985.