

ENCLOSURE 2

NOTICE OF DEVIATION

Tennessee Valley Authority
Browns Ferry 1, 2, and 3

Docket Nos. 50-259, 260 and 296
License Nos. DPR-33, 52 and 68

The following deviation was identified during an inspection conducted on June 26 - July 27, 1984:

In Reportable Occurrence Report BFRO-50-259/83068 RI (RHR pump motor failure) dated May 25, 1984, it was stated that a followup report to address the failure mode and recurrence control would be issued by July 16, 1984.

Contrary to the above, the followup report was not issued until July 24, 1984, after the inspector informed the licensee that the report was not issued. Discussions with plant personnel revealed that an administrative error resulted in the report not being issued. The report had not been adequately tracked to ensure the final report was issued.

This deviation is applicable to Unit 1.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding the deviation, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Security of safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: OCT 17 1984

8502060190 841017
PDR ADOCK 05000259
Q PDR