

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

85 JAN 22 15:55
January 15, 1985

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Re: Catawba Nuclear Station, Units 1 & 2
Docket Nos. 50-413 and 50-414
Significant Deficiency No. 413-414/84-03

Dear Mr. O'Reilly:

Please be advised that all corrective action for the Unit 2 diesels regarding inspection of the fuel pump drives for looseness of hubs has been completed. The engine 2A hubs were inspected and found to be tight. The 2B hubs were inspected, found to be loose, and were reinstalled with Loctite.

Very truly yours,

H. B. Tucker

Hal B. Tucker

LTP:slb

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Robert Guild, Esq.
P. O. Box 12097
Charleston, South Carolina 29412

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

NRC Resident Inspector
Catawba Nuclear Station

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207

8502060574 850115
PDR ADOCK 05000413
S PDR

OFFICIAL COPY
LEV
10