


INRYCO, Inc.
Concrete Systems Division
7200 S. Narragansett Avenue
Bedford Park
Chicago, Illinois 60638-6087

312 585 7300 Chicago
312 594 7300 Suburban

TLX-72-1497 BDPK
FAX: Ext. 202

50-364



Inryco

February 4, 1985

United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Attention: Director, Regional Office

SUBJECT: Alabama Power Company
Joseph Farley Nuclear Plant - Unit 2
Compliance with 10CFR Part 21

Gentlemen:

On January 28, 1985 the Alabama Power Company reported an apparent failure of a post tensioned tendon on the subject plant. A subsequent investigation revealed that another tendon anchor from the same heat had cracked but has not failed.

Inryco is participating in an investigation to determine the cause of the anchor failure. Meanwhile, in keeping with 10CFR21, Inryco is alerting you of its involvement with the problem.

The anchorages that failed or cracked were furnished to Inryco by Western Concrete of Gardena, California. Further information will be forthcoming in conjunction with the Alabama Power investigation.

INRYCO, INC.

Donald W. Waitkus
Donald W. Waitkus (lgw)
Supervisor, Quality Assurance

Chester E. Matykiewicz
Chester E. Matykiewicz
Responsible Officer

lgw

8502080505 850204
PDR ADOCK 05000364
S PDR

1E19
1/0
FEB 5 1985