

WARNING

Unauthorized Disclosure is Prohibited,
Section 147 Atomic Energy Act 1954
and 10.CFR 73.21. Violations Subject
To Civil And Criminal Sanctions.

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report Nos. 50-237/92015(DRSS); 50-249/92015(DRSS)

Docket Nos. 50-237; 50-249

License Nos. DPR-19; DPR-25

Licensee: Commonwealth Edison Company
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Facility Name: Dresden Nuclear Power Station, Units 2 and 3

Inspection At: Dresden Site, Morris, Illinois

Inspection Conducted: June 15-19 and 23, 1992

Inspectors: J. L. Belanger for
T. J. Madeda
Physical Security Inspector

7-22-92
Date

J. L. Belanger
J. L. Belanger
Senior Physical Security Inspector

7-22-92
Date

Approved By: James R. Creed
James R. Creed, Chief
Safeguards Section

7/22/92
Date

Inspection Summary

Inspection on June 15-19 and 23, 1992 (Report Nos. 50-237/92015(DRSS); 50-249/92015(DRSS))

Areas Inspected: Routine, unannounced physical security inspection involving: Management Support; Protected and Vital Area Physical Barriers, Detection and Assessment Aids; Protected and Vital Area Access Control of Personnel, Packages and Vehicles; Alarm Stations and Communications; Power Supply; Testing, Maintenance and Compensatory Measures; Security Training and Qualification.

Results: No violations of NRC requirements were noted.

Four security program observations were identified regarding: (1) a vulnerability of search equipment; (2) weak vehicle search procedures; (3) procedural weakness involving package searches and (4) a weakness in the storage of Safeguards Information. The licensee has taken adequate corrective action for each finding noted above.

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

Licensee performance continued to be effective in implementing the site security program. Management attention to and involvement in security activities at the site and corporate level showed strong support for the security program. Security equipment was operating in an effective and reliable manner. Licensee resources were ample and properly allocated to meet security program requirements. Security personnel observed were knowledgeable of their duties and tested security equipment performed as required, except as addressed in the observations noted above. Excellent licensee performance in the area of security training was noted.