

Official File

NOV 28 1984

Georgia Power Company
ATTN: Mr. R. J. Kelly
Executive Vice President
P. O. Box 4545
Atlanta, GA 30302

Gentlemen:

SUBJECT: REPORT NOS. 50-321/84-34 AND 50-366/84-34

We have received your response of November 8, 1984, to our Notice of Violation issued on October 9, 1984, concerning activities conducted at your Hatch facility. Subsequent to the implementation of your stated corrective actions to ensure that systems are properly returned to service, the "keep-full" jockey pump system was improperly aligned.

The improper alignment of the jockey pump system (identified in Inspection Report 50-321 and 366/84-41 as an example to Violation 84-41-01) indicates that your corrective actions are not adequate to preclude further occurrences of this nature.

It is therefore requested that you address this matter as part of your response to Violation 84-41-01.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original Signed by
John A. Olshinski

John A. Olshinski, Director
Division of Reactor Projects

cc: J. T. Beckham, Vice President
and General Manager-Nuclear
Operation
H. C. Nix, Site General Manager
P. E. Fornel, Site QA Supervisor
L. Gucwa, Chief, Nuclear Engineer

bcc: NRC Resident Inspector
Hugh S. Jordan, Executive Secretary
Document Control Desk
State of Georgia

*NOTE FOR CONCURRENCES, SEE ATTACHED SHEET

RII	RII	RII	RII
RCarroll:cdg	VPanciera	VBrownlee	JPuckett
11/ /84	11/ /84	11/ /84	11/ /84

8503010422 841128
PDR ADOCK 05000321
PDR

11 IE-61

Georgia Power Company
ATTN: Mr. R. J. Kelly
Executive Vice President
P. O. Box 4545
Atlanta, GA 30302

Gentlemen:

SUBJECT: REPORT NOS. 50-321/84-34 AND 50-366/84-34

We have received your response of November 8, 1984, to our Notice of Violation issued on October 9, 1984, concerning activities conducted at your Hatch facility. Subsequent to the implementation of your stated corrective actions to ensure that systems are properly returned to service, the "keep-full" jockey pump system was improperly aligned.

The improper alignment of the jockey pump system (identified in Inspection Report 50-321 and 366/84-41 as an example to Violation 84-41-01) indicates that your corrective actions are not adequate to preclude further occurrences of this nature.

It is therefore requested that you address this matter as part of your response to Violation 84-41-01.

Should you have any questions concerning this letter, please contact us.

Sincerely,

John A. Olshinski, Director
Division of Reactor Projects

cc: J. T. Beckham, Vice President
and General Manager-Nuclear
Operation
H. C. Nix, Site General Manager
P. E. Fornel, Site QA Supervisor
L. Gucwa, Chief, Nuclear Engineer

bcc: NRC Resident Inspector
Hugh S. Jordan, Executive Secretary
Document Control Desk
State of Georgia

RII

for
RCarroll:cdg
11/26/84

RI

VPauciera
11/26/84

RII

HIO
VBrownlee
11/26/84

RII

JPuckett
11/26/84