## ENCLOSURE 1

## NOTICE OF VIOLATION

Virginia Electric Power Company North Anna Docket Nos. 50-338 and 50-339 License Nos. NPF-4 and NPF-7

The following violation was identified during an inspection conducted on October 9-12, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 4.11.1.1.1 requires that whenever the secondary coolant activity is greater that  $1 \times 10^{-5} \mu \text{Ci/ml}$ , the turbine building sump shall be placed in manual operation and samples shall be taken and analyzed prior to release.

Contrary to the above, on January 1, 1984, January 13, 1984, February 2, 1984, February 16, 1984, and February 25, 1984, with secondary coolant activity greater than 1 x  $10^{-5} \mu$ Ci/ml, the licensee made unmonitored releases from the turbine building sump to the plant storm drains.

This is a Severity Level IV violation (Supplement IV).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: NOV 2 7 1984