

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2						DOCKET NUMBER (2) 0 5 0 0 0 3 6 1			PAGE (3) 1 OF 0 1		
--	--	--	--	--	--	--------------------------------------	--	--	----------------------	--	--

TITLE (4)
CONTAINMENT PURGE ISOLATION SYSTEM TRAIN A ACTUATIONS

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQ. NUMBER	REV. NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 1	0 3	8 5	8 5	0 0 1 7	0 0	0 1	2 2	8 5			0 5 0 0 0 0

OPERATING MODE (9) N

POWER LEVEL (10) 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the followi..g) (11)

20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)
20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)
20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	
20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)	
20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
J. G. HAYNES, STATION MANAGER	7 1 1 4 4 9 2 1 - 7 7 0 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (if yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

Abstract (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)


On January 3, 1985, at 1945, with Unit 2 defueled, the Train "B" Containment Purge Isolation System (CPIS) (EIIS System Code VA) actuated when the Containment Area Radiation Monitor 2RT-7857 (EIIS Component Code RIT) cabinet was opened for a routine surveillance. See also LER 84-030 (Docket No. 30-361). At the time, a containment purge was in progress, and all CPIS actuated components performed properly, isolating the main purge. Containment radiation levels were verified to be below the CPIS actuation setpoint, and CPIS was reset and the purge reinitiated. During the investigation following the actuation, the actuation could not be reproduced, nor were any defects discovered which could have caused the actuation. As corrective action for both this event and LER 84-030, a sign will be placed on the cabinet door cautioning personnel to open and close the door with care.

There are no credible circumstances under which these events would have been more severe.

8502010846 850122
PDR ADDCK 05000361
S PDR

IE22
44

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES
STATION MANAGER

TELEPHONE
(714) 492-7700

January 22, 1985

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 85-007
San Onofre Nuclear Generating Station, Unit 2

Pursuant to 10 CFR 50.73(a)(2)(iv), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the actuation of the Containment Purge Isolation System. Neither the health and safety of plant personnel nor the public were affected by this event.

If you require any additional information, please so advise.

Sincerely,

Enclosure: LER No. 85-007

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

IE22
11