

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

February 1, 1985


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No. 50-370
LER 370/84-26

Gentlemen:

The subject Licensee Event Report, dated October 26, 1984 stated that check valves in the Auxiliary Feedwater (CA) system at McGuire would be replaced during the upcoming refueling outages in 1985, for each unit. Due to extended lead times for procurement of these valves, replacement will not be possible until the 1986 refueling. Other corrective actions outlined in the LER have been or will be performed as stated in the LER.

Very truly yours,



Hal B. Tucker

SAG/mjf

Attachment

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8502110678 850201
PDR ADOCK 05000370
S PDR

IB22
1/0