

APPENDIX A

NOTICE OF VIOLATION

Duquesne Light Company
Beaver Valley Power Station, Unit 2

Docket No. 50-412
License No. CPPR-105

As a result of the inspection conducted on July 24 - August 24, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

10 CFR 50, Appendix B, Criterion V, requires that activities affecting quality shall be prescribed by procedures and shall be accomplished in accordance with these procedures.

Specification 2BVS-981 contains in-place storage requirements for the Personnel Air Lock to prevent damage. After the doors are opened, this includes protection of door seals and sealing surfaces and support of the doors to prevent sagging.

Contrary to the above, during the period from July 26 until August 23, 1984, protection of the Personnel Air Lock was not provided to prevent damage of sealing surfaces or support of the doors to prevent sagging.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Duquesne Light Company is hereby required to submit to this office within thirty days of the date of the cover letter to this Notice, a written statement or explanation in reply including: (1) the corrective steps which have been taken and results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance is achieved. Where good cause is shown, consideration will be given to extending your response time.

8410260130 840926
PDR ADOCK 05000412
g PDR