

APPENDIX A

NOTICE OF VIOLATION

Duquesne Light Company
Beaver Valley Power Station, Unit 2

Docket No. 50-412
License No. CPPR-105

As a result of the inspection conducted on July 16-20, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

10 CFR Appendix B, Criterion V, requires that "Activities affecting quality shall be prescribed by documented instructions, procedures ... and shall be accomplished in accordance with these instructions, procedures"

Installation Specification No. 2BV-977, Addendum 4, pages 1-35, lines 14-20, requires that caps or plugs be used for sealing tubing and instrument openings to prevent entry of dirt and dust.

Contrary to the above, on July 18 and July 19, 1984, the inspector identified several instruments and tubing runs that were not plugged nor capped.

This is a Severity Level V Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Beaver Valley Power Station is hereby required to subject to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) The corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

DL50-412/84-08 - 0003.0.0
08/27/84

B410260144 B40920
PDR ADOCK 05000412
Q PDR