

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

Inspection Report: 50-458/92-31

Operating License: NPF-47

Licensee: Gulf States Utilities
Senior Vice President
P.O. Box 220
St. Francisville, Louisiana 70775

Facility Name: River Bend Station

Inspection At: St. Francisville, Louisiana

Inspection Conducted: September 8-11, 1992

Inspectors: A. B. Earnest, Physical Security Specialist
Facilities Inspection Programs Section

T. W. Dexter, Senior Physical Security Specialist
Facilities Inspection Programs Section

Approved:

Blaine Murray
Blaine Murray, Chief, Facilities Inspection
Programs Section

9/28/92
Date

Inspection Summary

Areas Inspected: Routine, announced inspection of assessment aids, detection aids-protected area, records and reports, security systems power supply, access control-personnel, testing and maintenance, and training and qualifications.

Results:

- The assessment aids provided good assessment capabilities (paragraph 1).

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

9210190011 921013
PDR ADDOCK 05000458
G PDR

- The perimeter detection aids were tested and, with one minor exception, provided excellent detection of potential intruders. The one zone exception was identified as an inspection followup item (paragraph 2).
- Some minor security incidents were not recorded (paragraph 3.1).
- The licensee had identified an incident of records falsification by a security officer. This item was identified as a noncited violation (paragraph 3.1).
- The emergency power supply for the security systems provided uninterruptible power in case of a power failure (paragraph 3.2).
- The personnel access control equipment was adequate to ensure that personnel entering the plant were adequately searched (paragraph 3.3).
- During an audit of self-screening contractors, the licensee identified a contractor who had not met the access authorization program requirements. This item was identified as an unresolved item (paragraph 3.3).
- The testing and maintenance program was timely and efficient in maintaining the security systems in optimum condition (paragraph 3.4).
- The training and qualification program appeared to be compliance oriented (paragraph 3.5).

Summary of Inspection Findings:

- An inspection followup item (IF1 458/9231-01) was identified (paragraph 2).
- A noncite violation was identified (paragraph 3.1).
- An unresolved item (458/9231-02) was identified (paragraph 3.3).

Attachments

- Attachment 1 - Persons Contacted and Exit Meeting.