NRC Form (9-83)	36	•											LI	CE	ENSE	E	EV	EN	ıT	RE	PORT	(	LER)		PPR	OVE	ED (	GUL. 0MB 31/65	NO				SION
PACILITY	NA.			_		_			_	_	_	_	-	-			_	_		_		-		OCKET NUMBER	-		_	_	_	F	-	GE	-
		E	)WI	N .	I. 1	HA	TC	H,	U	IT	1												0	15 10 10	10	13	1	2 1	1	1	0	F	0/2
TITLE (4		oss	SIB	LE	FA	BR	IC	ATI	10	I A	ND	/01	R C	0	NSTE	RUC	TI	ON	1	AK	DEQUAC	C	IES										
EVENT DATE (6) LER NUMBER (6)									REPORT DATE (7) OTHE								OTHER F	FACILITIES INVOLVED (8)															
MONTH NAV VEAD VEAD SEQUENTIAL REVISE								VISIO	N HONTH I DAY I				YEA	YEAR			FACILITY NAM	DOCKET NUMBER(S)															
	-	-	-					-	UME	16 M	+	NI	MBE	+		+		+	-	-					0	15	1	0	0	10	1	1	1
1 0	1	1	8	4	8	4	-	0	1	4	-		0 0		1 10	1	18		8	4					0	15	51	0 1	0	10	L	1	1
OPE	RAT	TING			THIS	RE	POR	TISS	UB	MITTE	D P(	PS	JANT	T	THE	teat	HEE	ME	STP	OF 1	0 C#R & 10	Ch	eck one or more of	the following) (1	1)								
MODE (9) 5 20.402(a)					T	20.468(c)							60.73(a)(2)(iv)					73.71(b)															
POWER						20.406(a)(1)(i) 20.406(a)(1)(ii)					1	60.38(c)(1)						×	1	50.73(a)(2)(v)		73.71(c)											
LEVEL Q O			0								50.36(c)(2)				60.73(a)(2)(vii)				OTHER /Specify in Abstract														
						20	406	11110	(1)					]	50.736	1(2)	(1)						50.73(a)(2)(viii)(A	)			366						2000
						20	406	1(1)(	w)						50.736	1(2)	(44)					1	50.73(a)(2)(viii)(B)	- 1									
						20	408	e)(1)(v	1					1	50,736	(2)	(88e)-						50.73(a)(2)(a)										
					7.00									LH	CENSEE	COP	NTA	CT F	OR	THIS	LER (12)												
NAME														ı											TEL	EPH	ION	E NI	JMB	ER			
																								AREA CODE									
T.	L	. 1	Elt	on	, A	ct	in	g S	u	ot.	01	£ 1	Reg	u	lato	ry	C	on	mp l	ia	nce			9 1 12	3	16	1	1	-	17	18	P	+
								CO	MP	ETE	ONE	LIN	E FO	R	EACH C	OMP	ONE	NT	FAII	LURE	DESCRIBE	D	IN THIS REPORT	(13)									
CAUSE	0	OMP	ONEN	NENT		MANUFAC TURER			REPORTABLE TO NPROS			E				*	CAI		SYSTEM	COMPONENT		MANUFAC TURER	REPORT TO NP										
194		,												T									1		1				T				•••••
	-	-	-	_		-	-	-	-	1	-			+	******	*****			-			-			+	-	_	-	+		-		

On 10/11/84, with the reactor mode switch in the refuel position and the unit shutdown for refueling, 15 indications were identified by ultrasonic testing during the in-service inspection (ISI) of the recirculation piping and residual heat removal (RHR) weld areas. The welds have been identified as having possible inter-granular stress corrosion cracking (IGSCC); however, further inspection and evaluation is under way. The unit has been placed in an LCO per Tech. Specs. section 3.6.K.

SUPPLEMENTAL REPORT EXPECTED (14)

X YES I'M yes, complete EXPECTED SUBMISSION DATE!

ABSTHACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

An update report will be submitted which will include a summary assessment of actual and potential safety consequence and implications due to these events and the corrective actions to be taken when the ISI and engineering evalution of the results are completed. As per Tech. Specs. section 3.6.K, the unit will remain in cold shutdown until the engineering evaluation and the required corrective action is completed.

8411010340 841018 PDR ADDCK 05000321 S PDR

TEDO

YEAR

1, 5 8,4

MONTH

1, 2

EXPECTED

(9-83) LICENSEE EVEN	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION  APPROVED OMB EXPIRES: 8/31/8												
FACILITY NAME (1)	DOCKET NUMBER (2)		LER	NUMBER (6)		PAGE (3)							
		YEAR		SEQUENTIAL NUMBER	REVISION NUMBER		THE ST						
EDWIN I. HATCH, UNIT 1	0  5  0  6  5   3   2	8 4	_	01114	-010	0 2	OF 0 12						
TEXT (If more space is required, use additional NRC Form 366A's) (17)													

This 30 day LER is required by 10CFR 50.73 (a)(2)(VI) because the indications show possible fabrication and/or construction inadequacies.

On 10/11/84, with the reactor mode switch in the refuel position and the unit shutdown for refueling, 15 indications were identified by ultrasonic testing during the in-service inspection (ISI) of the recirculation piping residual heat removal (RHR) weld areas. The welds have been identified as having possible inter-granular stress corrosion cracking (IGSCC); however, further inspection and evaluation is under way. The unit has been placed in an LCO per Tech. Specs. section 3.6.K.

The health and safety of the public were not affected by this non-repetitive event; however, a similar event occurred as reported by LER 50-321/1982-089, Rev. 2.

An update report will be submitted which will include a summary assessment of actual and potential safety consequences and implications due to these events and the corrective actions to be taken when the ISI and engineering evalution of the results are completed. As per Tech. Specs. section 3.6.K, the unit will remain in cold shutdown until the engineering evaluation and the required corrective action is completed.

Georgia Power Company Post Office Box 439 Baxley, Georgia 31513 Telephone 912 367-7781 912 537-9444

Georgia Power

Edwin I. Hatch Nuclear Plant

October 18, 1984 GM-84-953

PLANT E. I. HATCH Licensee Event Report Docket No. 50-321

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Attached is Licensee Event Report No. 50-321/1984-14. This report is required by 10 CFR 50.73(a)(2)(VI).

General Manager

HCN/TLE/vlt

R. J. Kelly xc:

R. E. Conway

J. T. Beckham, Jr. P. D. Rice K. M. Gillespie

S. B. Tipps

R. D. Baker

Control Room

Document Control