

DEC 19 1973

631 Park Avenue
King of Prussia, Pennsylvania 19406

H. D. Thornburg, Chief
Field Support and Enforcement Branch
Directorate of Regulatory Operations, HQ

OYSTER CREEK (DN 50-219)
ABNORMAL OCCURRENCE REPORT NO. 73-31
MOMENTARY INTERRUPTION OF 125V D.C. POWER SUPPLYING INSTRUMENTATION
ASSOCIATED WITH VARIOUS SAFEGUARDS SYSTEM

The above abnormal occurrence is forwarded for information. Distribution will be made by this office to the PDR, Local PDR, NSIC, DTIE, and State Representatives.

JCP&L reported an abnormal occurrence precipitated by improper installation of jumpers which were wrongly installed without benefit of written procedures (administrative controls). The circumstances surrounding this event are unique in that the licensee had previously received RO Bulletin 73-6 dated November 26, 1973, which in part specifically relates to jumper installation, temporary circuitry changes, and management reviews.

As a result of this abnormal occurrence, the licensee has been requested to expedite necessary actions specified in the RO Bulletin.

E. J. Brunner, Chief
Reactor Operations Branch

9604120128 960213
PDR FOIA
DEKOK95-258 PDR

B/46

OFFICE ▶	XXXXXXXX				
SURNAME ▶	EJ Brunner				
DATE ▶					