

. 0

Rit Jam a

UNIFED STATES ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION 1 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

OCT 3 0 1973

P. J. Knapp

INSPECTOR'S EVALUATION OF OYSTER CREEK STATION BASED ON INSPECTION OF SEPTEMBER 5-7, 1973

The conditions at Oyster Creek observed during our inspection are <u>not</u> indicative of a good radiation safety program. Radiation levels are higher than necessary. There are areas of contamination that could be easily cleaned up. Housekeeping is very bad. Nobody in the Health Physics Group has time to accomplish what could be considered their normal duties. They spend all their time "putting out fires," running from one incident to the next, so that a normal, routine attention to smear surveys, checking on activities of personnel including surprise audits of work habits, monitoring of personnel, etc., never takes place. One of their supervisors spends so much time on unessential details that he had no time to investigate a contamination spill that took place two weeks before.

The number one cause of the poor radiation safety program is lack of management control. Management knows that employees are violating RWPs, but cannot (or will not) do anything about it. They find signs torn down, barriers removed, RWPs destroyed, but no corrective action is taken. We suggested that maybe someone should mop up the contaminated crud on the floor at one area in the reactor building. The reply was "Why bother? The stuff won't go anywhere." We said that since we were able to remove the material by wiping with a tissue, it seemed that it could easily be tracked around by anyone walking through the area. The reply was "That's why we have step-off pads and contamination zones." They would not need dozens of contamination zones if they cleaned the place. They still do not have a Radiation Protection Supervisor, so there is no strong leadership--no one seems to take on any responsibility for anything.

There is no rapport among the Health Physics people or between them and the rest of the workers. I am sure that the hourly radiation technicians would not turn in one of their fellow bargaining unit workers for a violation of Radiation Protection Procedures. At least, it has never happened as far as I could determine from talking to Supervision. One supervisor stated that they have no mechanism for disciplining violators that is at all effective.

The average employee (and some foremen) is so uninformed about radiation levels that they have no idea of dose rates in their own daily work areas. If it were not for pocket dosimeters, I am sure many would show up as overexposures every quarter.

9604120183 960213 PDR FOIA DEKOK95-258 PDR Their reorganization hiring is badly bogged down. They have had 6 months since they committed themselves to do something and they have only moved one employee into an assistant radiation technician job so far. Apparently, JCPL has not given the Station Superintendent the money and authority he needs to get some people on board.

We should keep in mind, however, that no matter how many people they hire, they will never have an effective program as long as the general attitude of their employees remains the same.

One item was discussed that was not included in the report: testing of charcoal filters for halogen removal efficiency. Their testing frequency is O.K., however, they have only freon leak-tested their filters in the past. This has apparently been accepted practice up to now. The licensee is aware of this and is looking into the requirement for testing halogen removal efficiency. We did not pursue this item.

Kr. Refail

John Mann

R. Meyer Ralph Meyer

U. S. ATOMIC ENERGY COMMISSION

DIRECTORATE OF REGULATORY OPERATIONS

REGION I

RO Inspection Report No.: 50-219/73-14

Licensee: Jersey Central Power & Light Co.

Madison Avenue at Punch Bowl Road

Morristown, New Jersey

	-	all look ways to get a date of a second				
Location:		Forked	River,	New	Jersey	
TOFOF OF THE	abress	and the second of the second				****

Type of Licensee: BWR, 1930 Mwt

Type of Inspection: Routine, Unannounced

Dates of Inspection: September 5, 6, 7, 1973

Dates of Previous Inspection: August 28, 29, 1973

Accompanying Inspectors:

الانبطان

Reporting Inspector: John Moun

John Mann, Radiation Specialist

R. G. Meyer, Radiation Specialist

Docket No.:	50-219
License No.:	DPR-16
Priority:	0
Category:	С

DATE

DATE

Other Accompanying Personnel: None

Reviewed By:

P. J. Knapp, Senior, Facility Radiological Protection Section

DATE

0/24/13